

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 380L**AAD2004-100***Not authorized*
6/1/2020

Vehicle No.:

Chassis No.:

Vehicle Make:

30 APR 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 380L

VF1ABL15AUC282609

RENAULT

LATITUDE

29.4.2020

TOKIO MARINE

22/3/2016

PART		LIST	
1	BUMPER COVER REAR	\$	<i>Bu</i> 561.70 ✓
1	BUMPER LOWER REAR	\$	<i>Not in</i> 411.90 ✓
1	BUMPER BRACKET CTR REAR	\$	<i>Di</i> 98.10 ✓
1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10 X
1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80 X
1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60 X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80 X
1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20 X
1	BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60 X
1	BUMPER BEAM REAR	\$	<i>Bu</i> 547.80 ✓
1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 114.50 X
1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 100.90 X
1	BUMPER HARNESS REAR	\$	<i>SL</i> 301.10 X
1	BOOT REAR	\$	<i>Bu</i> 1,677.20 ✓
1	BOOT FINISHER	\$	<i>SL</i> 344.70 X
1	BOOT WHEATERSTRIP	\$	<i>CM</i> 178.20 <i>508.20 89.10.50</i>
1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70 X
1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 277.70 ✓
1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 82.40 —
1	BOOT BADGE	\$	<i>N</i> 95.80 —
1	BOOT STRUT LH	\$	<i>SL</i> 145.10
1	BOOT STRUT RH	\$	<i>SL</i> 145.10
1	BOOT HINGE LH	\$	<i>N</i> 254.20 } X
1	BOOT HINGE RH	\$	<i>N</i> 253.80 }
1	BOOT TRIM BOARD	\$	<i>SL</i> 611.00
1	BOOT LOCK	\$	<i>N</i> 246.60

Trans-cab Auto Services Pte Ltd

AAD2004-100

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 380L

2	BOOT RUBBER PLUG	\$	Sn	139.30	X
1	BOOT SWITCH	\$	Sn	113.00	X
1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	X
2	LICENCE PLATE LAMP	\$	Sn	26.30	X
1	TAILLAMP RH	\$	mgm	313.10	✓
1	TAILLAMP PANEL RH	\$	R	401.40	X
1	TAILLAMP LH	\$	mgm	401.40	✓
1	TAILLAMP PANEL LH	\$	R	401.40	X
1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	nc	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	X
1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
1	SPARE TYRE BOARD	\$	Sn	680.90	X
1	EXHAUST REAR	\$	R	5,263.60	X
1	EXHAUST CAP REAR	\$	R	125.40	X
TOTAL		\$		17,992.87	
10%		\$		1,799.29	
		\$		16,193.58	

Special Nett

1SET	PARKING AID	\$	Sn	700.00	X
1SET	REAR BUMPER CLIP	\$	nc	69.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	nc	38.00	✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nc	20.00	X
1SET	BUMPER RETAINER RH CLIP RR	\$	nc	25.00	X
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nc	20.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	nc	25.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nc	30.00	X
1SET	BUMPER LOWER REAR CLIP	\$	nc	66.00	✓
2	END PANEL SEAM SEALANT	\$	nc	170.00	X
1SET	BOOT FINISHER CLIP	\$	nc	30.00	X
1	BOOT STICKER "Trans-cab"	\$	nc	35.00	30sn
1	BOOT STICKER "6555-3333"	\$	nc	35.00	30sn
1	BOOT INNER TRIM CLIP	\$	nc	45.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 380L**AAD2004-100**

1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Ph	385.00	X
1 SPARE TYRE	\$	Sh	330.00	X
1 TAILLAMP CLIP RH	\$	nh	25.00	✓
2 REAR WINDSCREEN SEALANT	\$	nn	150.00	X
1 WINDSCREEN MOULDING	\$	nn	180.00	X
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	120.00	X
1 TAILLAMP CLIP LH	\$	nh	25.00	✓
1 Rear Bumper Protector	\$	nn	120.00	3000
1SET Rear licence plate with holder	\$	Sh	100.00	X
1SET END PANEL INSULATION PAD	\$	Sh	200.00	X
TOTAL	\$		2,940.00	
TOTAL PARTS	\$		19,133.58	

LABOUR

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ nn 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 7,500.00 6000

To supply and re-do rear luggage floor panel insulation padding.

\$ nn 380.00 X

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 600

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 600

Trans-cab Auto Services Pte Ltd

AAD2004-100

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 380L

To repair and realign rear exhaust pipe.	\$	22	350.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	5	170.00	X
To check steering geometry and computer wheel alignment	\$	5	220.00	X
To Rust-Proofing Of The Affected Areas.	\$		170.00	601
Putty And Spray Painting Of The Affected Portion.	\$		7,500.00	661
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	5	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
To Check Electrical Lighting Concerned.	\$		170.00	201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	5	380.00	X
TOTAL	\$		18,660.00	
Over All Total	\$		37,793.58	

(LUMP SUM) Repair Days

~~25~~ DAYS

5 days

37,791.58#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: