

SJJ9171J.

TPQBE.

Hyundai Avante

Jasper.

KMHD841CMK4879307

Rear Number Plate	Bent	30(SN)	✓
Rear Number Plate Holder	Deformed	30(SN)	✓
Rear Number Plate Lamp	x 02 N/A nec	55.5 x 2 = 111	x
Rear Bumper	Deformed	654.30	✓
Rear Bumper Clips.	Nec	30	✓
Rear Bumper Side Holder	x 02 Nec	85.9 x 2 = 171.80	✓
Rear Bumper Lower Garnish	cracked.	496.30	✓
Rear Bumper Reflector	x 02 Cracked.	305.7 x 2 = 611.40	✓
Rear Bumper Reinforcement	cracked	345.40	✓
Rear Bumper Reinforcement Bracket	x 03 N/A nec	35 x 3 = 105	x
Reverse Sensor	Downyged	280(SN)	200(SN)
Rear End Panel	Dented	657.80	✓
Rear End Panel Top Garnish.	Cracked	175.80	✓
Rear End Panel Sealant.	Nec	60(SN)	✓
Rear End Panel Antenna Sensor	Downyged	191.60	✓
Bootlid	Dented	1853	✓
Bootlid Lock	N/A nec	145.70	x
Bootlid Weatherstripe.	N/A nec	145.60	x
Hyundai Logo	} Nec	68.90	✓
Avante Wording		80.30	✓
Elite Emblem		45.40	✓
Taillamp	x 02 N/A nec	545.6 x 2 = 1091.20	x
Spare Tyre Panel Top Cover	N/A nec	385.90	x
Rear Exhaust Pipe	} N/A nec	785	x
Rear Exhaust Mounting		28.50	x
Rear LH Undercover	✓ torn	94.30	✓

547640

SN: 320

JOC

438112

SJJ9171J

Panel Beating
Spray Painting
Wiring

To remove reverse sensor

To remove upholstery,

To underseal

To remove exhaust pipe

To transfer bootlid fittings.

~~1200~~ 800~~1000~~ 800~~50~~ 30~~100~~ 50~~150~~ 60~~150~~ 60

150 X

~~150~~ 50

Total: 655112

H/s: 52K.

06 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: