

ASS. REC. BY:

REF:

FC2/20005508/Kg9392

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cob

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SITC 5607G Yr Regn: 10, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 491083 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL 15/AUC 279378Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: M1 / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 29/4/20D.O.I. 30/4/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt Bump

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/

GIA not ready

15/5

L/Ry & 2550h Confirm

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

CLOSE: 30/7/2020

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G**AAD2004-099***Not Notion
L/Sing 82550/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

30 APR 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5607G

VF1ABL15AUC279378

RENAULT

LATITUDE

29.4.2020

FCIL

14/10/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	FRONT BRACE PANEL
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT LH
1	BONNET HINGE LH
1	BONNET LOCK
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL

	LIST
\$	<i>Bu</i> 747.20 ✓
\$	<i>Sn</i> 344.70 X
\$	<i>Sn</i> 394.68 X
\$	<i>Di</i> 101.40 ✓
\$	<i>Sn</i> 10.70 X
\$	<i>Sn</i> 292.50 X
\$	<i>Sn</i> 147.00 X
\$	<i>Sn</i> 207.21 X
\$	<i>R</i> 663.70 X
\$	<i>mgm</i> 743.60 ✓
\$	<i>R</i> 127.70 X
\$	<i>B</i> 414.40 ✓
\$	<i>Sn</i> 112.30
\$	<i>Sn</i> 38.90
\$	<i>Sn</i> 11.80
\$	<i>Sn</i> 65.50
\$	<i>R</i> 177.22
\$	<i>R</i> 1,312.70 } X
\$	<i>Sn</i> 294.30
\$	<i>Sn</i> 53.30
\$	<i>R</i> 236.50
\$	<i>R</i> 152.80
\$	<i>Sn</i> 969.90
\$	<i>Sn</i> 225.36
\$	<i>Sn</i> 686.00
\$	<i>Sn</i> 592.70

Trans-cab Auto Services Pte Ltd**AAD2004-099**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G

1	FRAME FULL SUPPORT BRACKET	\$	R	41.60	}	X
1	AIR CLEANER BOX	\$	Sn	464.20		
1	AIR CLEANER HOSE	\$	Sn	175.85		
1	AIR CLEANER LOWER	\$	Sn	271.26		
1	STEERING PUMP ELECTRIC L70Y	\$	Sn	2,026.70		
1	DOOR PANEL FRT LH	\$	R	2,844.66		
1	DOOR HINGE UPPER LH	\$	R	274.50		
1	DOOR HINGE LOWER LH	\$	R	300.55		
1	DOOR CHECK FRONT LH	\$	Sn	90.90		
1	DOOR MIRROR ASSY LH	\$	Sn	727.90		
1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00		
1	DOOR SEAL FRT LH	\$	Sn	69.60		
1	ROCKER PANEL OUTER LH	\$	R	1,184.99		
TOTAL		\$		20,266.77		
10%		\$		2,026.68		
		\$		18,240.10		

Special Nett

1	BUMPER CLIP FRT	\$	nn	66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	nn	25.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	nn	15.00	
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1	WHEELARCH CLIP FRT LH	\$	nn	35.00	
1	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
1SET	FRAME FULL SUPPORT PANEL NUT	\$	nn	25.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	35.00	
1SET	RADIATOR GRILLE SCREW	\$	nn	20.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	
1	FRONT LEFT TYRE	\$	Sn	330.00	
1	FRONT LEFT TYRE RIM	\$	Sn	380.00	
1SET	Front licence plate with holder	\$	Sn	100.00	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn	80.00	60sn
1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00	15sn
1	Windscreen moulding	\$	nn	180.00	X

Trans-cab Auto Services Pte Ltd

AAD2004-099

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G

2	FRONT WINDSCREEN SEALANT	\$	<i>nn</i>	140.00	X
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	120.00	X
TOTAL		\$		1,822.00	

TOTAL PARTS	\$	20,062.10
-------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *5001*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *5* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *5* 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 *601*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *6601*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

Trans-cab Auto Services Pte Ltd**AAD2004-099**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G

To Check Electrical Lighting Concerned.	\$	170.00	2ol
To rust-proofing of the affected areas.	\$	170.00	3ol
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
TOTAL	\$	14,340.00	
Over All Total	\$	34,402.10	

LUMP SUM (REPAIR DAY)~~20~~ days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5607G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Apr 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001928
Chassis No.:	VF1ABL15AUC279378
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Oct 2014
First Registration Date:	14 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$15,627.00
Total Rebate Amount:	\$24,375.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Apr 2020

OK