

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5607G****AAD2004-099***Not Authored  
L/Sing & 2550/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**30 APR 2020****SHC 5607G**

VF1ABL15AUC279378

RENAULT

LATITUDE

29.4.2020

**FCIL**

14/10/2014

| PART                              | LIST             |
|-----------------------------------|------------------|
| 1 BUMPER COVER FRT                | \$ Bu 747.20 ✓   |
| 1 BUMPER SPOILER FRT              | \$ Su 344.70 X   |
| 1 BUMPER ABSORBER FRT             | \$ Su 394.68 X   |
| 1 BUMPER RETAINER FRT LH          | \$ Di 101.40 ✓   |
| 1 BUMPER SUPPORT FRT              | \$ Su 10.70 X    |
| 1 BUMPER UNDERTRAY FRT            | \$ Su 292.50 X   |
| 1 BUMPER GRILLE LOWER FRT         | \$ Su 147.00 X   |
| 1 BUMPER FOG LAMP GRILLE LH       | \$ Su 207.21 X   |
| 1 BUMPER BEAM FRT                 | \$ R 663.70 X    |
| 1 HEADLAMP LH                     | \$ Mgem 743.60 ✓ |
| 1 HEADLAMP PANEL FRT LH           | \$ R 127.70 X    |
| 1 FENDER PANEL FRT LH             | \$ Bu 414.40 ✓   |
| 1 WHEELARCH FRT LH                | \$ Su 112.30     |
| 1 FENDER BRACKET FRT LH           | \$ Su 38.90      |
| 1 FENDER BRACKET LOWER LH         | \$ Su 11.80      |
| 1 FENDER INSULATOR LH             | \$ Su 65.50      |
| 1 FRONT BRACE PANEL               | \$ R 177.22      |
| 1 BONNET                          | \$ R 1,312.70 X  |
| 1 BONNET INSULATOR                | \$ Su 294.30     |
| 1 BONNET STRUT LH                 | \$ Su 53.30      |
| 1 BONNET HINGE LH                 | \$ R 236.50      |
| 1 BONNET LOCK                     | \$ R 152.80      |
| 1 RADIATOR GRILLE                 | \$ Su 969.90     |
| 1 RADIATOR GRILLE BADGE 'RENAULT' | \$ Su 225.36     |
| 1 RADIATOR GRILLE FRAME           | \$ Su 686.00     |
| 1 FRAME FULL SUPPORT PANEL        | \$ Su 592.70     |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5607G****AAD2004-099**

|       |                             |    |           |   |   |  |
|-------|-----------------------------|----|-----------|---|---|--|
| 1     | FRAME FULL SUPPORT BRACKET  | \$ | 41.60     | } | X |  |
| 1     | AIR CLEANER BOX             | \$ | 464.20    |   |   |  |
| 1     | AIR CLEANER HOSE            | \$ | 175.85    |   |   |  |
| 1     | AIR CLEANER LOWER           | \$ | 271.26    |   |   |  |
| 1     | STEERING PUMP ELECTRIC L70Y | \$ | 2,026.70  |   |   |  |
| 1     | DOOR PANEL FRT LH           | \$ | 2,844.66  |   |   |  |
| 1     | DOOR HINGE UPPER LH         | \$ | 274.50    |   |   |  |
| 1     | DOOR HINGE LOWER LH         | \$ | 300.55    |   |   |  |
| 1     | DOOR CHECK FRONT LH         | \$ | 90.90     |   |   |  |
| 1     | DOOR MIRROR ASSY LH         | \$ | 727.90    |   |   |  |
| 1     | DOOR HARNESS WIRE LH        | \$ | 2,670.00  |   |   |  |
| 1     | DOOR SEAL FRT LH            | \$ | 69.60     |   |   |  |
| 1     | ROCKER PANEL OUTER LH       | \$ | 1,184.99  |   |   |  |
| TOTAL |                             | \$ | 20,266.77 |   |   |  |
| 10%   |                             | \$ | 2,026.68  |   |   |  |
|       |                             | \$ | 18,240.10 |   |   |  |

**Special Nett**

|      |                                 |    |        |       |   |
|------|---------------------------------|----|--------|-------|---|
| 1    | BUMPER CLIP FRT                 | \$ | 66.00  | }     | X |
| 1    | BUMPER BRACKET CLIP FRT LH      | \$ | 25.00  |       |   |
| 1    | BUMPER SUPPORT CLIP FRT LH      | \$ | 15.00  |       |   |
| 1    | BUMPER GRILLE LOWER CLIP        | \$ | 69.00  |       |   |
| 1    | WHEELARCH CLIP FRT LH           | \$ | 35.00  |       |   |
| 1    | FRAME FULL SUPPORT PANEL CLIP   | \$ | 70.00  |       |   |
| 1SET | FRAME FULL SUPPORT PANEL NUT    | \$ | 25.00  |       |   |
| 2    | FRAME FULL SUPPORT PANEL STUD   | \$ | 35.00  |       |   |
| 1SET | RADIATOR GRILLE SCREW           | \$ | 20.00  |       |   |
| 1SET | RADIATOR GRILLE FRAME CLIP      | \$ | 52.00  |       |   |
| 1    | FRONT LEFT TYRE                 | \$ | 330.00 |       |   |
| 1    | FRONT LEFT TYRE RIM             | \$ | 380.00 |       |   |
| 1SET | Front licence plate with holder | \$ | 100.00 |       |   |
| 1    | FRONT DOOR STICKER 'Trans-Cab'  | \$ | 80.00  | 60.00 |   |
| 1    | FRONT DOOR STICKER 'Classic'    | \$ | 80.00  | 15.00 |   |
| 1    | Windscreen moulding             | \$ | 180.00 | X     |   |

**Trans-cab Auto Services Pte Ltd**

AAD2004-099

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G

|       |                                    |    |           |                 |   |
|-------|------------------------------------|----|-----------|-----------------|---|
| 2     | FRONT WINDSCREEN SEALANT           | \$ | <i>nn</i> | 140.00          | X |
| 1     | FRONT WINDSCREEN INNER SPONGE SEAL | \$ | <i>nn</i> | 120.00          | X |
| TOTAL |                                    | \$ |           | <u>1,822.00</u> |   |

|             |    |                  |
|-------------|----|------------------|
| TOTAL PARTS | \$ | <u>20,062.10</u> |
|-------------|----|------------------|

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *5000*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *4* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *4* 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 *600*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *6600*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5607G****AAD2004-099**

|                                                                          |           |                  |     |
|--------------------------------------------------------------------------|-----------|------------------|-----|
| To Check Electrical Lighting Concerned.                                  | \$        | 170.00           | 201 |
| To rust-proofing of the affected areas.                                  | \$        | 170.00           | 301 |
| To transfer of door fittings, attachment and perform water seepage test. | \$        | nn 170.00        | X   |
| To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.  | \$        | nn 170.00        | X   |
| <b>TOTAL</b>                                                             | <b>\$</b> | <b>14,340.00</b> |     |
| <b>Over All Total</b>                                                    | <b>\$</b> | <b>34,402.10</b> |     |

**LUMP SUM (REPAIR DAY)**

20 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: