

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G**AAD2004-099***Not Notified*
11 May 8 2550/-

Vehicle No.:

Chassis No.:

Vehicle Make:

30 APR 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5607G

VF1ABL15AUC279378

RENAULT

LATITUDE

29.4.2020

FCIL

14/10/2014

PART	LIST
1 BUMPER COVER FRT	\$ Bu 747.20 ✓
1 BUMPER SPOILER FRT	\$ Su 344.70 X
1 BUMPER ABSORBER FRT	\$ Su 394.68 X
1 BUMPER RETAINER FRT LH	\$ Di 101.40 ✓
1 BUMPER SUPPORT FRT	\$ Su 10.70 X
1 BUMPER UNDERTRAY FRT	\$ Su 292.50 X
1 BUMPER GRILLE LOWER FRT	\$ Su 147.00 X
1 BUMPER FOG LAMP GRILLE LH	\$ Su 207.21 X
1 BUMPER BEAM FRT	\$ R 663.70 X
1 HEADLAMP LH	\$ Mgem 743.60 ✓
1 HEADLAMP PANEL FRT LH	\$ R 127.70 X
1 FENDER PANEL FRT LH	\$ Bu 414.40 ✓
1 WHEELARCH FRT LH	\$ Su 112.30
1 FENDER BRACKET FRT LH	\$ Su 38.90
1 FENDER BRACKET LOWER LH	\$ Su 11.80
1 FENDER INSULATOR LH	\$ Su 65.50
1 FRONT BRACE PANEL	\$ R 177.22
1 BONNET	\$ R 1,312.70 X
1 BONNET INSULATOR	\$ Su 294.30
1 BONNET STRUT LH	\$ Su 53.30
1 BONNET HINGE LH	\$ R 236.50
1 BONNET LOCK	\$ R 152.80
1 RADIATOR GRILLE	\$ Su 969.90
1 RADIATOR GRILLE BADGE 'RENAULT'	\$ Su 225.36
1 RADIATOR GRILLE FRAME	\$ Su 686.00
1 FRAME FULL SUPPORT PANEL	\$ Su 592.70

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G**AAD2004-099**

1	FRAME FULL SUPPORT BRACKET	\$	41.60	}	X	
1	AIR CLEANER BOX	\$	464.20			
1	AIR CLEANER HOSE	\$	175.85			
1	AIR CLEANER LOWER	\$	271.26			
1	STEERING PUMP ELECTRIC L70Y	\$	2,026.70			
1	DOOR PANEL FRT LH	\$	2,844.66			
1	DOOR HINGE UPPER LH	\$	274.50			
1	DOOR HINGE LOWER LH	\$	300.55			
1	DOOR CHECK FRONT LH	\$	90.90			
1	DOOR MIRROR ASSY LH	\$	727.90			
1	DOOR HARNESS WIRE LH	\$	2,670.00			
1	DOOR SEAL FRT LH	\$	69.60			
1	ROCKER PANEL OUTER LH	\$	1,184.99			
TOTAL		\$	20,266.77			
10%		\$	2,026.68			
		\$	18,240.10			

Special Nett

1	BUMPER CLIP FRT	\$	66.00	}	X
1	BUMPER BRACKET CLIP FRT LH	\$	25.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	15.00		
1	BUMPER GRILLE LOWER CLIP	\$	69.00		
1	WHEELARCH CLIP FRT LH	\$	35.00		
1	FRAME FULL SUPPORT PANEL CLIP	\$	70.00		
1SET	FRAME FULL SUPPORT PANEL NUT	\$	25.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	35.00		
1SET	RADIATOR GRILLE SCREW	\$	20.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00		
1	FRONT LEFT TYRE	\$	330.00		
1	FRONT LEFT TYRE RIM	\$	380.00		
1SET	Front licence plate with holder	\$	100.00		
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00	60.00	
1	FRONT DOOR STICKER 'Classic'	\$	80.00	15.00	
1	Windscreen moulding	\$	180.00	X	

Trans-cab Auto Services Pte Ltd

AAD2004-099

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G

2	FRONT WINDSCREEN SEALANT	\$	<i>nn</i>	140.00	X
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	120.00	X
TOTAL		\$		<u>1,822.00</u>	

TOTAL PARTS	\$	<u>20,062.10</u>
-------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *5000*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *4* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *4* 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 *600*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *6600*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5607G**AAD2004-099**

To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
TOTAL	\$	14,340.00	
Over All Total	\$	34,402.10	

LUMP SUM (REPAIR DAY)

20 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: