

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B

AAD2004-097

*Not Authorized
Resurvey By mainf*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

30 APR 2020**SHD 9176B**

JTDKB3FU303079421

TOYOTA

PRIUS

28.4.2020

TOKIO MARINE

11/3/2019

PART**LIST**

1 FRONT BUMPER	\$	71	516.00	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	71	103.40	X
1 REINFORCEMENT, FRONT BUMPER	\$	71	716.60	✓
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	71	246.10	✓
1 COVER, FRONT BUMPER HOLE, LH	\$	71	29.30	✓
1 ABSORBER, FRONT BUMPER, LOWER	\$	CM	132.70	✓
1 ABSORBER, FRONT BUMPER ENERGY	\$	CM	79.60	✓
1 FRONT BUMPER SIDE RETAINER LH	\$	CM	82.30	✓
1 COVER SUB-ASSY, ENGINE, NO.1	\$	71	472.40	X
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	71	241.90	X
1 EXTENSION, FRONT BUMPER, LH	\$	71	120.10	X
1 FRONT LED LAMP (LOWER) LH	\$	CM	951.40	✓
1 FRONT HEADLAMP LH	\$	CM	2,637.60	✓
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$		960.50	?
1 MOTOR, HEADLAMP LEVELING, LH	\$		487.50	?
1 FRONT FENDER LH	\$	71	977.80	✓
1 LINER, FRONT FENDER, LH	\$	71	206.70	✓
1 EMBLEM, SIDE PANEL	\$	71	54.60	✓
1 PROTECTOR, FRONT FENDER SIDE PANEL, LH	\$	71	93.90	X
1 SEAL, FENDER APRON MUDGUARD, LH	\$	71	51.90	X
1 PAD, FRONT WHEEL OPENING EXTENSION, LH	\$	71	59.60	X
1 COVER SUB ASSY, FRONT PILLAR, UPR LH	\$	71	100.40	X
1 GRILLE SUB-ASSY, RADIATOR	\$	71	346.00	X
1 GRILLE, RADIATOR, LOWER NO.1	\$	71	170.10	X
1 EMBLEM ASSY, RADIATOR GRILLE	\$	71	90.80	X
1 FRONT BONNET	\$	71	983.10	X
1 HINGE ASSY, HOOD, LH	\$	71	58.90	✓
1 LOCK ASSY, HOOD	\$	71	135.00	X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2004-097

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B

1	INSULATOR, HOOD	\$	SL	410.90
1	BRACE, HOOD LOCK SUPPORT	\$	SL	78.30
1	COVER, RADIATOR SUPPORT OPENING	\$	SL	235.30
1	WIRE, ENGINE ROOM MAIN	\$	SL	7,323.90
1	WIRE, ENGINE	\$	SL	2,577.20
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	SL	245.10
1	SUPPORT SUB ASSY, RADIATOR, UPPER	\$	SL	377.10
1	SUPPORT SUB ASSY, RADIATOR, LOWER	\$	SL	409.90
1	SUPPORT, RADIATOR, UPPER LH	\$	N	78.90
1	APRON SUB-ASSY, FRONT FENDER, LH	\$	N	979.40
1	APRON ASSY, FRONT FENDER, LH	\$	N	176.80
1	MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT LH	\$	SL	62.80
1	MEMBER, FRONT APRON TO COWL SIDE, UPPER LH	\$	SL	110.00
1	BRACE SUB-ASSY, FENDER APRON, LH	\$	N	292.50
1	MEMBER SUB-ASSY, FRONT SIDE, LH	\$	N	2,397.60
1	MEMBER SUB-ASSY, FRONT SIDE, INNER LH	\$	N	794.70
1	PLATE, FRONT SIDE MEMBER, OUTER LH	\$	SL	292.10
1	MEMBER, FRONT SIDE INNER, LH	\$	N	459.60
1	REINFORCE SUB-ASSY, FRONT BUMPER MOUNTING, LH	\$	N	184.60
1	EXTENSION SUB-ASSY, FRONT SIDE MEMBER, LH	\$	N	110.00
1	SUPPORT, FRONT SIDE MEMBER, LH	\$	N	54.10
1	REINFORCEMENT, FRONT SIDE MEMBER, FRONT LH	\$	N	45.80
1	PANEL SUB-ASSY, FRONT STEP, LH	\$	SL	117.10
1	GUIDE, RADIATOR AIR, NO.3	\$	SL	112.70
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	SL	69.90
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$	SL	29.60
1	CONDENSER ASSY, COOLER	\$	SL	1,783.20
1	HOSE SUB-ASSY, SUCTION	\$	SL	646.80
1	HOSE SUB-ASSY, DISCHARGE	\$	SL	402.90
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	SL	691.00
1	PIPE SUB ASSY, SUCTION	\$	SL	465.80
1	SHROUD, FAN	\$	SL	264.70
1	FAN, LH	\$	SL	219.10
1	MOTOR, COOLING FAN MOTOR, LH	\$	SL	655.10
1	AIR CLEANER ASSY	\$	SL	1,137.60
1	BATTERY	\$	SL	1,584.90

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B**AAD2004-097**

1	TERMINAL, BATTERY POSITIVE	\$	58.10	
1	SENSOR ASSY, BATTERY STATE	\$	306.10	
1	HOLDER, BATTERY CURRENT SENSOR	\$	14.10	
1	BLOCK, JUNCTION	\$	18.80	
1	COVER, FUSIBLE LINK	\$	33.90	
1	BLOCK ASSY, FUSIBLE LINK	\$	200.12	
1	CLAMP SUB ASSY, BATTERY	\$	115.50	
1	CLAMP, BATTERY, NO.2	\$	51.80	
1	COVER, RELAY BLOCK, LOWER	\$	85.10	
1	HOLDER, CONNECTOR	\$	158.30	
1	RELAY, INTEGRATION NO.1	\$	295.80	
1	BLOCK ASSY, RELAY	\$	98.90	
1	COVER, RELAY BLOCK, UPPER, NO.1	\$	98.90	
1	LOUVER SUB ASSY, COWL TOP VENTILATOR	\$	686.80	
1	SHIELD, COWL WATER EXTRACT, LH	\$	19.60	
1	SHAFT ASSY, FRONT DRIVE, LH	\$	1,251.70	✓
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	760.10	✓
1	JOINT ASSY, LOWER BALL, FRONT LH	\$	283.40	?
1	KNUCKLE, STEERING, LH	\$	663.40	✓
1	LINK ASSY, FRONT STABILIZER, LH	\$	237.10	X
1	BAR, STABILIZER, FRONT	\$	367.30	?
1	BUSH, FRONT STABILIZER BAR, LH	\$	32.60	X
1	BRACKET, FRONT STABILIZER, NO.1 LH	\$	54.80	X
1	FRONT SHOCK ABSORBER	\$	438.30	✓
1	SUPPORT SUB-ASSY, FRONT SUSPENSION, LH	\$	236.40	X
1	SPRING, FRONT COIL, LH	\$	166.10	X
1	SEAT SUB-ASSY, FRONT SPRING LH, W/INSULATOR	\$	45.70	✓
1	GEAR ASSY, STEERING	\$	1,955.40	?
1	CROSSMEMBER SUB-ASSY, FRONT SUSPENSION	\$	2,585.50	✓
1	REINFORCEMENT SUB-ASSY, SIDE RAIL, REAR LH	\$	133.30	
1	COVER, MOTOR UNDER, REAR LH	\$	80.10	
1	DISC, FRONT	\$	502.70	
1	CYLINDER ASSY, FRONT DISC BRAKE, LH	\$	1,077.90	
1	MOUNTING, FRONT DISC BRAKE CYLINDER, LH	\$	230.00	
1	BRACKET, FRONT BUMPER SIDE, LH	\$	59.30	
1	BRACKET, HEADLAMP, LH	\$	34.80	
1	BRACKET, FRONT SIDE PANEL, LH	\$	58.50	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B**AAD2004-097**

1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50	} <i>Per X</i>
1	BRACKET, RADIATOR SHUTTER, LH	\$	23.20	
1	PIPE ASSY, EXHAUST, FRONT	\$	2,927.20	
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,339.30	
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80	
1	PANEL SUB ASSY, FRONT DOOR, LH	\$	1,300.70	
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	97.50	
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	110.60	
1	CHECK ASSY, FRONT DOOR	\$	183.80	
1	WEATHERSTRIP, FRONT DOOR, LH	\$	231.30	
1	RUN, FRONT DOOR GLASS, LH	\$	153.60	
1	TAPE, BLACK OUT, NO.1 LH	\$	13.30	
1	TAPE, BLACK OUT, NO.2 LH	\$	43.50	
1	TAPE, BLACK OUT, NO.3 LH	\$	26.30	
1	WIRE, FRONT DOOR, LH	\$	532.80	

TOTAL	\$	58,104.82
25%	\$	14,526.21
	\$	43,578.62

Special Nett

1	FRONT WHEEL RIM	\$	<i>Net</i> 1,879.40	✓
1	FRONT WHEEL RIM COVER	\$	<i>Net</i> 211.50	✓
1	FRONT TYRE 195/65/15	\$	<i>Net</i> 350.00	<i>70% Net</i>
1SET	CLIP, FRONT FENDER LINER	\$	<i>Net</i> 38.00	✓
1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>Net</i> 200.00	X
1SET	BUMPER CLIP FRT	\$	<i>Net</i> 69.00	✓
1SET	FRONT BUMPER RETAINER CLIP	\$	<i>Net</i> 38.00	} X
1	FRONT DOOR STICKER "Trans-Cab"	\$	<i>Net</i> 100.00	
1	WINDSCREEN SEALANT	\$	<i>Net</i> 150.00	
1	FRONT WINDSCREEN MOULDING	\$	<i>Net</i> 180.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>Net</i> 120.00	
1	WINDSCREEN MOULDING CLIP	\$	<i>Net</i> 30.00	
1SET	ROCKER PANEL MOULDING CLIP	\$	<i>Net</i> 38.00	} X
2	SEAM SEALANT (FOR BODY REPAIR)	\$	<i>Net</i> 170.00	
1SET	ENGINE UNDER COVER CLIP	\$	<i>Net</i> 35.00	

Trans-cab Auto Services Pte Ltd

AAD2004-097

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B

1SET HOOD INSULATOR CLIP

	\$	nn	25.00	X
TOTAL	\$		3,633.90	

TOTAL PARTS	\$		47,212.52	
--------------------	----	--	------------------	--

LABOUR

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	nn	380.00	X
----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		9,000.00	500
----	--	----------	-----

Putty And Spray Painting Of The Affected Portion.

\$		9,000.00	600
----	--	----------	-----

To transfer of Fender fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of Bonnet fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To Rust-Proofing Of The Affected Areas.

\$		170.00	300
----	--	--------	-----

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.

\$	nn	170.00	X
----	----	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	nn	380.00	X
----	----	--------	---

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$		380.00	200
----	--	--------	-----

To check ABS and brake efficiency, final checking and testing.

\$	nn	380.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

AAD2004-097

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B

To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	220.00	601
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	2401
To transfer of door fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	1001
Towing Fees	\$	170.00	501
To lift-up engine with gear box and refit.	\$	L 440.00	X
To remove and refit battery, electrical wiring, fuse box and relay to enable repair.	\$	S 400.00	X
To conduct and perform a comprehensive engine diagnostic check and reset vehicle warning indicators.	\$	S 400.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	S 170.00	X
To reseal sealant on gap	\$	L 170.00	X
TOTAL	\$	23,990.00	

Over All Total**\$ 71,202.52****(PART-BY-PART) Repair Days****30 days****40 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) id
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementing (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____