

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B

AAD2004-097

*Not Authorized**Recovery B4 paint**813,335.64*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

30 APR 2020**SHD 9176B**

JTDKB3FU303079421

TOYOTA

PRIUS

28.4.2020

TOKIO MARINE

11/3/2019

	PART		LIST	
1	FRONT BUMPER	\$	<i>Tu</i> 516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>su</i> 103.40	X
1	REINFORCEMENT, FRONT BUMPER	\$	<i>Bu</i> 716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	<i>Bu</i> 246.10	✓
1	COVER, FRONT BUMPER HOLE, LH	\$	<i>nu</i> 29.30	✓
1	ABSORBER, FRONT BUMPER, LOWER	\$	<i>cm</i> 132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	<i>cm</i> 79.60	✓
1	FRONT BUMPER SIDE RETAINER LH	\$	<i>cm</i> 82.30	✓
1	COVER SUB-ASSY, ENGINE, NO.1	\$	<i>su</i> 472.40	X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	<i>su</i> 241.90	X
1	EXTENSION, FRONT BUMPER, LH	\$	<i>su</i> 120.10	X
1	FRONT LED LAMP (LOWER) LH	\$	<i>cm</i> 951.40	✓
1	FRONT HEADLAMP LH	\$	<i>cm</i> 2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	<i>su</i> 960.50	X
1	MOTOR, HEADLAMP LEVELING, LH	\$	<i>su</i> 487.50	X
1	FRONT FENDER LH	\$	<i>Bu</i> 977.80	✓
1	LINER, FRONT FENDER, LH	\$	<i>mr</i> 206.70	✓
1	EMBLEM, SIDE PANEL	\$	<i>nu</i> 54.60	✓
1	PROTECTOR, FRONT FENDER SIDE PANEL, LH	\$	<i>su</i> 93.90	X
1	SEAL, FENDER APRON MUDGUARD, LH	\$	<i>nu</i> 51.90	X
1	PAD, FRONT WHEEL OPENING EXTENSION, LH	\$	<i>su</i> 59.60	X
1	COVER SUB ASSY, FRONT PILLAR, UPR LH	\$	<i>n</i> 100.40	X
1	GRILLE SUB-ASSY, RADIATOR	\$	<i>su</i> 346.00	X
1	GRILLE, RADIATOR, LOWER NO.1	\$	<i>su</i> 170.10	X
1	EMBLEM ASSY, RADIATOR GRILLE	\$	<i>su</i> 90.80	X
1	FRONT BONNET	\$	<i>n</i> 983.10	X
1	HINGE ASSY, HOOD, LH	\$	<i>dy</i> 58.90	✓
1	LOCK ASSY, HOOD	\$	<i>n</i> 135.00	X

338.20
100.00
100.00
500.00
200.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B**AAD2004-097**

1	INSULATOR, HOOD	\$	S _L	410.90
1	BRACE, HOOD LOCK SUPPORT	\$	S _L	78.30
1	COVER, RADIATOR SUPPORT OPENING	\$	S _L	235.30
1	WIRE, ENGINE ROOM MAIN	\$	S _L	7,323.90
1	WIRE, ENGINE	\$	S _L	2,577.20
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	S _L	245.10
1	SUPPORT SUB ASSY, RADIATOR, UPPER	\$	S _L	377.10
1	SUPPORT SUB ASSY, RADIATOR, LOWER	\$	S _L	409.90
1	SUPPORT, RADIATOR, UPPER LH	\$	N	78.90
1	APRON SUB-ASSY, FRONT FENDER, LH	\$	N	979.40
1	APRON ASSY, FRONT FENDER, LH	\$	N	176.80
1	MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT LH	\$	S _L	62.80
1	MEMBER, FRONT APRON TO COWL SIDE, UPPER LH	\$	S _L	110.00
1	BRACE SUB-ASSY, FENDER APRON, LH	\$	N	292.50
1	MEMBER SUB-ASSY, FRONT SIDE, LH	\$	N	2,397.60
1	MEMBER SUB-ASSY, FRONT SIDE, INNER LH	\$	N	794.70
1	PLATE, FRONT SIDE MEMBER, OUTER LH	\$	S _L	292.10
1	MEMBER, FRONT SIDE INNER, LH	\$	N	459.60
1	REINFORCE SUB-ASSY, FRONT BUMPER MOUNTING, LH	\$	N	184.60
1	EXTENSION SUB-ASSY, FRONT SIDE MEMBER, LH	\$	N	110.00
1	SUPPORT, FRONT SIDE MEMBER, LH	\$	N	54.10
1	REINFORCEMENT, FRONT SIDE MEMBER, FRONT LH	\$	N	45.80
1	PANEL SUB-ASSY, FRONT STEP, LH	\$	S _L	117.10
1	GUIDE, RADIATOR AIR, NO.3	\$	S _L	112.70
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	S _L	69.90
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$	S _L	29.60
1	CONDENSER ASSY, COOLER	\$	S _L	1,783.20
1	HOSE SUB-ASSY, SUCTION	\$	S _L	646.80
1	HOSE SUB-ASSY, DISCHARGE	\$	S _L	402.90
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	S _L	691.00
1	PIPE SUB ASSY, SUCTION	\$	S _L	465.80
1	SHROUD, FAN	\$	S _L	264.70
1	FAN, LH	\$	S _L	219.10
1	MOTOR, COOLING FAN MOTOR, LH	\$	S _L	655.10
1	AIR CLEANER ASSY	\$	S _L	1,137.60
1	BATTERY	\$	S _L	1,584.90

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B**AAD2004-097**

1	TERMINAL, BATTERY POSITIVE	\$		58.10	
1	SENSOR ASSY, BATTERY STATE	\$		306.10	
1	HOLDER, BATTERY CURRENT SENSOR	\$		14.10	
1	BLOCK, JUNCTION	\$		18.80	
1	COVER, FUSIBLE LINK	\$		33.90	
1	BLOCK ASSY, FUSIBLE LINK	\$		200.12	
1	CLAMP SUB ASSY, BATTERY	\$		115.50	
1	CLAMP, BATTERY, NO.2	\$		51.80	
1	COVER, RELAY BLOCK, LOWER	\$		85.10	
1	HOLDER, CONNECTOR	\$		158.30	
1	RELAY, INTEGRATION NO.1	\$		295.80	
1	BLOCK ASSY, RELAY	\$		98.90	
1	COVER, RELAY BLOCK, UPPER, NO.1	\$		98.90	
1	LOUVER SUB ASSY, COWL TOP VENTILATOR	\$		686.80	
1	SHIELD, COWL WATER EXTRACT, LH	\$		19.60	
1	SHAFT ASSY, FRONT DRIVE, LH	\$	R	1,251.70	car X
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	B	760.10	✓
1	JOINT ASSY, LOWER BALL, FRONT LH	\$	L	283.40	X
1	KNUCKLE, STEERING, LH	\$	B	663.40	✓
1	LINK ASSY, FRONT STABILIZER, LH	\$	L	237.10	X
1	BAR, STABILIZER, FRONT	\$	L	367.30	X
1	BUSH, FRONT STABILIZER BAR, LH	\$	L	32.60	X
1	BRACKET, FRONT STABILIZER, NO.1 LH	\$	L	54.80	X
1	FRONT SHOCK ABSORBER	\$	B	438.30	✓
1	SUPPORT SUB-ASSY, FRONT SUSPENSION, LH	\$	L	236.40	X
1	SPRING, FRONT COIL, LH	\$	L	166.10	X
1	SEAT SUB-ASSY, FRONT SPRING LH, W/INSULATOR	\$	L	45.70	X
1	GEAR ASSY, STEERING	\$	B	1,955.40	X
1	CROSSMEMBER SUB-ASSY, FRONT SUSPENSION	\$	B	2,585.50	✓
1	REINFORCEMENT SUB-ASSY, SIDE RAIL, REAR LH	\$	R	133.30	
1	COVER, MOTOR UNDER, REAR LH	\$	L	80.10	
1	DISC, FRONT	\$	L	502.70	
1	CYLINDER ASSY, FRONT DISC BRAKE, LH	\$	L	1,077.90	
1	MOUNTING, FRONT DISC BRAKE CYLINDER, LH	\$	L	230.00	
1	BRACKET, FRONT BUMPER SIDE, LH	\$	L	59.30	
1	BRACKET, HEADLAMP, LH	\$	L	34.80	
1	BRACKET, FRONT SIDE PANEL, LH	\$	L	58.50	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B**AAD2004-097**

1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50
1	BRACKET, RADIATOR SHUTTER, LH	\$	23.20
1	PIPE ASSY, EXHAUST, FRONT	\$	2,927.20
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,339.30
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80
1	PANEL SUB ASSY, FRONT DOOR, LH	\$	1,300.70
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	97.50
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	110.60
1	CHECK ASSY, FRONT DOOR	\$	183.80
1	WEATHERSTRIP, FRONT DOOR, LH	\$	231.30
1	RUN, FRONT DOOR GLASS, LH	\$	153.60
1	TAPE, BLACK OUT, NO.1 LH	\$	13.30
1	TAPE, BLACK OUT, NO.2 LH	\$	43.50
1	TAPE, BLACK OUT, NO.3 LH	\$	26.30
1	WIRE, FRONT DOOR, LH	\$	532.80

TOTAL	\$	58,104.82
25%	\$	14,526.21
	\$	43,578.62

Special Nett

1	FRONT WHEEL RIM	\$	1,879.40	✓
1	FRONT WHEEL RIM COVER	\$	211.50	✓
1	FRONT TYRE 195/65/15	\$	350.00	✓
1SET	CLIP, FRONT FENDER LINER	\$	38.00	✓
1	FRONT NUMBER PLATE WITH MOULDING	\$	200.00	✓
1SET	BUMPER CLIP FRT	\$	69.00	✓
1SET	FRONT BUMPER RETAINER CLIP	\$	38.00	✓
1	FRONT DOOR STICKER "Trans-Cab"	\$	100.00	✓
1	WINDSCREEN SEALANT	\$	150.00	✓
1	FRONT WINDSCREEN MOULDING	\$	180.00	✓
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	120.00	✓
1	WINDSCREEN MOULDING CLIP	\$	30.00	✓
1SET	ROCKER PANEL MOULDING CLIP	\$	38.00	✓
2	SEAM SEALANT (FOR BODY REPAIR)	\$	170.00	✓
1SET	ENGINE UNDER COVER CLIP	\$	35.00	✓

Trans-cab Auto Services Pte Ltd

AAD2004-097

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B

1SET HOOD INSULATOR CLIP

	\$	nn	25.00	X
TOTAL	\$		3,633.90	

TOTAL PARTS	\$		47,212.52	
--------------------	----	--	------------------	--

LABOUR

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	nn	380.00	X
----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		9,000.00	500
----	--	----------	-----

Putty And Spray Painting Of The Affected Portion.

\$		9,000.00	600
----	--	----------	-----

To transfer of Fender fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$	h	170.00	X
----	---	--------	---

To transfer of Bonnet fittings, attachments and perform water seepage test.

\$	h	170.00	X
----	---	--------	---

To Rust-Proofing Of The Affected Areas.

\$		170.00	300
----	--	--------	-----

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.

\$	h	170.00	X
----	---	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	h	380.00	X
----	---	--------	---

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$		380.00	200
----	--	--------	-----

To check ABS and brake efficiency, final checking and testing.

\$	h	380.00	X
----	---	--------	---

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9176B**AAD2004-097**

To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	220.00	601
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	2401
To transfer of door fittings, attachments and perform water seepage test.	\$	170.00	in X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	in X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	1001
Towing Fees	\$	170.00	501
To lift-up engine with gear box and refit.	\$	440.00	L X
To remove and refit battery, electrical wiring, fuse box and relay to enable repair.	\$	400.00	S X
To conduct and perform a comprehensive engine diagnostic check and reset vehicle warning indicators.	\$	400.00	S X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	S X
To reseal sealant on gap	\$	170.00	L X
TOTAL	\$	23,990.00	

Over All Total \$ 71,202.52**(PART-BY-PART) Repair Days****30 days****\$day,**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) of
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: