

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-060

DATE : 30-Apr-2020

POLICY NO. : PNPV2020-00002166

VEHICLE REG. NO. : SMK854R

VEHICLE MAKE : NISSAN NOTE 1.2 CVT

TO Motor Claim Department
 AXA INSURANCE SINGAPORE PTE LTD
 8 Shenton Way, #27-01 AXA Tower, Singapore 068811
 Tel: 1800-880-4741
 Fax: 6880 4740

FOR SURVEYOR

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	Acknowledged by Repairer	
			Signature	DATE
	SPARE PARTS			
1	Front Bumper / CR4.	1	\$ 480.00	\$ 480.00
2	Front Bumper Clips / Nec.	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH / BR	1	\$ 30.00	\$ 30.00
4	Front Bumper Retainer LH X Svc	1	\$ 30.00	\$ 30.00
5	Front Bumper Undercover / CR4.	1	\$ 380.00	\$ 380.00
6	Front Bumper Foglamp Garnish RH / CR4.	1	\$ 80.00	\$ 80.00
7	Front Reinforcement X Svc R	1	\$ 400.00	\$ 400.00
8	Front Sponge / CR4	1	\$ 250.00	\$ 250.00
9	Front Grille with Chrome Trim X Svc	1	\$ 300.00	\$ 300.00
10	Front Fender RH / PD	1	\$ 600.00	\$ 600.00
11	Front Fender Shield RH / CR4	1	\$ 120.00	\$ 120.00
12	Front Fender Clips / Nec	10	\$ 5.00	\$ 50.00
13	Front Headlamp RH / Svc CR4.	1	\$ 1,650.00	\$ 1,650.00
14	Front Wiper Tank Assy / CR4	1	\$ 180.00	\$ 180.00
Total Spare Parts			\$	4,600.00
	SPECIAL NETT			
Total Special Nett			\$	-
	LABOUR			
15	Spray Painting Front Bumper, Fender RH include Blending	1	\$ 600.00	\$ 600.00
16	Remove, Replace, Repair and Refit Accident Affected Area	1	\$ 600.00	\$ 600.00
17	Computerized Wheel Alignment	1	\$ 70.00	\$ 70.00
18	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour			\$	1,300.00
Amount Before Excess			\$	5,900.00
Add GST @ 7%				413.00
Total Amount Payable			\$	6,313.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Repair day - 7 days.

L/S

After paint photo

Sun Pm (Llc)

04/05/2020

TP without prejudice.

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Supplementary
Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-060 (SUP)

DATE : 6-May-2020

POLICY NO. : PNPV2020-00002166

VEHICLE REG. NO. : SMK854R

VEHICLE MAKE : NISSAN NOTE 1.2 CVT

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Tie Rod RH / CRU	1	\$ 150.00	\$ 150.00
2	Tie Rod End RH / BT	1	\$ 120.00	\$ 120.00
Total Spare Parts				\$ 270.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
3	Remove, Replace and Repair Front Undercarriage RH	1	\$ 250.00	\$ 250.00
Total Labour				\$ 250.00
Amount Before Excess				\$ 520.00
Add GST @ 7%				36.40
Total Amount Payable				\$ 556.40

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

$$\begin{array}{r}
 3,740 \\
 + 1,270 - \text{supp} \\
 \hline
 4,010 \\
 - 20\% \\
 \hline
 P = 3,208 \\
 L = 1,340 \\
 \hline
 4,548 \\
 - 20\% \\
 \hline
 3,638.4
 \end{array}$$

4/5
\$ 3,650
4 days

1090
250
1,340