

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Make & Model : Toyota

Wish

Vehicle Number : SKU9402Z

Quantity	Description	Repairer's Estimate
	SIDE	
1	Bumper Strip X N/A	\$489
1	RH Fender / DO	\$1,785
1	RH Side Mirror / MIS	\$1,200
1	Under Tray Cover X N/A	\$350
1	Rim tyre X N/A	\$360
1	RH Headlight / CUT	\$400 /
1	Condenser X N/A	\$450
1	Radiator X N/A	\$450
1	Reinforcement Bar Sponge X N/A	\$450
1	find RH Door Replace / DO	\$1,072 /
	LABOUR & MISC	
1	Tow	\$200 60 /
	Checking of wiring, lighting and resetting	\$400 30 /
	Remove and refit undercarriage	\$500 X
	Wheel alignment	\$300 X
	Remove and replace damaged parts (for door)	\$1,000 80 /
	Apply undercoating on repaired and replaced panel	\$800 30 /
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200 400 /
	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 400 /
	Total Repair Cost :	\$12,406

744 /
652 /

2868
-25%
2151

940

Steve (LKK) WTL PRL
4/5/20, 2.30pm
4 days
L/S
Ry AL SLy

Finalize \$1290
repair limit

P- 2151
N- 60
L- 940
3151
L/S-2520-80
= 2500