



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2004305  
INV Date 04/06/2020  
Reference CC6/EQI20005519/Aga3q2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SDG 9637U  
Insured Veh. SMF 7303U  
Claim No.  
Policy No. DMPPHQ19-007349  
Accident Date 31/03/2020  
Inspection Date 06/04/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI20005519/Aga3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 04-06-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SMF 7303U	<b>Veh. Inspected</b>	SDG 9637U
	<b>Policy No.</b>	DMPPHQ19-007349	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>		<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	06/04/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA CAMRY	<b>c.c</b>	1998
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
	<b>Chassis No.</b>	MR053BK4107044260	<b>Colour</b>	SILVER
	<b>Odometer</b>	96826	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	215/60 R16	GOODYEAR	6 mm
	<b>L/H Front Tyre</b>	215/60 R16	GOODYEAR	6 mm
	<b>R/H Rear Tyre</b>	215/60 R16	GOODYEAR	6 mm
	<b>L/H Rear Tyre</b>	215/60 R16	GOODYEAR	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	31/03/2020	<b>Inspection Date</b>	06/04/2020
	<b>Survey held at</b>	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>7 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDG 9637U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT LID	BUCKLED	980.20	980.20
2	REAR BOOT LID HINGE @\$131.75	NOT NECESSARY	263.50	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	76.10	76.10
1	REAR BOOT LID 2.5 LOGO	NECESSARY	53.20	53.20
1	REAR BOOT LID CAMRY LOGO	NECESSARY	74.00	74.00
2	REAR BOOT LID SIDE REFLECTOR @\$387.00	CUT	774.00	774.00
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID NUMBER PLATE GARNISH	CRACKED	387.00	387.00
1	REAR BOOT LID LOCK	DAMAGED	429.30	287.30
1	REAR BOOT LID WEATHERSTRIP	CUT	182.90	182.90
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	561.20	-
8	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$564.10	CRACKED	1,128.20	832.60
4	REAR TAIL LAMP CLIP @\$6.50	NECESSARY	26.00	26.00
2	REAR TAIL LAMP PANEL @\$193.20	TO REPAIR SEE LABOUR	386.40	-
1	REAR BUMPER	DISTORTED	561.60	561.60
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER INNER @\$131.20	NECESSARY	262.40	262.40
2	REAR BUMPER SIDE RETAINER OUTER @\$131.35	NOT NECESSARY	262.70	-
2	REAR BUMPER SIDE REFLECTOR @\$83.10	O/S CUT	166.20	83.10
1	REAR BUMPER REINFORCEMENT	DENTED	531.51	361.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	780.00	-
1	REAR END PANEL OUTER	DENTED	880.00	602.00
1	REAR END PANEL TOP GARNISH	DEFORMED	381.40	381.40
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	808.10	-
1	REAR SPARE TYRE PANEL TOP COVER	TORN	329.40	329.40
1	REAR SPARE TYRE PANEL SEALANT	NOT NECESSARY	450.00	-
2	REAR FENDER @\$981.45	TO REPAIR SEE LABOUR	1,962.90	-

Report Ref No. CC6/EQI20005519/Aga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIM BOARD @\$780.00	NOT NECESSARY	1,560.00	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR EXHAUST	BENT	891.85	891.85
1	REAR CENTER EXHAUST	NOT NECESSARY	981.20	-
2	REAR EXHAUST MOUNTING @\$65.90	NOT NECESSARY	131.80	-
	LESS 25% DISCOUNT		-	-1,794.01
			16,521.06	5,382.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
			350.00	200.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIT CUSHION .		280.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN .	NOT NECESSARY	120.00	-
	GUM .	NOT NECESSARY	60.00	-
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT REVERSE CAMERA.		180.00	50.00
	TO REMOVE & REFIT REAR AND CENTER EXHAUST .	NOT NECESSARY	380.00	-
	TO CHECK WIRING .		100.00	30.00
	TUFF KOTE.		150.00	60.00
	TOWING FEE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL,REAR END PANEL INNER ,REAR FENDER AND REAR SPARE TYRE PANEL .		1,600.00	1,000.00
	SPRAY PAINTING.		1,600.00	1,000.00
			4,720.00	2,250.00
<b>GRAND TOTAL</b>			<b>21,591.06</b>	<b>7,832.04</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,200.00</b>

Report Ref No. CC6/EQI20005519/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SDG 9637U

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDG 9637U

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

