



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

31-03-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPEQ.

Cecilia.

Accident date: 31/03/2020

Estimated repair cost for vehicle no: SDG9637U TOYOTA CAMRY 2.0 AUTO '09

CHASSIS: MR053BK4107044260

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$980.20 ✓
2	2	Rear Boot Lid Hinge <i>Not nec</i>	\$131.75	\$263.50 X
3	1	Rear Boot Lid Emblem Logo <i>?</i>		\$76.10 ✓
4	1	Rear Boot Lid 2.0 Logo <i>Nec</i>		\$53.20 ✓
5	1	Rear Boot Lid Camry Logo		\$74.00 ✓
6	2	Rear Boot Lid Side Reflector <i>cut</i>	\$387.00	\$774.00 ✓
7	1	Rear Boot Lid Number Plate <i>Not nec</i>		\$50.00 X
8	1	Rear Boot Lid Number Plate Garnish <i>cracked</i>		\$387.00 ✓
9	1	Rear Boot Lid Lock <i>Damaged</i>		\$429.30 287.30 ✓
10	1	Rear Boot Lid Weatherstrip <i>cut</i>		\$182.90 ✓
11	1	Rear Boot Lid Inner Trim Board <i>Not</i>		\$561.20 X
12	8	Rear Boot Lid Inner Trim Board Clip <i>Nec</i>	\$6.50	\$52.00 X
13	2	Rear Tail Lamp <i>cracked</i>	\$564.10	\$1,128.20 832.60 ✓
14	4	Rear Tail Lamp Clip <i>nec</i>	\$6.50	\$26.00 ✓
15	2	Rear Tail Lamp Panel <i>Repair</i>	\$193.20	\$386.40 X
16	1	Rear Bumper <i>Distorted</i>		\$561.60 ✓
17	8	Rear Bumper Clip <i>nec</i>	\$6.50	\$52.00 30 ✓
18	2	Rear Bumper Side Retainer Inner <i>nec</i>	\$131.20	\$262.40 ✓
19	2	Rear Bumper Side Retainer Outer <i>nec</i>	\$131.35	\$262.70 X
20	2	Rear Bumper Side Reflector <i>RH cut</i>	\$83.10	\$166.20 83.10 ✓
21	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00 200 (sn) ✓
22	1	Rear Bumper Reinforcement <i>Dented</i>		\$531.51 361 ✓
23	1	Rear End Panel Inner <i>Repair</i>		\$780.00 X
24	1	Rear End Panel Outer <i>Dented</i>		\$880.00 602 ✓
25	1	Rear End Panel Top Garnish <i>Deformed</i>		\$381.40 ✓
26	1	Rear Spare Tyre Panel <i>Repair</i>		\$808.10 X
27	1	Rear Spare Tyre Panel Top Cover <i>torn</i>		\$329.40 ✓
28	1	Rear Spare Tyre Panel Sealant <i>Not nec</i>		\$450.00 X

29	2	Rear Fender <i>Repis</i>	\$981.45	\$1,962.90 <i>X</i>
30	2	Rear Fender Inner Trim Board <i>3 MP</i>	\$780.00	\$1,560.00 <i>X</i>
31	16	Rear Fender Inner Trim Board Clip <i>3 MP</i>	\$6.50	\$104.00 <i>X</i>
32	1	Rear Exhaust <i>Best</i>		\$891.85 <i>X</i>
33	1	Rear Center Exhaust <i>He me</i>		\$981.20 <i>X</i>
34	2	Rear Exhaust Mounting <i>Ne me</i>	\$65.90	\$131.80 <i>X</i>

717605

Subtotal :- \$16,871.06

5382.03. S.N: 200

Labour charges

To remove & refit cushion	2250	\$280.00 60
To remove & refit rear windscreen		\$120.00 <i>X</i>
Gum		\$60.00 <i>X</i>
To remove & refit reverse sensor		\$100.00 50
To remove & refit reverse camera		\$180.00 50
To remove & refit rear and center exhaust		\$380.00 <i>X</i>
To check wiring		\$100.00 30
Tuff kote		\$150.00 60
Towing fee		\$150.00 <i>X</i>
Panel beating		\$1,600.00 1000
Spray painting		\$1,600.00 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$4,720.00

Total:- \$21,591.06

total 7832.03

h/s: 6.21K

07 Days