

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Order No: **SFQ5828K**
 Model: **Lexus IS250**
 Order No:
 Date of manufacturing:

#	DESCRIPTION List Item	QTY	U/P	AMT
	Front bumper / Re	1		1256.30 570
	Front bumper retainer RH X NN	1		92.50 X
	Front bumper retainer LH / Re	1		92.50 50
	Front bumper bracket RH X	1		125.00 X
	Front bumper bracket LH X	1		125.00 X
	Front bumper sponge X	1		233.50 X
	Front bumper reinforcement X	1		574.60 X
	Fog lamp LH X / CRA	1		253.60 /
	Fog lamp garnish LH X	1		156.20 X
	Front bumper lower grille X	1		289.30 X
	Radiator grille assy X	1		598.10 X
	Front bumper towing cap X	1		75.20 X
	Front fender LH X Repair	1		785.80 X
	Front fender inner shield LH / TN	1		168.40 /
	Head lamp LH X / CRA	1		1245.60 900
	Front absorber LH X	1		521.30 X
	Front knuckle arm LH X	1		565.70 X
	Front upper arm LH X	1		362.50 X
	Front lower arm LH X	1		373.60 X
	Front knuckle bearing LH X	1		215.60 X
				8110.30 1942
	Special Nett Items			25%: 1456.5
	Front wheel rim LH X / NN	1		700.00 X
	Front wheel tyre LH X	1		250.00 X
	Front bumper clip set / NEC	1		50.00 30
	Front fender inner shield clip set / NEC	1		50.00 20
				1050.00 50
	Labour & Miscellaneous Charge			
	To check wiring and lighting system		100.00	X 30
	To conduct head lamp focus		120.00	X
	To supply under coating on parts replaced		80.00	X
	To perform anti rust treatment on affected areas		60.00	X NN

To conduct all wheel alignment before and after
 To R&R front LH wheel rim , tyre and balancing
 To press front LH knuckle bearing assy
 To R&R front LH under carriage damaged parts
 To repair , replace and realign damaged areas
 To spray painting on affected areas
 Sundries

180.00 X
 50.00 X
 100.00 X
 350.00 X
 900.00
 800.00
 50.00 X
 880

2790.00

2386.5

20% : 1900

List Items Subtotal
 Special Nett Items Subtotal
 Labour Items Subtotal
 Total

11,950.30

4 Days.

(lump sum Repair).

After repair photos.

lump

05/5/2020.

Guo Qiang - 82880282.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey, refinish and repaint
- To display damaged parts during the survey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: