



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101376

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 05/03/2021  
Reference CC6/FCI20005526/Uea3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. GBE 7740B  
Insured Veh. SHC 1690R  
Claim No. D20002029MFSH  
Policy No. D-18088936MFSH  
Accident Date 30/04/2020  
Inspection Date 04/05/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 500.00        |
| <b>Subtotal</b>                | <b>500.00</b> |
| <b>GST (7%)</b>                | <b>35.00</b>  |
| <b>Grand Total</b>             | <b>535.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                 |                             |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------|-----------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                |                                                                                      |                 | Ref: CC6/FCI20005526/Uea3q2 |  |
|                                                                                                                                        |                                                                                      |                 | Date: 05/03/2021            |  |
|                                                                                                                                        |                                                                                      |                 | Code: FCI2                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                 |                             |  |
| Insured Veh.                                                                                                                           | SHC 1690R                                                                            | Veh. Inspected  | GBE 7740B                   |  |
| Policy No.                                                                                                                             | D-18088936MFSH                                                                       | Coverage (\$)   | 0.00                        |  |
| Claim No.                                                                                                                              | D20002029MFSH                                                                        | Excess (\$)     | 0.00                        |  |
| Assign From                                                                                                                            | VIC                                                                                  | Assign Date     | 04/05/2020                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                 |                             |  |
| Make & Model                                                                                                                           | TOYOTA HIACE (M)                                                                     | c.c             | 2982                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.    | 2016                        |  |
| Chassis No.                                                                                                                            | JTFHT02P400189604                                                                    | Colour          | SILVER                      |  |
| Odometer                                                                                                                               | 199043 KM                                                                            | Steering        | IN ORDER                    |  |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification    | NIL                         |  |
| General                                                                                                                                | GOOD                                                                                 |                 |                             |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                 |                             |  |
|                                                                                                                                        | Size                                                                                 | Make            | Balance                     |  |
| R/H Front Tyre                                                                                                                         | 195 R15                                                                              | MICHELIN        | 6 mm                        |  |
| L/H Front Tyre                                                                                                                         | 195 R15                                                                              | MICHELIN        | 6 mm                        |  |
| R/H Rear Tyre                                                                                                                          | 195 R15                                                                              | MICHELIN        | 6 mm                        |  |
| L/H Rear Tyre                                                                                                                          | 195 R15                                                                              | MICHELIN        | 6 mm                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                 |                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                      |                 |                             |  |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                 |                             |  |
| Accident Date                                                                                                                          | 30/04/2020                                                                           | Inspection Date | 04/05/2020                  |  |
| Survey held at                                                                                                                         | FALCON-AIR AUTO SERVICES PTE LTD<br>BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840 |                 |                             |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                 |                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                 |                             |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                      |                 |                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      |                 | <b>5 Working Days</b>       |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7740B

| Qty                                | Description of Parts                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                              |                      |                           |                   |
| 1                                  | TAILGATE                                     | BADLY DENTED         | 2,165.00                  | 2,135.20          |
| 1                                  | TAILGATE LOGO EMBLEM                         | NECESSARY            | 85.00                     | 66.80             |
| 1                                  | TAILGATE TOYOTA STICKER                      | NECESSARY            | 95.00                     | 68.20             |
| 1                                  | TAILGATE HIACE STICKER                       | NECESSARY            | 95.00                     | 65.00             |
| 1                                  | TAILGATE INNER TRIM BOARD                    | NOT NECESSARY        | 395.00                    | -                 |
| 1                                  | O/S TAILGATE EDGE RUBBER                     | NOT NECESSARY        | 49.00                     | -                 |
| 1                                  | REAR BUMPER                                  | DISTORTED            | 665.00                    | 566.10            |
| 1                                  | O/S REAR BUMPER SIDE RETAINER                | CRACKED              | 65.00                     | 65.00             |
| 1                                  | TAILGATE LOCK                                | DENTED / JAMMED      | 485.00                    | 391.10            |
| 1                                  | TAILGATE WEATHERSTRIP                        | TWISTED              | 495.00                    | 368.90            |
| 1                                  | REAR END PANEL-OUTER                         | BADLY DENTED         | 881.00                    | 881.00            |
| 1                                  | REAR END PANEL-INNER                         | BADLY DENTED         | 1,155.00                  | 981.10            |
| 1                                  | REAR END PANEL GARNISH                       | NOT NECESSARY        | 295.00                    | -                 |
| 1                                  | EXHAUST MUFFLER                              | TO REPAIR SEE LABOUR | 975.00                    | -                 |
| 1                                  | EXHAUST MUFFLER GASKET                       | NOT NECESSARY        | 65.00                     | -                 |
| 1                                  | EXHAUST MUFFLER RUBBER HANGER                | NOT NECESSARY        | 75.00                     | -                 |
| 1                                  | O/S TAILLAMP                                 | CRACKED              | 485.80                    | 408.20            |
| 1                                  | O/S TAILLAMP LOWER PANEL                     | DENTED               | 195.00                    | 195.00            |
| 1                                  | O/S TAILLAMP LOWER PANEL RETAINER            | NO SUCH PARTS        | 55.00                     | -                 |
|                                    | LESS 25% DISCOUNT                            |                      | -2,193.95                 | -1,547.90         |
|                                    |                                              |                      | 6,581.85                  | 4,643.70          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                              |                      |                           |                   |
| 1                                  | TAILGATE SEALANT (SN)                        | NOT NECESSARY        | 100.00                    | -                 |
| 1                                  | BTL TAILGATE GLASS SEALANT (SN)              | NECESSARY            | 40.00                     | 40.00             |
| 1                                  | TAILGATE GLASS INNER SEAL (SN)               | NECESSARY            | 80.00                     | 30.00             |
| 1                                  | TAILGATE MICHELIN STICKER (SN)               | NECESSARY            | 150.00                    | 50.00             |
| 1                                  | 70KM/H STICKER (SN)                          | NECESSARY            | 40.00                     | 10.00             |
| 1                                  | COMPANY LOGO STICKER (SN)                    | NECESSARY            | 250.00                    | 100.00            |
| 1                                  | COMPANY QR STICKER (SN)                      | NECESSARY            | 250.00                    | 180.00            |
| 12                                 | TAILGATE INNER TRIM BOARD CLIPS @\$5.00 (SN) | NOT NECESSARY        | 60.00                     | -                 |

Report Ref No. CC6/FCI20005526/Uea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                                                                                                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 12                                                                          | REAR BUMPER CLIP @\$5.00 (SN)                                                                                                                                                        | NECESSARY     | 60.00                     | 50.00             |
| 1                                                                           | REVERSE SENSOR (SN)                                                                                                                                                                  | SHORTED       | 250.00                    | 200.00            |
|                                                                             |                                                                                                                                                                                      |               | 1,280.00                  | 660.00            |
|                                                                             | <b><u>LABOUR</u></b>                                                                                                                                                                 |               |                           |                   |
|                                                                             | TO CHECK LIGHT SYSTEM AND WIRING.                                                                                                                                                    |               | 50.00                     | 20.00             |
|                                                                             | RE-SPRAY ANTI-RUST.                                                                                                                                                                  |               | 150.00                    | 60.00             |
|                                                                             | INSTALL REVERSE SENSOR.                                                                                                                                                              |               | 120.00                    | 50.00             |
|                                                                             | APPLY BODY SEALANT TO CAR JOINTS.                                                                                                                                                    | NOT NECESSARY | 150.00                    | -                 |
|                                                                             | INSTALL REVERSE CAMERA.                                                                                                                                                              |               | 150.00                    | 40.00             |
|                                                                             | TRANSFER TAILGATE GLASS.                                                                                                                                                             |               | 150.00                    | 100.00            |
|                                                                             | TRANSFER TAILGATE PARTS.                                                                                                                                                             |               | 150.00                    | 60.00             |
|                                                                             | TO WATER TEST TO CHECK FOR WATER LEAKAGE.                                                                                                                                            | NOT NECESSARY | 50.00                     | -                 |
|                                                                             | TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL,REPAIR INNER PANEL,REWELD INNER PANEL,REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME.INCLUSIVE OF THE REPAIR OF EXHAUST MUFFLER. |               | 900.00                    | 700.00            |
|                                                                             | TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS.                                                                                                                                         |               | 900.00                    | 600.00            |
|                                                                             |                                                                                                                                                                                      |               | 2,770.00                  | 1,630.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                                      |               | <b>10,631.85</b>          | <b>6,933.70</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                      |               |                           | <b>5,500.00</b>   |

Report Ref No. CC6/FCI20005526/Uea3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBE 7740B

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 7740B

RE-INSPECTION

