

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D



FALCON-AIR

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES707656

Date : 04/05/2020

Vehicle Num. : GBE 7740B

Make/Model : TOYOTA HIACE

Chassis/Eng# : JTFHT02P400189604

Accident Date : 30/04/2020

Claim No. :

Reference : 3PTY 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	LIST ITEMS :		
2.	1 PC	TAILGATE	2135.20	2,165.00 ✓
3.	1 PC	TAILGATE LOGO EMBLEM	66.80	85.00 ✓
4.	1 PC	TAILGATE TOYOTA STICKER	68.20	95.00 ✓
5.	1 PC	TAILGATE HIACE STICKER	65.00	95.00 ✓
6.	1 PC	TAILGATE INNER TRIM BOARD		395.00 X
7.	1 PC	O/S TAILGATE EDGE RUBBER		49.00 X
8.	1 PC	REAR BUMPER	566.10	665.00 ✓
9.	1 PC	O/S REAR BUMPER SIDE RETAINER	391.10	65.00 ✓
10.	1 PC	TAILGATE LOCK	368.90	485.00 ✓
11.	1 PC	TAILGATE WEATHERSTRIP		495.00 ✓
12.	1 PC	REAR END PANEL - OUTER		881.00 ✓
13.	1 PC	REAR END PANEL - INNER	981.10	1,155.00 ✓
14.	1 PC	REAR END PANEL GARNISH		295.00 X
15.	1 PC	EXHAUST MUFFLER		975.00 X
16.	1 PC	EXHAUST MUFFLER GASKET		65.00 X
17.	1 PC	EXHAUST MUFFLER RUBBER HANGER		75.00 X
18.	1 PC	O/S TAILLAMP	408.20	485.80 ✓
19.	1 PC	O/S TAILLAMP LOWER PANEL		195.00 ✓
		O/S TAILLAMP LOWER PANEL RETAINER		55.00 X
List Total S\$:				8,775.80
25.00% Discount S\$:				2,193.95
				6,581.85

Not Authorized
4/5/20
2/5/20
5 days.
The phl. Attorney

CONTINUE / ...

1-61916
257
4648.7

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

**FALCON-AIR**

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES707656

Date : 04/05/2020

Vehicle Num : GBE 7740B

Make/Model : TOYOTA HIACE

Chassis/Eng# : JTFHT02P400189604

Accident Date : 30/04/2020

Claim No. :

Reference : 3PTY 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

1.	1 PC	SPECIAL NETT ITEMS :		
2.	1 BTL	TAILGATE SEALANT	117	100.00 X
3.	1 PC	TAILGATE GLASS SEALANT	117	40.00 ✓
4.	1 PC	TAILGATE GLASS INNER SEAL	117	80.00 30
5.	1 PC	TAILGATE MICHELIN STICKER	117	150.00 50
6.	1 PC	70KM/H STICKER	117	40.00 10
7.	1 PC	COMPANY LOGO STICKER	117	250.00 100
8.	1 PC	COMPANY QR STICKER	117	250.00 100
9.	12 PC	TAILGATE INNER TRIM BOARD CLIPS	117	5.00 60.00 X
10.	12 PC	REAR BUMPER CLIP	117	5.00 60.00 X
11.	1 PC	REVERSE SENSOR	117	250.00 200

Special Nett Total SS :

1,280.00

LABOUR :

TO CHECK LIGHT SYSTEM AND WIRING
RE-SPRAY ANTI-RUST
INSTALL REVERSE SENSOR
APPLY BODY SEALANT TO CAR JOINTS
INSTALL REVERSE CAMERA
TRANSFER TAILGATE GLASS
TRANSFER TAILGATE PARTS
TO WATER TEST TO CHECK FOR WATER LEAKAGE

50.00 20
150.00 60
120.00 50
117 150.00 X
150.00 40
150.00 100
150.00 60
117 50.00 X

CONTINUE / ...

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

9-46437
S.N-660
L-1630
69337
206
1546

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877Attention : Motor Claim Department
Contact : 62222311 Fax No. : 62223547

Estimate : ES707656

Date : 04/05/2020
Vehicle Num. : GBE 7740B
Make/Model : TOYOTA HIACE
Chassis/Eng# : JTFHT02P400189604
Accident Date : 30/04/2020
Claim No. :
Reference : 3PTY 1/2
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL REPAIR
INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED
PARTS AND ALIGN THE SAME
TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS

900.00	700
900.00	600
2,770.00	

Labour Total SS :

E. & O.E.	Total SS	10,631.85

for FALCON-AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg