

ASS. REC. BY:

REF:

AIG/20005527/KK03

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

KGC

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STJ 4446A

Yr Regn:

09, 08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1595

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

47445

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTHMFD 46208'S 202451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

1/5/20

D.O.I.

4/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11 Sep 8 240d Car hire

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Not Notwork
C/Rep &?
Resurvey After Paint
4-5 days

SOLAR LOGISTICS PTE LTD
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP 200501
Date 4/5/2020
No of Page : 1/3

Registraion No : SJJ 4446A

Accident Date : 1-May-20

Our Ref : TP 200501

Model : Honda Civic 1.6
Chassis No: JHMFD46208S202451
Engine Capacity :

S/No	Qty	Items	Unit Price	Amount
1	1	Rear bumper <i>Br</i>	\$	-
2	2	Rear bumper retainer <i>X 1m</i>	\$	-
3	1	Rear bumper reinforcement <i>N/A</i>	\$	-
4	1	Rear bumper sponge <i>N/A</i>	\$	-
5	1	Rear end panel <i>?</i>	\$	-
6	1	Rear end panel Garnish <i>?</i>	\$	-
7	1	Tailgate <i>Boot lid Br</i>	\$	-
8	1	Tailgate Garnish <i>Br X</i>	\$	-
9	1	Tailgate Hinge <i>R X</i>	\$	-
10	1	Tailgate Absorber <i>Br X</i>	\$	-
11	2	Tailgate Stoper (Big) <i>Br X</i>	\$	-
12	2	Tailgate Stoper (Small) <i>Br X</i>	\$	-
13	1	Tailgate weather ship <i>Br X</i>	\$	-
14	1	Tailgate Lock <i>Not</i>	\$	-
15	1	Tailgate Lock(Key) <i>Br X</i>	\$	-
16	2	Number plate Lamp <i>Br X</i>	\$	-
17	2	Tail Lamp LED (Body) <i>Br X</i>	\$	-
18	2	Tail Lamp LED (Tailgate) <i>N/A</i>	\$	-
19	2	Rear Fender Shield <i>Br X</i>	\$	-
20	1	Exhaust pipe <i>R X</i>	\$	-

\$	-
-25% \$	-
Total for spare parts \$	-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Special Nett

1	1 set	Rear Bumper Clips	\$	50.00	\$	na	50.00	✓
2	10	Tailgate Hinge Clips						X
3	1 set	Reverse sensor						✓
4	1	No. Plate with Casing	\$	80.00	\$		80.00	✓
5	1	Emblem "Honda" Logo						✓
6	1	Emblem "Civic"						✓
7	1	Emblem "i-VTEC1.6"						✓
8	1	Spare tyre Box						✓

Total for SP	\$	130.00
Sub-Total for Parts :	\$	130.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		1,200.00 ?
2		To putty and spray paint on all accident damage parts and other accident affected areas		1,000.00 600/
3		To remove and refit reverse sensor		120.00 50/
4		To check wiring system to facilitate repair and refit the same		120.00 20/
5		Apply rust proofing on the adjacent panels		50.00 ?
6		To remove and refit exhaust pipe		na 80.00 X
TOTAL AMOUNT :				2,570.00
OVERALL COST :				2,700.00



KGC WORKSHOP PTE LTD

Since 1987

Sincere • Secure • Satisfaction

Not Notified
6/1 Sup @ 2400h
Resurvey After Painting
4-5 days

SOLAR LOGISTICS PTE LTD
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP 200501
Date 4/5/2020
No of Page : 1/3

Registration No : SJJ 4446A

Accident Date : 1-May-20

Our Ref : TP 200501

Model : Honda Civic 1.6

Chassis No: JHMFD46208S202451

Engine Capacity :

S/No	Qty	Items	Unit Price	Amount
1	1	Rear bumper <i>Per</i>	638.00	\$ 638.00 -
2	2	Rear bumper retainer <i>X Sm</i>	14.60	\$ 29.20 -
3	1	Rear bumper reinforcement <i>N/A</i>	Nil	\$ Nil -
4	1	Rear bumper sponge <i>N/A</i>	Nil	\$ Nil -
5	1	*Rear end panel <i>?</i>	<i>By</i> 320.50	\$ 320.50 -
6	1	Rear end panel Garnish <i>?</i>	<i>Sm</i> 66.60	\$ 66.60 X
7	1	Tailgate <i>Boothed Per</i>	610.70	\$ 610.70 -
8	1	Tailgate Garnish <i>Sm X</i>	121.60	\$ 121.60 -
9	1	Tailgate Hinge <i>R X</i>	48.60	\$ 48.60 -
10	1	Tailgate Absorber <i>Sm X</i>	120.00	\$ 120.00 -
11	2	Tailgate Stoper (Big) <i>Sm X</i>	10.00	\$ 20.00 -
12	2	Tailgate Stoper (Small) <i>Sm X</i>	8.00	\$ 16.00 -
13	1	Tailgate weather ship <i>Sm X</i>	97.60	\$ 97.60 -
14	1	Tailgate Lock <i>Not</i>	194.50	\$ 194.50 -
15	1	Tailgate Lock(Key) <i>Sm X</i>	97.20	\$ 97.20 -
16	2	Number plate Lamp <i>Sm X</i>	28.00	\$ 56.00 -
17	2	Tail Lamp LED (Body) <i>Sm X</i>	226.20	\$ 452.40 -
18	2	Tail Lamp LED (Tailgate) <i>MS G/L</i>	184.60	\$ 369.20 -
19	2	Rear Fender Shield <i>Sm X</i>	19.00	\$ 38.00 -
20	1	Exhaust pipe <i>R X</i>	535.00	\$ 535.00 -

	\$	3,831.10	-
-20% ≡	\$	766.22	-
Total for spare parts	\$	3,064.88	-



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Special Nett

1	1 set	Rear Bumper Clips	\$	50.00	\$	<i>na</i>	50.00	✓
2	10	Tailgate Hinge Clips <i>X</i>	\$	3.50	\$	<i>na</i>	35.00	<i>X</i>
3	1 set	Reverse sensor <i>Per X</i>	\$	200.00	\$		200.00	
4	1	No. Plate with Casing <i>Per X</i>	\$	80.00	\$		80.00	
5	1	Emblem "Honda" Logo <i>na</i>	\$	28.70	\$		28.70	
6	1	Emblem "Civic" <i>na</i>	\$	29.10	\$		29.10	
7	1	Emblem "i-VTEC 1.6" <i>na</i>	\$	49.50	\$		49.50	
8	1	Spare tyre Box <i>Per X</i>	\$	316.00	\$		316.00	

Total for SP \$ 788.30 ~~130.00~~

Sub-Total for Parts : \$ 3,853.18 ~~130.00~~

S/No	Qty	Items	Unit Price	Amount
------	-----	-------	------------	--------

1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		1,200.00 <i>600</i>
2		To putty and spray paint on all accident damage parts and other accident affected areas		1,000.00 <i>600</i>
3		To remove and refit reverse sensor		120.00 <i>50</i>
4		To check wiring system to facilitate repair and refit the same		120.00 <i>20</i>
5		Apply rust proofing on the adjacent panels		50.00 <i>30</i>
6		To remove and refit exhaust pipe		<i>na</i> 80.00 <i>X</i>

TOTAL AMOUNT : 2,570.00

OVERALL COST : \$ 6,423.18 ~~2,700.00~~

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

475K

Vehicle Details

Vehicle No.:

SJJ4446A

Vehicle to be Exported:

No

Intended Deregistration Date:

02 May 2020

Vehicle Make:

HONDA

Vehicle Model:

CIVIC 1.6L VTi AUTO

Primary Colour:

White

Manufacturing Year:

2008

Engine No.:

R16A13006983

Chassis No.:

JHMFD46208S202451

Maximum Power Output:

92.0 kW (123 bhp)

Open Market Value:

\$18,890.00

Original Registration Date:

12 Sep 2008

First Registration Date:

12 Sep 2008

Transfer Count:

1

Original ARF Paid:

\$18,890.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

11 Sep 2023

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$16,170.00

COE Rebate Amount:

\$10,860.00

Total Rebate Amount:

\$10,860.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 May 2020

OK