



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2100036

INV Date 05/01/2021

Reference CC4/LPC20005530/Kka3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 1646A

Insured Veh. YN 8705C

Claim No. 19/20/20/VC05/023329

Policy No. Z19VC05003137

Accident Date 30/04/2020

Inspection Date 05/05/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20005530/Kka3q2	Date: 05/01/2021
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8705C	Veh. Inspected	GBF 1646A	
Policy No.	Z19VC05003137	Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023329	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	04/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VM20095949	Colour	METALLIC GREY	
Odometer	98698 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	GOODRIDE	9 mm	
L/H Front Tyre	175/70 R14	GOODRIDE	9 mm	
R/H Rear Tyre	175/70 R14	GOODRIDE	9 mm	
L/H Rear Tyre	175/70 R14	GOODRIDE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/04/2020	Inspection Date	05/05/2020	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 1646A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH FENDER (N)	BENT	1,551.30	1,551.30
1	RH TAILLAMP (N)	CRACKED	236.50	236.50
1	REAR BUMPER (N)	BENT	481.50	481.50
1	REAR BUMPER RETAINER (N)	DISTORTED	38.30	38.30
1	RH SLIDE DOOR RAIL (CTR) RUBBER TYPE (N)	DENTED / CUT	184.80	184.80
1	RH SLIDE DOOR GLASS (N)	CRACKED	1,240.00	1,240.00
	LESS 10% DISCOUNT		-373.24	-373.24
			3,359.16	3,359.16
<u>SPECIAL NETT ITEMS</u>				
2	GLASS SEALANT @\$40.00 (SN)	NECESSARY	80.00	40.00
1	V-COOL (SN)	NECESSARY	180.00	100.00
			260.00	140.00
<u>LABOUR</u>				
	TO CHECK WIRING AND LIGHTING.		60.00	20.00
	TO REMOVE AND REFIT REVERSE SENSOR.		40.00	40.00
	TO REMOVE AND REFIT REAR RH FENDER GLASS.		100.00	60.00
	TO REMOVE AND REFIT RH SLIDE DOOR GLASS.		100.00	50.00
	TO REMOVE AND REFIT INNER TRIMS AND UPHOLSTERY.		100.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.		800.00	600.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		600.00	480.00
			1,800.00	1,310.00
GRAND TOTAL			5,419.16	4,809.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,850.00
---	--	--	-----------------

Report Ref No. CC4/LPC20005530/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 1646A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 1646A

RE-INSPECTION

