

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kenny Lim

Date: 05 May 2020

Preliminary Advice

Vehicle No	: SCY8642C	Accident Date	: 30/04/2020
Make	: TOYOTA COROLLA ALTIS	Policy No.	: Z20VP05025924
Assignment Date	: 04/05/2020	Excess	: S\$0.00
Date of Inspection	: 04/05/2020	Est. Duration of Repair	: 7.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages interior parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,250.50
Revised Amount	:S\$	1,557.75
Check Items (Estimated)	:S\$	430.00
Total	:S\$	1,987.75
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	47,907.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,093.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :