

Date: 09.04.2020
 Vehicle No: SLQ3172K
 Model: TOYOTA AQUA 1.5 HYBRID
 Chassis: NHP106598524-2017
 Reg.Year: 2017

Third Party Insurer: AIG
 Third Party Veh No: SML1343L
 Date of Accident: 06.04.2020

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	<i>Rec</i>	\$608.31
2	REAR BUMPER SIDE BRACKET LH	1	<i>Dir</i>	\$68.20
3	REAR BUMPER REINFORCEMENT	1		\$478.40
4	REAR BUMPER CLIPS	8	\$5.50	<i>Re</i> \$44.00
5	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,198.91
LESS 25%				-\$299.73
PARTS TOTAL				\$899.18

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

2001
\$300.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

501
\$80.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL & ETC.

2201
\$500.00

LABOUR TOTAL \$880.00

TingAn TOTAL \$1,779.18

Not Authorised
Resurvey B4 paint
2 days

P/P = 1,010.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Head office

6 Yung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

