

Third Party Insurer: SOMPO
Third Party Veh No: GBF5486T
Date of Accident: 01.05.2020

10855.39 NOT Withheld
 @ ~~10482.25~~ Pending B4 pain

6 days

[illegible]

Rea home in guide LH cracks 142.60

Acknowledged by Repairer
Signature:
Date:

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 04.05.2020
Vehicle No: SLU666B
Model: MERCEDES BENZ E250
Chassis: WDD2130452A298626-2017
Reg. Year: 2017

Third Party Insurer: SOMPO
Third Party Veh No: GBF5486T
Date of Accident: 01.05.2020

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,200.00	600
LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER & ETC.	\$90.00	60
LABOUR CHARGES TO REMOVE & REPLACE REAR SAFETY BELT LH & RH, REAR SEAT ASSY, FRONT SAFETY BELT RH ASSY & ETC.	\$250.00	200
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT LID, REAR END PANEL, REAR BUMPER & ETC.	\$900.00	600
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	22 X
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	20
TO RESET AIR BAG CONTROL UNIT & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	✓
TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	\$180.00	150
LABOUR TOTAL	\$3,020.00	

gAn

TOTAL \$16,368.98

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

