

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6 #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2000102**
Date: 04 May 2020
Veh Reg No: **SFE6238U**
Make Model: NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Chasis No: SJNFEAJ11U1571203
Reg. Date: 22-06-2016
Your Ref No: SME151S

Claim Type: Third Party
Accident Date: 03/05/2020
TP Veh Reg No: SME151S

Estimate Repair Cost to Vehicle No :SFE6238U

Quantity	Description	List Price SS	Amount SS
Net Price			
1	1 PC FRT FENDER RH <i>replaced</i>	685.10 ✓	
2	1 PC FRT FENDER COWLING RH <i>replaced</i>	122.40 ✓	
3	1 PC FRT WHEEL ARCH GARNISH RH <i>cut</i>	483.00 ✓	
4	1 PC HEADLAMP RH <i>cracked</i>	612.00 ✓	
5	1 PC HEADLAMP RETAINER RH <i>new</i>	54.70 ✗	
6	1 PC BONNET <i>Reps</i>	961.40 ✗	
7	1 PC FRT BUMPER <i>replaced</i>	674.60 ✓	
8	1 PC FRT BUMPER REINFORCEMENT <i>3 new</i>	675.40 ✗	
9	1 PC FRT BUMPER SPONGE	89.40 ✗	
10	1 PC FRT BUMPER RETAINER RH <i>new</i>	36.70 ✓	
11	1 PC FRT WIPER TANK <i>new</i>	201.90 ✗	
12	1 PC FRT GRILLE <i>cracked</i>	493.30 ✓	
13	1 PC FRT GRILLE TOP LAMP RH <i>cracked</i>	327.00 ✓	
14	1 SET FRT PARKING SENSOR <i>2nd</i>	220.00 ✓	
15	1 PC FRT FOG LAMP COVER RH <i>replaced</i>	74.70 ✓	
16	1 PC FRT SPORTS RIM RH <i>cut</i>	1,231.90 <i>(500/sw)</i>	
		6,890.50	
Less 10%		689.05	6,201.45
Special Net			
17	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	50.00 <i>30</i>	
18	1 SET FRT WHEEL ARCH GARNISH CLIPS RH <i>new</i>	40.00 <i>20</i>	
19	1 SET FRT BUMPER CLIPS <i>new</i>	60.00 <i>30</i>	
20	1 SET FRT GRILLE CLIPS <i>new</i>	40.00 ✗	
		190.00	190.00
Labour			
21	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 <i>500</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000102
Date: 04 May 2020
Veh Reg No: SFE6238U
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
SDR
Chasis No: SJNFEAJ11U1571203
Reg. Date: 22/06/2016
Your Ref No: SME151S

Claim Type: Third Party
Accident Date: 03/05/2020
TP Veh Reg No: SME151S

Estimate Repair Cost to Vehicle No :SFE6238U

Quantity	Description	List Price	Amount
		SS	SS
22	1 TO SPRAY PAINTING	1,000.00	600
23	1 TO SPRAY UNDERSEAL	80.00	+
24	1 TO REPLACE FRT PARKING SENSOR	80.00	50
25	1 TO CHECK WIRING	50.00	30
26	1 TO CHECK WHEEL ALIGNMENT	120.00	80
		2,330.00	2,330.00
	Total		SS 8,721.45
	Add GST @ 7%		610.50
	Total Amount Payable		SS 9,331.95

TOTAL: SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED THIRTY ONE AND CENTS NINETY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE

Adrian Lj
H/S 04/05/20
05 Apr
total: 5195.92
H/S 4150