

COMFORTDELGRO ENGINEERING

Our Job Ref No 305397453

Date : 06.05.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHB3389D CCPL

01.05.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLG6624G

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

Final Lumpsum Repair cost

\$750/-

but subjected to
insurance approval.

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature :

Name :

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Tokio Marine

Date: 04.05.2020

Time: 12:49:14

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305397453
 REGN NO : SHB3389D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 07.08.2014
 DATE/TIME IN : 04.05.2020 10:00
 ACCIDENT DATE : 01.05.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	reflon
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nec
0003	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40	xnn
0004	04-01-0103-0907-G	I40VC BRKT ASSY-RR BUMPER	1 L	35.60	20.00	28.48	xnn
0005	03-01-0103-0121-G	I40VC GUARD ASSY-RR WHEEL	1 L	169.30	20.00	135.44	xnn
0006	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00	135.70	xnn
0007	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	0.20	50.00	nec

SUB-TOTAL : 1,434.42 \$952.40

JOB NATURE

0000 L	PANEL BEATING
0001 23-502	SPRAYPAINT ON AFFECTED AREA
0002 L	REMOVE/REFIX REVERSE SENSOR
0003 L	MERIMEN CHARGE

350.00 \$280

250.00 \$200

120.00 \$60

11.00

2165.42

Labour: \$551

Total: \$1503.40

50%
Lumpsum: \$750/=

(2) repair days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)

4/5/2020 1300

Parasuram@lkkauto.com

88622778

aft repair photo

(L/S)

(2) repair days