



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 3149L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	CHARGE AIR COOLER; COOL.UNIT XR	BENT	1,148.00	1,148.00
1	EXTERIOR EE O/S CORNER; F/GLASS	CRACKED	732.00	732.00
2	DOOR RETAINER SLAM LOCK	BENT	29.00	29.00
1	DOOR MICROSWITCH-ADJUSTABLE; RR ENG DR	NOT NECESSARY	78.00	-
1	SEALED LEVER LATCH; OS/NS;RR SIDE DR	NECESSARY 1PC ONLY	68.00	34.00
1	HYDRAULIC OIL COOLER; COOLING UNIT	SERVICEABLE	309.00	-
2	SS 4X4 X3MM 5 JOINT BUTT HINGE	BENT	113.00	113.00
1	O/S LOWER ENG ACCESS DOOR; SHEETMETAL	BENT	1,626.00	1,626.00
1	RADIATOR FLYSCREEN; O/S LOWER ENG ACCESS	TO REPAIR SEE LABOUR	386.00	-
6	SIKA 552 WHITE 660ML SAUSAGE	NECESSARY	84.00	84.00
2	CLAMP; CHARGE AIR-COOLER TO ENG	NECESSARY	32.00	32.00
1	HOSE 1040MM; HYD.EQPT	NOT NECESSARY	61.00	-
1	SEALING RING; CHARGE-AIR COOLERS	NECESSARY	4.00	4.00
1	HYDRAULIC HOSE; HYD.MOTOR; FAN DR	NOT NECESSARY	151.00	-
1	REAR REVERSE LAMP; B9TL EU5	SERVICEABLE	81.00	-
1	REFLEX REFLECTOR	SERVICEABLE	1.00	-
1	LED STOP / TAIL LIGHT 24V; 30541713 1 LED	CRACKED	65.00	65.00
1	LED INDICATOR LIGHT 24V; 30541714 1 LED	CRACKED	65.00	65.00
1	PROFILE.ENG MODULE	NOT NECESSARY	821.00	-
			5,854.00	3,932.00
<b><u>LABOUR</u></b>				
ASSESSEMENT OF BUS (CONTRACTOR REPAIRS).			188.00	150.00
CONTRACTOR'S REPAIR CHARGES. INCLUSIVE OF THE REPAIR OF RADIATOR FLYSCREEN; O/S LOWER ENG ACCESS.			5,328.60	1,800.00
			5,516.60	1,950.00
<b>GRAND TOTAL</b>			<b>11,370.60</b>	<b>5,882.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,882.00</b>

Report Ref No. CS1/LPC20005554/R1vf3s2



Report Ref No. CS1/LPC20005554/R1vf3s2

A handwritten signature in black ink, appearing to read 'MRB'.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to read 'A.L.P.'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.