

General View of SBS3149L




Damaged of rear flyscreen ,O/S lower engine access

Rear side latch bent, 1 sets (LH/RH)



Damaged of rear flyscreen ,O/S lower engine access



Damaged of door microswitch – adjustable RR engine DR



Damaged of door microswitch – adjustable RR engine DR, (close-up)



Damaged of Hydraulic oil cooler, cooling unit, located behind/after the radiator assembly.



Damaged of Hydraulic oil cooler, cooling unit, (Close-up), located behind/after the radiator assembly.



Rear reverse lamp assembly, dislodge/damaged



Rear reverse lamp assembly, dislodge/damaged



Rear reverse lamp assembly, dislodge/damaged