

ASS. REC. BY:

REF:

AIG / 2000 5559/KK

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

MBM

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

1-B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 37164

Yr Regn:

02, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS

NOR

c.c.

1198

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

1277

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

E12

028839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

3/5/20

D.O.I.

6/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/5

84837-12

3/6

86045-46 Car from

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$


☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

MBM WHEELPOWER PTE LTD



Your Ref: SMR3852P

Our Ref: SMS3716U

To: AIG

CC

Fax

Date: 5/5/2020
 From: Danny
 Fax: 64525333
 Contact: 93288668
 Make / Model: NISSAN NOTE 1.2X
 Chassis No.: E12628839
 Engine No.: HR12046561K
 Year of Make: 2019
 Accident Date: 3 May 2020

*Not Authorized
 Return B&P
 5 days
 @ 6045.46*

ESTIMATE FOR VEHICLE NO.: SMS3716U

DESCRIPTION

FRONT BUMPER → 534.90
 FRONT BUMPER RH SIDE RETAINER
 FRONT BUMPER LH SIDE RETAINER
 FRONT BUMPER LOWER RH COVER
 FRONT BUMPER LOWER LH COVER
 FRONT BUMPER SPONGE 152.10
 FRONT REINFORCEMENT
 RADIATOR GRILLE ASSY → 376.30
 RADIATOR GRILLE TOP COVER 1 276.50
 FRONT LH FENDER
 FRONT LH FENDER INNER SHIELD
 FRONT RH FENDER
 FRONT RH FENDER INNER SHIELD
 HEAD LAMP RH → 1416.30
 HEAD LAMP LH 5 1416.30
 BUMPER CLIPS
 FENDER INNER SHIELD CLIPS
 DISTANCE SENSOR @\$200 EACH

QTY

1
1
1
1
1
1
1
1
1
1
1
1
1
1
1
1
10
10
2

\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$

List Price

B 939.00 ✓
 D11 55.00 ✓
 D11 55.00 ✓
 S 57.00 X
 D11 57.00 ✓
 CM 236.00 2
 R 406.00 X
 D11 475.00 ✓
 Mgmt 324.00 ✓
 R 604.00 X
 D11 140.00 ✓
 R 604.00 X
 D11 140.00 ✓
 Mgmt 1,836.00 ✓
 1,836.00 ✓
 M 60.00 ✓
 M 60.00 ✓
 S 400.00 X

Total: \$ 8,284.00
 LESS 20% \$102 (1,656.80)
 Parts Total: \$ 6,627.20

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT

1

\$

nn 80.00 X
(Bill) 120.00 ✓
50/-

TOWING

1

\$

LABOURTO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$

600/-
1,200.00

TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT

\$

nn 100.00 X

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$

nn 250.00 X

TO APPLY ANTI RUST COATING

\$

nn 150.00 X

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$

nn 150.00 X

TO REMOVE & REPLACE BUMPER SENSORS

\$

60.00 ✓

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$

20/- 80.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$

800/- 1,500.00*Car-o-line**\$350/- — \$250/-*

Total: \$ 10,317.20

7% GST: \$ 722.20

Grand Total: \$ 11,039.40**Mbm wheelpower pte ltd**

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY


t 62628888 f 64525333

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD

Your Ref: SMR3852P

Our Ref: SMS3716U



To: AIG

CC

Fax

Date: 11/5/2020
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: NISSAN NOTE 1.2X
Chassis No.: E12628839
Engine No.: HR12046561K
Year of Make: 2019
Accident Date: 3 May 2020

SUPPLEMENTARY FOR VEHICLE NO. : SMS3716U

LABOUR

TO CONDUCT RE-ALIGNMENT OF FRONT CHASSIS ON (CAR-O-LINER) ✓

250.00

QTY

List Price

\$

350.00

Total: \$

350.00

7% GST: \$

24.50

Grand Total: \$

374.50

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62628888 f 64525333

Company Registration Number : 200204110W



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1235448

Date: 04/05/20

M/S: MBM WHEELPOWER

Vehicle No: SMS 3716 U Model : NISSAN NOTE

From: 8C BOON KENG RD Time Start: 11.30AM

To: AUTOCITY #06-09 Time End: 11.50AM

Remarks: _____

☐ Change Tyres /Jump Start

☒ Accident

☐ Use Car Carrier

☒ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☐ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 120

GST S\$ 8.40

TOTAL S\$ 128.40

Received By

bizSAFE₃

Important Note:

Ym9301H HUAT

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.