



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Stew (LKK)

WHL Phil
5/5/20, 11.30 am

Estimation

3 days

L/S, Rj AL spj

Date:

30/4/2020

Vehicle:

SML1452E

Make / Model:

HONDA SHUTTLE

Chassis:

GP7-2009063

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER / TN	1	\$ 1,250.00	\$ 1,250.00
2	FRONT BUMPER SIDE RETAINER RH / BR	1	\$ 28.70	\$ 28.70
3	RH FRONT HEADLAMP / CUT	1	\$ 950.00	\$ 950.00
4	RH FRONT FENDER / OO	1	\$ 511.90	\$ 511.90
5	RH FRONT FENDER INNER COWLING / ERADAF	1	\$ 145.00	\$ 145.00
6	RH FRONT WHHEL CAP / CUT	1	\$ 195.00	\$ 195.00
7	RH FRONT DOOR X R	1	\$ 757.20	\$ 757.20
8	RH FRONT WIND MIRROR X NAI	1	\$ 527.50	\$ 527.50
9	RH FRONT FRONT WIND MIRROR COVER X NAI	1	\$ 67.30	\$ 67.30
10	RH ROCKER PANEL GARNISH X NN	1	\$ 593.20	\$ 593.20
11	RH FRONT FENDER EMBLEM HYBRID / NPC	1	\$ 90.10	\$ 90.10
				\$ 5,115.90
			Less 20%	\$ 1,023.18
			Total	\$ 4,092.72
S/Nett items:				
1	FRONT BUMPER CLIPS / NPC	1 SET	\$ 80.00	\$ 80.00
2	RH FRONT FENDER INNER COWLING CLIPS / NPC	1 SET	\$ 80.00	\$ 80.00
3	RH ROCKER PANEL GARNISH CLIPS X NAI	1 SET	\$ 80.00	\$ 80.00
4	RH ROCKER PANEL GARNISH SEAL X NAI	1	\$ 60.00	\$ 60.00
5	MISCELLANEOUS X NAI	1	\$ 100.00	\$ 100.00
				\$ 400.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND TRANSFER ALL RH FRONT DOOR FITTING	1	\$ 150.00	\$ 150.00
3	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 150.00	\$ 150.00
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 2,080.00
Parts Replacement Amount				\$ 4,492.72
Total Amount for Labour				\$ 2,080.00
Total Amount				\$ 6,572.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2274-96

AI- 50

L- 1160

3484-96

L/S- 2787-96

= 2800

1050 ✓

✓

✓

460 ✓

✓

150 ✓

X

X

X

X

60 ✓

2843-70

-29%

2274-96 ✓

30 ✓

20 ✓

X

X

X

X

50 ✓

30

X

X

30

600

500

1160 ✓