



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2100843

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/02/2021
Reference CC3/CTI20005571/Fps3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 1447C
Insured Veh. GBD 8979D
Claim No. SNM20D201874
Policy No. DMCVSN1527811904
Accident Date 05/05/2020
Inspection Date 05/05/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20005571/Fps3q2	
			Date: 08/02/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 8979D	Veh. Inspected	SHC 1447C	
Policy No.	DMCVSN1527811904	Coverage (\$)	0.00	
Claim No.	SNM20D201874	Excess (\$)	0.00	
Assign From		Assign Date	05/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ (G2)	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVKU164570	Colour	BLUE	
Odometer	112129 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DURATURN	8 mm	
L/H Front Tyre	195/65 R15	DURATURN	8 mm	
R/H Rear Tyre	195/65 R15	DURATURN	9 mm	
L/H Rear Tyre	195/65 R15	DURATURN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/05/2020	Inspection Date	05/05/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1447C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	459.40	459.40
2	REAR BUMPER SIDE BRACKET RH/LH @\$55.80	NOT NECESSARY	111.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	294.80	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER LOWER MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER CENTRE MOULDING	CRACKED	451.25	451.25
1	BOOT LID	BUCKLED	2,480.40	2,480.40
1	BOOT LID GLASS UPPER	NECESSARY	543.30	543.30
1	BOOT LID GLASS LOWER	NECESSARY	384.90	384.90
1	BOOT LAMP LH	CRACKED	794.40	794.40
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	BOOT LID HYBRID PLATE	NECESSARY	24.30	24.30
1	BOOTLID H EMBLEM	NOT NECESSARY	28.00	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	31.90	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
	LESS 20% DISCOUNT		-1,277.81	-1,038.25
			5,111.24	4,153.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE/W HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR REVERSE SENSOR (SN)	DAMAGED	180.00	180.00
1	COMFORT LOGO STICKER (SN)	NECESSARY	30.00	30.00
1	TEL NUMBER STICKER (SN)	NECESSARY	30.00	30.00
			290.00	240.00
<u>LABOUR</u>				
	PANEL BEATING.		760.00	640.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	CHECK WIRING.		60.00	30.00
	TUFF KOTE.		60.00	30.00

Report Ref No. CC3/CTI20005571/Fps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR.		60.00	60.00
			1,440.00	1,160.00
GRAND TOTAL			6,841.24	5,553.00
RECOMMENDED COST OF REPAIRS				5,553.00

Report Ref No. CC3/CTI20005571/Fps3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 1447C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 1447C

RE-INSPECTION

