

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1447C

05/05/20

MAKE :

CHIANG/CHINA

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER <i>cra</i>		\$459.40
1	REAR BUMPER SIDE BRACKET RH /LH <i>xnn</i>		\$55.80
10	REAR BUMPER CLIPS <i>nec</i>		\$22.00
1	REAR BUMPER REINFORCEMENT ?		\$294.80
1	REAR BUMPER REINFORCEMENT BRACKET ?		\$138.10
1	REAR BUMPER LOWER MOULDING <i>xnn</i>		\$155.00
1	REAR BUMPER FOG LAMP <i>xnn</i>		\$201.50
1	REAR BUMPER CENTRE MOULDING <i>cra</i>		\$451.25
1	BOOT LID <i>Buc</i>		\$2,480.40
1	BOOT LID GLASS UPPER <i>nec</i>		\$543.30
1	BOOT LID GLASS LOWER <i>nec</i>		\$384.90
1	BOOT LAMP LH <i>cra</i>		\$794.40
1	EMBLEM- IONIQ <i>nec</i>		\$31.30
1	BOOT LID HYBRID PLATE <i>nec</i>		\$24.30
1	BOOTLID H EMBLEM <i>nec</i>		\$28.00
1	REAR BUMPER REFLECTOR RH <i>xnn</i>		\$31.90
1	REAR BUMPER TOW COVER <i>xnn</i>		\$98.80
SUB TOTAL			\$6,389.05
20.00%			\$1,277.81
DISCOUNTED TOTAL			\$5,111.24
1	REAR NUMBER PLATE/W HOLDER <i>xnn</i>		\$50.00
1	REAR REVERSE SENSOR <i>dm</i>		\$180.00
1	COMFORT LOGO STICKER <i>nec</i>		\$30.00
1	TEL NUMBER STICKER <i>nec</i>		\$30.00
			\$290.00
Labour Charge			
Panel Beating			
Spray Painting Charge			
Check wiring			
Tuff Kote			
Remove/refix Reverse sensor			
TOTAL LABOUR			\$1,440.00
ESTIMATE TOTAL			\$6,841.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)
5/5/2020 1545
Pansuran@lkkauto.com
886 22778
BEF paint photo
P/R
3 repair days

\$640
\$400
\$30
\$30

\$760.00
\$500.00
\$60.00
\$60.00
\$60.00

CHINA

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braemar Road Singapore 579701

Mainline + 65 6381 6280 Facsimile + 65 6381 1700

Workshops

59 Loyang Drive Singapore 508965

383 Sin Ming Drive Singapore 575117

45 Pandan Road Singapore 609286

120 Little Road Singapore 120149

14 Serangoon Road Singapore 556114

1 Sungei Kadut Road Singapore 670001

561 Mathur Industrial Park A Singapore 670001

A member of COMFORTDELGRO

Date/Time: 05.05.2020 11:29

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305397763

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045

STOMER NO. 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755 (O)

(R)
(P)

COUNT CARD NO.

REGN NO:

SHC1447C

MILEAGE

MAKE:

HYUNDAI

FUEL

E 1/2 F

MODEL

IONIQ(G2)

DATE/TIME IN

05.05.2020 09:55

YR OF MANU.

02.07.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164570

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 05.05.2020

NATURE: 3P 05.05.2020

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

:

1.2

e No.:

SHC1447C

CHIANG

Vehicle No

SHC1447C

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard