

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON S 079914

ALLIED WORLD ASSURANCE COMPANY LTD

Date: 27-05-2020

CS3/AWA20005574/Evf3e2



Page No.:1 of 1

			Code: AWA			
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	YP 3409E	Veh. Inspected	FBB 8129B		
	Policy No.	AVCPSB0082391903	Coverage (\$)	0.00		
	Claim No.	NSV2000159/HLF	Excess (\$)	0.00		
	Assign From	HEW LEE FONG	Assign Date	06/05/2020		
2. Vehicle Particulars & Condition						
	Make & Model	BAJAJ PULSAR	c.c	179		
	Engine No.	HIDDEN	Year of Reg.	2007		
	Chassis No.	MD2DHDJZZNCH61419	Colour	RED		
	Odometer	99999 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	FAIR				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	60/70-17	DUNLOP	5 mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre	70/80-17	DUNLOP	5 mm		
	L/H Rear Tyre			mm		
4. Description of Damages						
	THE VEHICLE SUS					

5.	General Information						
	Accident Date	24/04/2020	Inspect Date / Time	06/05/2020 ( 01:53 PM )			
	Survey held at	EQUATOR BROTHERHOOD					
		25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800					
5a.	5a. Remarks						

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. **Estimate Days of Repair** 

ESTIMATED NORMAL PERIOD FOR REPAIR:

4 Working Days

Report Ref No. CS3/AWA20005574/Evf3e2

Inspected By

6

**CHEN TSUE YEE** 

K.K.LAU CPT(RET)

**Automotive Assessor** 

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.