

Ryder Auto Pte Ltd
2 Kaki Bukit Ave 2, #02-19 Kaki Bukit
Autohub
417921

Insurer Reference: SMP7011J
Repairer Reference: 031572
Date calculated: 05/05/2020 3:39 PM

Full Report
Registration: SFA1604A
Printed: 05/05/2020 3:39 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	San Choon	Currency:	SGD
Claim Reference:	SMP7011J	Date of Incident:	04/05/20
Estimated Repair Time:	6	Hire Car Start:	04/05/20
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: AUDI
Model: A6 ALLROAD/RS6(4G)
Sub Model: BASE MODEL
Model Sheet Number: 00 72 01
Registration: SFA1604A
VIN number: WAUZZZ4G2DN043978
Odometer:

Tanfuk 97495749
wp
5/5/20 @ 420pm
Resurvey before paint
03 days
tanfuk@lkhauto.com

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:


Damage Areas

All
Underbody

☐ **Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour

Time Base 10 WU/h

Price = 80.00 SGD/h

Code	Description	WU	Price SGD
63 69 19 00	R + R REAR BUMPER COVER	9.0	72.00
63 69 55 51	RENEW REAR BUMPER COVER (REMOVED)	2.0	16.00
	INCLUDES: R + R REAR LOWER SPOILER		
NO NUMBER	R + R LEFT REAR OUTER BUMPER BRACKET	1.0	8.00
NO NUMBER	R + R RIGHT REAR OUTER BUMPER BRACKET	1.0	8.00
63 50 19 50	R + R REAR IMPACT SUPPORT (BUMPER REMOVED)	3.0	24.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		1.60	16.0
Total of Labour			128.00

Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - MF	WU	Price SGD
63 69 61 52	REAR BUMPER NEW PART PAINTING S1	14.0	112.00
51 01 71 63)	PAINTING PREPARATION WORK STAGE S2 METAL, PLASTIC NEW PARTS S1 AND S2 (PART/S REMOVED)	11.0	88.00
51 01 71 93	PREPARATION FOR PAINT (PLASTIC PARTS) (ASSEMBLY OPERATION)	2.0	16.00
Total Paint		Hrs 2.70	WU 27.0
			Price SGD 216.00

Material Cost - Paint
Total

Price SGD
to check ? **1,000.00**

Spare Parts

			prices as at 2020-05-04
Code	Description	Part Number	Price SGD
2619	L/R OUT BUMPER GUIDE	4G9 807 453 F	x 40.65
2621	L/SCREW	N 909 059 03	acc ✓ 20.00
2620	R/R OUT BUMPER GUIDE	4G9 807 454 F	x 40.65
2622	R/SCREW	N 909 059 03	nei ✓ 18.00
2581	REAR BUMPER	4G9 807 067 F	de ✓ 1,921.40
		GRU	
2609	REAR BUMPER GUARD	4G9 807 835	at ✓ 255.95
2640	RR BUMP IMPACT SUPP	4G9 807 309 C	bt ✓ 754.00
2631	RR CTR BUMPER GUIDE	4G9 807 458 A	x 90.65
Savings			0.00
Subtotal			3,141.30
Addition(+ 20.00%)			628.26
Total			3,769.56

Extras

Code	Description	Price SGD
1000	3m sticker 3m sticker	300 500.00*
1001	Eco-disposal fee Bumper	30.00*
	Total Extras	530.00

Final Calculation

	SGD	SGD
Parts	3,141.30	
Addition(+20.00%)	628.26	
Total Parts		3,769.56
Labour Time Base 10 WU/h		
Total 16.0 WU X 80.00 SGD/h	128.00	
Total of Labour		128.00
Total Of Extras		530.00
Paint Work Time Base 10 WU/h		
Labour Cost 27.0 WU X 80.00 SGD/h	216.00	
Material Cost	1,000.00	
Total Paint Including Material		1,216.00
Repair Cost Excludes GST		5,643.56
GST (+7.0%)		395.05
Repair Cost Included GST		6,038.61

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.