



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                                                | Owner Name & Vehicle Info |                                          |
|-----------------------------------------------------------------------------------------------------------------------|---------------------------|------------------------------------------|
| PATRICIA OWYANG LAI FONG MRS<br>PATRICIA HENG<br>991 BUKIT TIMAH ROAD<br>#06-08<br>SINGAPORE 589630<br><br>Contact No | Cust No/Name              | LCV09767/PATRICIA OWYANG LAI FONG MRS PA |
|                                                                                                                       | Reg No/Reg Date           | SJZ1929J / 15/05/201                     |
|                                                                                                                       | Date In/Mileage           | / 0                                      |
|                                                                                                                       | Chassis No                | KNAF3416MK5041620                        |
|                                                                                                                       | Engine No                 | G4FGJH721879                             |
|                                                                                                                       | Make/Model                | KIA/CERATO 1.6 A EX G333                 |
|                                                                                                                       | Colour/Trim               | SWP SNOW WHITE PEAR/ WK SATURN BLACK     |

| Account No                                                                                   | Terms  | Date/Time Printed | CSE | Operator          | WIP No |            |       |              |
|----------------------------------------------------------------------------------------------|--------|-------------------|-----|-------------------|--------|------------|-------|--------------|
| LCV09767                                                                                     | CRDVCH | 09/03/2020/ 16:33 | QUK | 282 / Kevin Leong | 13022  |            |       |              |
| Description of Goods / Services                                                              |        |                   |     |                   | Qty    | Unit Price | Disc% | Amount       |
| E PNT88000<br>TO REPLACE REAR BUMPER & AFFECTED AREA<br>TO REPAIR ON END PANEL               |        |                   |     |                   |        |            |       | 1100 1650.00 |
| E PNT98000<br>PAINT WORK ON REAR BUMPER & END PANEL                                          |        |                   |     |                   |        |            |       | 840 1260.00  |
| E PNT88000<br>TO REMOVE & INSTALL REAR PARKING ASSIST                                        |        |                   |     |                   |        |            |       | 100 150.00   |
| M SUNDRY<br>TO APPLY SEALANT ON AFFECTED AREA                                                |        |                   |     |                   |        |            |       | 80.00        |
| E PNT88000<br>TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR                |        |                   |     |                   |        |            |       | 100 180.00   |
| A 54900099<br>CHECK ELECTRICAL SYSTEM                                                        |        |                   |     |                   |        |            |       | 60 80.00     |
| A 10028901<br>TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST |        |                   |     |                   |        |            |       | 200.00       |
| M SUNDRY<br>TO APPLY ZERTONA COATING (invoice sales agreement)                               |        |                   |     |                   |        |            |       | 100.00       |
| M SUNDRY<br>SUNDRIES                                                                         |        |                   |     |                   |        |            |       | 20 50.00     |
| M PANEL ASSY-BACK Xsu                                                                        |        |                   |     |                   | 1.00   | 324.00     | 00.00 | 324.00       |
| M COVER-RR BUMPER UNDER, LH Xsu                                                              |        |                   |     |                   | 1.00   | 33.00      | 00.00 | 33.00        |
| M COVER-RR BUMPER LWR cm (1pc)                                                               |        |                   |     |                   | 5.00   | 241.00     | 00.00 | 241 1205.00  |
| M COVER-RR BUMPER de                                                                         |        |                   |     |                   | 1.00   | 651.00     | 00.00 | 651.00       |
| M COVER-RR BUMPER FOG LAMP, LH ?                                                             |        |                   |     |                   | 1.00   | 19.00      | 00.00 | 19.00        |
| M COVER-RR BUMPER FOG LAMP, RH ?                                                             |        |                   |     |                   | 1.00   | 19.00      | 00.00 | 19.00        |
| M LAMP ASSY-SIDE T/SIGNAL, LH ?                                                              |        |                   |     |                   | 1.00   | 181.00     | 00.00 | 181.00       |
| M LAMP ASSY-SIDE T/SIGNAL, RH ?                                                              |        |                   |     |                   | 1.00   | 181.00     | 00.00 | 181.00       |
| M EXTN WIRING ASSY-BWS ?                                                                     |        |                   |     |                   | 1.00   | 207.00     | 00.00 | 207.00       |
| M BRACKET-RR BEAM UPR MTG, LH ?                                                              |        |                   |     |                   | 1.00   | 9.00       | 00.00 | 9.00         |
| M BRACKET-RR BEAM UPR MTG, RH ?                                                              |        |                   |     |                   | 1.00   | 9.00       | 00.00 | 9.00         |
| M BRACKET-RR BEAM LWR, CTR ?                                                                 |        |                   |     |                   | 1.00   | 6.00       | 00.00 | 6.00         |
| M BRACKET-RR BEAM LWR MTG ?                                                                  |        |                   |     |                   | 1.00   | 6.00       | 00.00 | 6.00         |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                              | Owner Name & Vehicle Info                                                                                                                                                                                                                                                 |
|-----------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| PATRICIA OWYANG LAI FONG MRS<br>PATRICIA HENG<br>991 BUKIT TIMAH ROAD<br>#06-08<br>SINGAPORE 589630 | Cust No/Name LCV09767/PATRICIA OWYANG LAI FONG MRS PA<br>Reg No/Reg Date SJZ1929J / 15/05/201<br>Date In/Mileage / 0<br>Chassis No KNAF3416MK5041620<br>Engine No G4FGJH721879<br>Make/Model KIA/CERATO 1.6 A EX G333<br>Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK |
| Contact No                                                                                          |                                                                                                                                                                                                                                                                           |

| Account No                       | Terms  | Date/Time Printed | CSE        | Operator          | WIP No |
|----------------------------------|--------|-------------------|------------|-------------------|--------|
| LCV09767                         | CRDVCH | 09/03/2020/ 16:33 | QUK        | 282 / Kevin Leong | 13022  |
| Description of Goods / Services  |        | Qty               | Unit Price | Disc%             | Amount |
| M ANTENNA ASSY-SMARTKEY          |        | 1.00              | 46.00      | 00.00             | 46.00  |
| M BEAM-RR BUMPER                 |        | 1.00              | 318.00     | 00.00             | 318.00 |
| M STAY-RR BUMPER LH              |        | 1.00              | 65.00      | 00.00             | 65.00  |
| M STAY-RR BUMPER RH              |        | 1.00              | 65.00      | 00.00             | 65.00  |
| M BRACKET ASSY-RR BPR SIDE UPR,L |        | 1.00              | 25.00      | 00.00             | 25.00  |
| M BRACKET-ASSY RR BPR SIDE UPR,R |        | 1.00              | 31.00      | 00.00             | 31.00  |
| CLIP (X10) rec / (Supl)          |        |                   |            |                   | 20.00  |

## Estimate

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

REMARKS:

Resue - 4 days  
Repair before paint

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

7170

7% GST on 7150.00 500.50

Total Payable 7,650.50