

ASS. REC. BY:

REF:

TH / 20005601 / Kea392

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7793T Yr Regn: 08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

m.p. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

120370

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD KB 3F4 7030 8 2712

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

2/5/20

D.O.I.

6/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2613.58 Summary

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

CLOSE: 14/8/2020

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7793T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

06 MAY 2020

PART

- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 REAR FENDER LINER
- 1 DUCT ASSY, QUARTER VENT, LH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 REAR BUMPER
- 1 REAR BUMPER UNDER COVER (BLACK)
- 1 REAR BUMPER SIDE RETAINER LH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 REAR BUMPER SIDE LH
- 1 PANEL SUB-ASSY, REAR DOOR, LH
- 1 HANDLE ASSY, REAR DOOR OUTSIDE, LH
- 1 TAPE, BLACK OUT, NO.1 LH
- 1 TAPE, BLACK OUT, NO.2 LH
- 1 TAPE, BLACK OUT, NO.3 LH
- 1 REAR WHEEL RIM
- 1 REAR WHEEL RIM COVER

AAD2005-002

*Not Authorized**Resurvey B4 paint**2613.38***SHB 7793T**

JTDKB3FU703082712

TOYOTA

PRIUS

2.5.2020

16/8/2019

LIST

\$	R	594.80	X
\$	B	871.50	✓
\$	Ln	139.80	X
\$	Ln	67.00	X
\$	Ln	88.50	X
\$	Bul/Br	442.60	✓
\$	Ln	576.30	} X
\$	Ln	116.50	
\$	Ln	502.00	
\$	Ln	451.80	
\$	Ln	123.70	
\$	R	1,294.90	
\$	Ln	97.40	
\$	na	21.90	
\$	na	34.90	
\$	na	15.40	
\$	Ln	1,879.40	
\$	Ln	211.50	

TOTAL	\$	7,529.90
25%	\$	1,882.48
	\$	5,647.43

Special Nett

- 1 REAR DOOR STICKER '6555-3333'
- 1SET REAR BUMPER CLIP

\$	100.00	<i>Go sm</i>
\$	na 68.00	✓

Trans-cab Auto Services Pte Ltd

AAD2005-002

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7793T

2	REAR WINDSCREEN SEALANT	\$	nn	140.00	}	X
1	WINDSCREEN MOULDING	\$	nn	180.00		
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	120.00		
1SET	REAR FENDER LINER CLIP	\$	nn	38.00		
1	REAR TYRE 195/65/15	\$	nn	350.00		
1SET	REAR BUMPER RETAINER CLIP	\$	nn	38.00		
1SET	ROCKER PANEL MOULDING CLIP	\$	nn	35.00		
1SET	TAILLAMP LOWER CLIP	\$	nn	30.00		
1SET	TAILLAMP UPPER CLIP	\$	nn	30.00	}	X
1	REAR BUMPER PROTECTOR	\$	nn	120.00		
TOTAL		\$		1,249.00		

TOTAL PARTS \$ 6,896.43**LABOUR**

To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	}	100%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00		
To check steering geometry and computer wheel alignment	\$	na 220.00	X	
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	↪ 170.00	X	
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	↪ 170.00	X	
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,500.00	600%	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7793T**AAD2005-002**

To reinstall rear bumper parking sensor.	\$	170.00	50%
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,500.00	660%
To Check Electrical Lighting Concerned.	\$	170.00	20%
To Rust-Proofing Of The Affected Areas.	\$	170.00	30%
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	15,340.00	
Over All Total	\$	22,236.43	

(PART-BY-PART) Repair Days~~20 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHB7793T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 May 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C43488
Chassis No.:	JTDKB3FU703082712
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	16 Aug 2019
First Registration Date:	16 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Aug 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,463.00
COE Rebate Amount:	\$18,770.00
Total Rebate Amount:	\$29,455.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 May 2020

OK