

**Trans-cab Auto Services Pte Ltd**  
 No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHB 7793T**

AAD2005-002

*Not Authorized*

*Resurvey B&Paint*

*\$2613.58*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

06 MAY 2020

**SHB 7793T**  
 JTDKB3FU703082712  
 TOYOTA  
 PRIUS  
 2.5.2020

16/8/2019

- |   | <b>PART</b>                          |
|---|--------------------------------------|
| 1 | MOULDING ASSY, BODY ROCKER PANEL, LH |
| 1 | PANEL SUB-ASSY, QUARTER, LH          |
| 1 | REAR FENDER LINER                    |
| 1 | DUCT ASSY, QUARTER VENT, LH          |
| 1 | SEAL, REAR BUMPER SIDE, LH           |
| 1 | REAR BUMPER                          |
| 1 | REAR BUMPER UNDER COVER (BLACK)      |
| 1 | REAR BUMPER SIDE RETAINER LH         |
| 1 | TAILLAMP LOWER LH                    |
| 1 | TAILLAMP UPPER LH                    |
| 1 | REAR BUMPER SIDE LH                  |
| 1 | PANEL SUB-ASSY, REAR DOOR, LH        |
| 1 | HANDLE ASSY, REAR DOOR OUTSIDE, LH   |
| 1 | TAPE, BLACK OUT, NO.1 LH             |
| 1 | TAPE, BLACK OUT, NO.2 LH             |
| 1 | TAPE, BLACK OUT, NO.3 LH             |
| 1 | REAR WHEEL RIM                       |
| 1 | REAR WHEEL RIM COVER                 |

|    | <b>LIST</b> |          |
|----|-------------|----------|
| \$ | R           | 594.80 X |
| \$ | B           | 871.50 ✓ |
| \$ | Ln          | 139.80 X |
| \$ | Ln          | 67.00 X  |
| \$ | Ln          | 88.50 X  |
| \$ | Bu/du       | 442.60 ✓ |
| \$ | Ln          | 576.30   |
| \$ | Ln          | 116.50   |
| \$ | Ln          | 502.00   |
| \$ | Ln          | 451.80   |
| \$ | Ln          | 123.70   |
| \$ | R           | 1,294.90 |
| \$ | Ln          | 97.40    |
| \$ | na          | 21.90    |
| \$ | na          | 34.90    |
| \$ | na          | 15.40    |
| \$ | Ln          | 1,879.40 |
| \$ | Ln          | 211.50   |

|              |    |                 |
|--------------|----|-----------------|
| <b>TOTAL</b> | \$ | <b>7,529.90</b> |
| <b>25%</b>   | \$ | <b>1,882.48</b> |
|              | \$ | <b>5,647.43</b> |

**Special Nett**

- 1 REAR DOOR STICKER '6555-3333'  
 1SET REAR BUMPER CLIP

|    |        |             |
|----|--------|-------------|
| \$ | 100.00 | <i>60sm</i> |
| \$ | na     | 68.00 ✓     |

AAD2005-002

**Trans-cab Auto Services Pte Ltd**  
 No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
 SHB 7793T

- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 REAR WINDSCREEN INNER SPONGE SEAL
- 1SET REAR FENDER LINER CLIP
- 1 REAR TYRE 195/65/15
- 1SET REAR BUMPER RETAINER CLIP
- 1SET ROCKER PANEL MOULDING CLIP
- 1SET TAILLAMP LOWER CLIP
- 1SET TAILLAMP UPPER CLIP
- 1 REAR BUMPER PROTECTOR

|              |           |                 |   |      |
|--------------|-----------|-----------------|---|------|
| \$           | na        | 140.00          | } | X    |
| \$           | na        | 180.00          |   |      |
| \$           | na        | 120.00          |   |      |
| \$           | na        | 38.00           |   |      |
| \$           | na        | 350.00          |   |      |
| \$           | na        | 38.00           |   |      |
| \$           | na        | 35.00           |   |      |
| \$           | na        | 30.00           |   |      |
| \$           | na        | 30.00           | } | 4050 |
| \$           | na        | 120.00          |   |      |
| <b>TOTAL</b> | <b>\$</b> | <b>1,249.00</b> |   |      |

**TOTAL PARTS \$ 6,896.43**

**LABOUR**

To transfer of Rear Fender fittings, attachments and perform water seepage test.

\$ 170.00

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ 170.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,500.00 6000

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7793T

AAD2005-002

|                                                                                 |           |                  |      |
|---------------------------------------------------------------------------------|-----------|------------------|------|
| To reinstall rear bumper parking sensor.                                        | \$        | 170.00           | 50%  |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$        | nn 380.00        | X    |
| Putty And Spray Painting Of The Affected Portion.                               | \$        | 6,500.00         | 660% |
| To Check Electrical Lighting Concerned.                                         | \$        | 170.00           | 20%  |
| To Rust-Proofing Of The Affected Areas.                                         | \$        | 170.00           | 30%  |
| To transfer of tire, rim and on wheel balancing.                                | \$        | nn 170.00        | X    |
| To transfer of door fittings, attachment and perform water seepage test.        | \$        | nn 170.00        | X    |
| <b>TOTAL</b>                                                                    | <b>\$</b> | <b>15,340.00</b> |      |
| <b>Over All Total</b>                                                           | <b>\$</b> | <b>22,236.43</b> |      |

(PART-BY-PART) Repair Days ~~20 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: