

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHB 7793T

AAD2005-002

Not Authorized

Resurvey B&Paint

\$2613.58

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

06 MAY 2020

SHB 7793T
 JTDKB3FU703082712
 TOYOTA
 PRIUS
 2.5.2020

16/8/2019

- | | PART |
|---|--------------------------------------|
| 1 | MOULDING ASSY, BODY ROCKER PANEL, LH |
| 1 | PANEL SUB-ASSY, QUARTER, LH |
| 1 | REAR FENDER LINER |
| 1 | DUCT ASSY, QUARTER VENT, LH |
| 1 | SEAL, REAR BUMPER SIDE, LH |
| 1 | REAR BUMPER |
| 1 | REAR BUMPER UNDER COVER (BLACK) |
| 1 | REAR BUMPER SIDE RETAINER LH |
| 1 | TAILLAMP LOWER LH |
| 1 | TAILLAMP UPPER LH |
| 1 | REAR BUMPER SIDE LH |
| 1 | PANEL SUB-ASSY, REAR DOOR, LH |
| 1 | HANDLE ASSY, REAR DOOR OUTSIDE, LH |
| 1 | TAPE, BLACK OUT, NO.1 LH |
| 1 | TAPE, BLACK OUT, NO.2 LH |
| 1 | TAPE, BLACK OUT, NO.3 LH |
| 1 | REAR WHEEL RIM |
| 1 | REAR WHEEL RIM COVER |

	LIST	
\$	R	594.80 X
\$	B	871.50 ✓
\$	Ln	139.80 X
\$	Ln	67.00 X
\$	Ln	88.50 X
\$	Bu/du	442.60 ✓
\$	Ln	576.30
\$	Ln	116.50
\$	Ln	502.00
\$	Ln	451.80
\$	Ln	123.70
\$	R	1,294.90
\$	Ln	97.40
\$	na	21.90
\$	na	34.90
\$	na	15.40
\$	Ln	1,879.40
\$	Ln	211.50

TOTAL	\$	7,529.90
25%	\$	1,882.48
	\$	5,647.43

Special Nett

- 1 REAR DOOR STICKER '6555-3333'
 1SET REAR BUMPER CLIP

\$	100.00	<i>60sm</i>
\$	na	68.00 ✓

AAD2005-002

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
 SHB 7793T

- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 REAR WINDSCREEN INNER SPONGE SEAL
- 1SET REAR FENDER LINER CLIP
- 1 REAR TYRE 195/65/15
- 1SET REAR BUMPER RETAINER CLIP
- 1SET ROCKER PANEL MOULDING CLIP
- 1SET TAILLAMP LOWER CLIP
- 1SET TAILLAMP UPPER CLIP
- 1 REAR BUMPER PROTECTOR

\$	na	140.00	}	X
\$	na	180.00		
\$	na	120.00		
\$	na	38.00		
\$	na	350.00		
\$	na	38.00		
\$	na	35.00		
\$	na	30.00		
\$	na	30.00	}	40.00
\$	na	120.00		
TOTAL	\$	1,249.00		

TOTAL PARTS \$ 6,896.43

LABOUR

To transfer of Rear Fender fittings, attachments and perform water seepage test.

\$ 170.00

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ 170.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$

6,500.00 600.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7793T

AAD2005-002

To reinstall rear bumper parking sensor.	\$	170.00	50%
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,500.00	660%
To Check Electrical Lighting Concerned.	\$	170.00	20%
To Rust-Proofing Of The Affected Areas.	\$	170.00	30%
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	15,340.00	
Over All Total	\$	22,236.43	

(PART-BY-PART) Repair Days ~~20 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: