

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: dynamicautowork@gmail.com

DATE : 11.05.20

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKD8196P**
 MODEL : **BMW 523i**
 DATE OF ACCIDENT : 06.05.20
 TIME OF ACCIDENT : 10.35HRS

Yiao Chen

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEAD REST <i>new</i>	2	\$ 809.00	\$ 1,618.00
2	HEAD REST SENSOR <i>Activated</i>	2	\$ 550.00	\$ 1,100.00
3	AIR BAG CONTROL UNIT <i>new</i>	1	\$ 2,960.00	\$ 2,960.00
4	BOOT LID <i>Bulged</i>	1	\$ 1,370.00	\$ 1,370.00
5	BOOT LID LAMP RH <i>new cut</i>	1	\$ 395.00	\$ 395.00
6	BOOT LID TOP LOCK <i>new</i>	1	\$ 150.00	\$ 150.00
7	BOOT LID WEATHERSTRIP <i>new</i>	1	\$ 215.00	\$ 215.00
8	BOOT LID LOGO <i>2 new</i>	1	\$ 69.00	\$ 69.00
9	BOOT LID EMBLEM '523i'	1	\$ 65.00	\$ 65.00
10	BOOT LID LOWER LOCK <i>new</i>	1	\$ 76.45	\$ 76.45
11	BOOT LID HINGE <i>new</i>	2	\$ 210.00	\$ 420.00
12	REAR BUMPER <i>Delc'd</i>	1	\$ 1,396.50	\$ 1,396.50
13	REAR BUMPER TOWING COVER <i>Delc'd</i>	1	\$ 22.65	\$ 22.65
14	REAR BUMPER TOP BEAM <i>crack'd</i>	1	\$ 395.00	\$ 395.00
15	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 679.80	\$ 679.80
16	REAR BUMPER REINFORCEMENT COVER GARNISH <i>crack'd</i>	1	\$ 45.65	\$ 45.65
17	REAR BUMPER SDE BRACKET (PLASTIC) <i>crack'd</i>	2	\$ 140.75	\$ 281.50
18	REAR BUMPER BOTTOM CENTER GARNISH <i>crack'd</i>	1	\$ 256.10	\$ 256.10
19	REAR BUMPER REFLECTOR RH <i>crack'd</i>	1	\$ 121.70	\$ 121.70
20	REAR BUMPER SENSOR <i>2 pieces bend</i>	2	\$ 225.45	\$ 450.90
21	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 62.05	\$ 248.20
22	REAR BUMPER LOWER GARNISH (SIDE) RH <i>crack'd</i>	1	\$ 95.00	\$ 95.00
23	TAIL LAMP RH <i>cut</i>	1	\$ 481.20	\$ 481.20
24	REAR FENDER DRAIN GARNISH RH <i>new</i>	1	\$ 123.25	\$ 123.25
25	REAR FENDER COWLING RH <i>new</i>	1	\$ 429.65	\$ 429.65
26	REAR END PANEL <i>Repr</i>	1	\$ 740.00	\$ 740.00
27	REAR END PANEL TOP GARNISH <i>new new</i>	1	\$ 195.00	\$ 195.00

7349.10

6614.19

TOTAL PRICE \$ 14,400.55
 LESS 5% \$ 720.03
SUB TOTAL PRICE \$ 13,680.52

12.4.10

TO : BUDGET DIRECT MOTOR CLAIMS DEPTS
VEHICLE NO : SKD8196P
MODEL : BMW 523I
DATE OF ACCIDENT : 06.05.20
TIME OF ACCIDENT : 10:35HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SPECIAL TYPE) <i>Neu</i>	1	\$ 180.00	\$ 180.00
2	REAR BUMPER CLIP (SET) <i>Neu</i>	1	\$ 120.00	\$ 120.00
3	REAR BUMPER REINFORCEMENT COVER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00
4	BOOT LID SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00
5	BOOT LID INSULATOTR CLIP (SET) <i>Neu</i>	1	\$ 120.00	\$ 120.00
6	TAIL LAMP CLIP (SET) <i>Neu</i>	1	\$ 40.00	\$ 40.00
7	REAR FENDER INNER TRIM CLIPS (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00
8	REAR FENDER DRAIN GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00
9	REAR FENDER COWLING CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00
10	REAR END PANEL INSULATION SEAL <i>2</i>	1	\$ 150.00	\$ 150.00
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00
12	REAR FLOOR STORAGE GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00

TOTAL \$ 1,040.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	500
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	500
3	TUFF COAT	\$ 250.00	x
4	WIRING CHECK	\$ 380.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	x.
6	RESET HEAD REST	\$ 800.00	380
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60
8	REAR CHASSIS ALIGNMENT	\$ 250.00	x
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	x

TOTAL \$ 6,270.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,720.52
TOTAL LABOUR COST : \$ 6,270.00
TOTAL REPAIR COST : \$ 20,990.52

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKD8196P**
MODEL : **BMW 523I**
DATE OF ACCIDENT : 06.05.20
TIME OF ACCIDENT : 10:35HRS

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY (HP: 9856 4815)

Admin L
x/s 12/05/20

06 Days .

Total 8144.19

x/s 6.5K

6.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: