

15/5/2010

INS. CASE OWNER:

CC 3/AXA1601

0557, K263K2

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

6/6/10

Date / Time:

6/6/10

Registered in Merimen:

9/6/10

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKR 2918P

Name of Insured:

ONG TIEN SUKH

Insured Tel No.:

HP:

97948375

Excess Sec II :\$

D.O.A:

6/6/10

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

C0387013

Policy No.:

GAD 45266

Make / Model:

TOYOTA

Place of Accident:

CIRCUIT RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
Cab

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
11/7/10 May	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$S	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	50 (Agreed / Assessed) BOLA S/N No.: N/L
Repair Cost:	\$S	
Loss of Rental (LOR):	\$S	(days)
Loss of Use (LOU):	\$S	(\$ x days)
Loss of Income (LOI):	\$S	(\$ x days)
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	\$S	
Medical:	\$S	
Disbursement:	\$S	(e.g. Tow/ Independent)
Legal Cost	\$S	
Total:	\$S	Global Sum \$S:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S	Name 1:
Payee 2: (Strike if N.A.)	\$S	Name 2:
Payee 3: (Strike if N.A.)	\$S	Name 3:

ASS. REC. BY:

Kenneth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 01 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 314050713 Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AIMake: Renault Longitude C.C. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 449310 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABLISAUC 276164Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: Rovert 215/60R16R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 8/6/16Survey held at ✓

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 8/6/16

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

RT M/S door mirror cracked

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/6 GIA & EH not ready8/6 @ 1521-97 Late7 File pass to Catherine2/12 @ 1521-97 Confirm Invoice C1 + 1/2 X 128.40 + 75)To wait IP driver acceptance.Red 18 14469.90, 90.5)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA16010557/Kzb3	
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 08-06-2016	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKR 2918P	Veh. Inspected	SHC 5071B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/06/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/06/2016	Inspection Date	06/06/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111*
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
 SHC 5071B - AXA

CANDY

*Not Notified
 1-B1
 1521.87
 Resumy Bypain*

Vehicle No.: **SHC 5071B - CANDY**
 Chassis No.: VF1ABL15AUC276164
 Vehicle Make: RENAULT
 Vehicle Model: LATITUDE
 Date of Accident : 06.06.2016
 Third Party Insurer : **AXA**

PART			LIST		
1	1	FENDER PANEL FRT LH	\$	R 602.95	X
2	1	FENDER WHEELARCH FRT LH (Linner)	\$	Sm 107.33	X
3	1	DOOR FRT LH	\$	R 2,188.20	X
4	1	DOOR HANDLE OUTER FRT LH	\$	Sm 198.55	X
5	1	DOOR HANDLE COVER FRT LH	\$	Sm 10.17	X
6	1	DOOR MIRROR LH	\$	CR 1,141.08	✓
7	1	DOOR SEAL FRT LH	\$	Sm 52.83	X
8	1	ROCKER PANEL OUTER LH	\$	R 759.61	X
9	1	DOOR REAR LH	\$	R 2,188.20	X
10	1	DOOR HANDLE OUTER REAR LH	\$	Sm 97.31	X
11	1	FENDER PANEL REAR LH	\$	R 2,537.80	X
12	1	FENDER WHEELARCH REAR LH (Linner)	\$	Sm 418.06	X

TOTAL	\$	10,302.08
10%	\$	1,030.21
	\$	9,271.87

Special Nett

1	1	DOOR STICKER "Trans-cab"	\$	na 80.00	60sm
2	1	DOOR STICKER "Classic"	\$	na 30.00	15sm
3	1	DOOR STICKER "6555-3333"	\$	na 80.00	X

TOTAL	\$	190.00
TOTAL PARTS	\$	9,461.87

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	1200
To Check Electrical Lighting Concerned.	\$	170.00	200
Putty and spray painting of the affected portion.	\$	3,000.00	2800

To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 X
To rust-proofing of the affected areas.	\$	170.00 X

TOTAL	\$	6,530.00
Over All Total	\$	15,991.87

(PARTS BY PARTS) Repair Days

10 Days

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before final spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Pre-claim" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5071B

Vehicle to be
Exported: YesIntended De-
registration Date: 06 Jun 2016

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: M9R8839C000718

Chassis No.: VF1ABL15AUC276164

Maximum Power
Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration
Date: 02 Dec 2013First Registration
Date: 02 Dec 2013

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility
Expiry Date: 01 Dec 2021PARF Rebate
Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 01 Dec 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$62,740.00

COE Rebate
Amount: \$43,024.00**Total Rebate
Amount: \$52,397.00**

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Jun 2016

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jun 2016		09 Jun 2016 11:19 Edit Adj Rpt	S\$1,521.97 Edit Estimates	S\$1,521.97 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ONG, TIEN SUNG, ID: S0054701H, Tel: +6597948375, Email: ls.lee@pas.sg		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5071B	Date of Loss:	06/06/2016 10:00 - :59
Claim Type:	TP / C0387013	Policy/Cover Note No.:	GA045266 (Comprehensive)
Vehicle Reg. No. (Insured):	SKR2918P	Policy No. (Claimant):	VPX/P1680520
		Excess:	S\$0.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/06/2016]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AXA_SG (12/07/2016): Re: Direct Settlement - Accident Involving SKR2918P (OI : AXA - C0387013) and SH...
- AXA_SG (30/06/2016): TP settlement - C0387013/GA045266
- AXA_SG (09/06/2016): WP / New TP Assignment - C0387013/GA045266

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC5071B (C0387013)
[SKR2918P]
TP
TRANS-CAB SERVICES PTE LTD
Jun 6 2016 10:00AM
[ONG, TIEN SUNG]
Trans-cab Auto Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer ▼	
Assessment Reports				1 per page ▼	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	30/06/16 16:10	Accident Statement From: SC - Reg. No: SKR2918P, Claimant: ONG TIEN SUNG		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/06/16 12:02	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/07/16 08:46	LKKPhotos		Load PDF	
Documentation				1 per page ▼	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	09/06/16 09:13	email_abs		Load PDF	
2	09/06/16 09:13	SHC5071B TP GIA REPORT_ABS		Load PDF	
3	09/06/16 09:13	TP ESTIMATE_ABS		Load PDF	
4	30/06/16 16:09	co-agent		Load TIF	
5	30/06/16 16:09	INSD GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16010557/KZB3K2

Date: 21/06/2017

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA045266
Claimant Vehicle No :	SHC5071B	Insured Vehicle No :	SKR2918P
Date of Loss:	06/06/2016	Nature of Claim:	TP
		Claim No:	C0387013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5071B	Engine No:	M9R8839C000718
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276164
Reg. Date:	02/12/2013 (Man. Year: 2013)	Odometer:	449310 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Rovelo 9 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Rovelo 9 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,461.88	1,101.97	8,359.91	88.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,530.00	420.00	6,110.00	93.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,991.88	1,521.97	14,469.91	90.48
+ GST 7.00/7.00% (S\$)	1,119.43	106.54	1,012.89	90.48
Nett Amount (S\$)	17,111.31	1,628.51	15,482.80	90.48

INSPECTION

Date of Assignment:	09/06/2016	
Date Inspected:	06/06/2016 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: ZAY YER LYNN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2017)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5071B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT LH (CONSISTENT)	Repair	602.95 FL	*- FL
2	1		*FENDER WHEELARCH FRT LH (LINNER) (CONSISTENT)	Serviceable	107.33 FL	*- FL
3	1		*DOOR FRT LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
4	1		*DOOR HANDLE OUTER FRT LH (CONSISTENT)	Serviceable	198.55 FL	*- FL
5	1		*DOOR HANDLE COVER FRT LH (CONSISTENT)	Serviceable	10.17 FL	*- FL
6	1		*DOOR MIRROR LH (CONSISTENT)	Cracked	1,141.08 FL	*1,141.08 FL
7	1		*DOOR SEAL FRT LH (CONSISTENT)	Serviceable	52.83 FL	*- FL
8	1		*ROCKER PANEL OUTER LH (CONSISTENT)	Repair	759.61 FL	*- FL
9	1		*DOOR REAR LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
10	1		*DOOR HANDLE OUTER REAR LH (CONSISTENT)	Serviceable	97.31 FL	*- FL
11	1		*FENDER PANEL REAR LH (CONSISTENT)	Repair	2,537.80 FL	*- FL
12	1		*FENDER WHEELARCH REAR LH (LINNER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
13	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Necessary	80.00 FS	*60.00 FS
14	1		*DOOR STICKER CLASSIC (CONSISTENT)	Necessary	30.00 FS	*15.00 FS
15	1		*DOOR STICKER 6555-3333 (CONSISTENT)	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,492.09	1,216.08
- List Item Discount on L Items 10.00/10.00% (S\$)	1,030.21	114.11
Total Parts (S\$)	9,461.88	1,101.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	120.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	280.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
5	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
Gross Labour Cost (S\$)			6,530.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >