

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHC 5956Z - AXA

1607-081

ROEL

Not Assembled
1-B.1
82482.94
Resurvey B4 point

Vehicle No.: **SHC 5956Z - ROEL**
 Chassis No.: **VF1ABL15AUC281473**
 Vehicle Make: **RENAULT**
 Vehicle Model: **LATITUDE**
 Date of Accident : **24.05.2016**
 Third Party Insurer : **AXA**

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Re/inst</i> 852.66 ✓
2	1	BUMPER LOWER REAR	\$	<i>Re/inst</i> 591.41 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 87.29 X
4	1	BUMEPR BRACKET SIDE RH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59 ✓
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 34.61 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 33.55 ✓
7	1	BUMEPR BRACKET SIDE LH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59 ✓
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 34.61 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 33.55 X
10	1	BUMPER BEAM REAR	\$	<i>Ry</i> 598.09 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 173.81 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 173.81 X
13	1	BOOT REAR	\$	<i>R</i> 2,209.75
14	1	BOOT FINISHER (Moulding)	\$	<i>Sm</i> 429.90
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 248.50
16	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 379.50
17	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 379.50
18	1	BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 173.35
19	1	BOOT BADGE	\$	<i>Sm</i> 173.35
20	1	BOOT STRUT (SPRING)	\$	<i>Sm</i> 212.36
21	1	BOOT HINGE LH	\$	<i>R</i> 282.96
22	1	BOOT HINGE RH	\$	<i>R</i> 282.96
23	1	BOOT INNER TRIM	\$	<i>Sm</i> 586.45
24	1	BOOT SWITCH	\$	<i>Sm</i> 107.78
25	1	BOOT LOCK	\$	<i>R</i> 155.90
26	1	BOOT LOCK CATCH	\$	<i>R</i> 72.00
27	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 170.63
28	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80
29	1	FENDER WHEELARCH REAR LH (Linner)	\$	<i>Sm</i> 418.06
30	1	FENDER INNER TRIM LH	\$	<i>Sm</i> 430.42
31	1	FENDER PANEL REAR RH	\$	<i>R</i> 2,537.80
32	1	FENDER WHEELARCH REAR RH (Linner)	\$	<i>Sm</i> 418.06
33	1	FENDER INNER TRIM RH	\$	<i>Sm</i> 430.42
34	1	TAILLAMP RH	\$	<i>Sm</i> 425.04

X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5956Z - AXA**ROEL**

35	1	TAILLAMP PANEL RH	\$	<i>R</i> 759.00 ✓
36	1	TAILLAMP LH	\$	<i>Sm</i> 425.04 ✓
37	1	TAILLAMP PANEL LH	\$	<i>R</i> 759.00 ✓
38	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 1,684.52 ✓
39	1	SPARE WHEEL PANEL TRIM	\$	<i>Sm</i> 470.93 ✓
40	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,132.13 ✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 311.20 ✓
42	1	EXHAUST REAR	\$	<i>R</i> 5,760.00 ✓
43	1	EXHAUST CAP REAR	\$	<i>R</i> 177.30 ✓

TOTAL	\$	<u>27,364.17</u>
10%	\$	<u>2,736.42</u>
	\$	<u>24,627.75</u>

Special Nett

1	1SET	PARKING AID	\$	<i>Sm</i> 600.00 X
2	1SET	REAR BUMPER CLIP	\$	<i>R</i> 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>R</i> 33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>R</i> 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>R</i> 20.00 ✓
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>R</i> 10.00 ✓
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>R</i> 20.00 ✓
8	1SET	BUMPER LOWER REAR CLIP	\$	<i>R</i> 66.00 ✓
9	1	EXHAUST MOUNTING REAR	\$	<i>Sm</i> 17.82
10	1SET	BOOT FINISHER CLIP	\$	<i>R</i> 24.20
11	1	BOOT STICKER "Trans-cab"	\$	<i>R</i> 30.00
12	1	BOOT STICKER "6555-3333"	\$	<i>R</i> 30.00
13	1	BOOT INNER TRIM CLIP	\$	<i>R</i> 45.00
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>R</i> 35.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>R</i> 35.00
16	1	FENDER INNER TRIM CLIP LH	\$	<i>R</i> 28.00
17	1	FENDER INNER TRIM CLIP LH	\$	<i>R</i> 28.00
18	1	TAILLAMP CLIP RH	\$	<i>R</i> 5.00
19	1	TAILLAMP CLIP LH	\$	<i>R</i> 5.00
20	2	REAR WINDSCREEN SELANT	\$	<i>R</i> 80.00
21	1	WINDSCREEN MOULDING	\$	<i>Sm</i> 100.00
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>R</i> 100.00
23	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sm</i> 385.00
24	1	SPARE TYRE	\$	<i>Sm</i> 330.00

TOTAL	\$	<u>2,103.02</u>
TOTAL PARTS	\$	<u>26,730.77</u>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5956Z - AXA**ROEL**

Putty And Spray Painting Of The Affected Portion.	\$	5,400.00 ²²⁰¹
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,600.00 ²⁰⁰¹
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 ⁶⁰¹
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X

TOTAL \$ 12,790.00**Over All Total \$ 39,520.77****(PARTS BY PARTS)****Repair Days****15Days***1 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: