

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5956Z - AXA*Not Authored***ROEL***1-B.1**2482.94**Resurvey BY paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5956Z - ROEL

VF1ABL15AUC281473

RENAULT

LATITUDE

24.05.2016

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Re/ump</i> 852.66	✓
2	1	BUMPER LOWER REAR	\$	<i>Re/ump</i> 591.41	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 87.29	X
4	1	BUMEPR BRACKET SIDE RH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 34.61	X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 33.55	✓
7	1	BUMEPR BRACKET SIDE LH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 34.61	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 33.55	X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 598.09	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 173.81	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 173.81	X
13	1	BOOT REAR	\$	<i>R</i> 2,209.75	} X
14	1	BOOT FINISHER (Moulding)	\$	<i>Sm</i> 429.90	
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 248.50	
16	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 379.50	
17	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 379.50	
18	1	BOOT BADGE 'RENAULT'	\$	<i>na</i> 173.35	
19	1	BOOT BADGE	\$	<i>na</i> 173.35	
20	1	BOOT STRUT (SPRING)	\$	<i>Sm</i> 212.36	
21	1	BOOT HINGE LH	\$	<i>R</i> 282.96	
22	1	BOOT HINGE RH	\$	<i>R</i> 282.96	
23	1	BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
24	1	BOOT SWITCH	\$	<i>Sm</i> 107.78	
25	1	BOOT LOCK	\$	<i>R</i> 155.90	
26	1	BOOT LOCK CATCH	\$	<i>R</i> 72.00	
27	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 170.63	
28	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80	} X
29	1	FENDER WHEELARCH REAR LH (Linner)	\$	<i>Sm</i> 418.06	
30	1	FENDER INNER TRIM LH	\$	<i>Sm</i> 430.42	
31	1	FENDER PANEL REAR RH	\$	<i>R</i> 2,537.80	
32	1	FENDER WHEELARCH REAR RH (Linner)	\$	<i>Sm</i> 418.06	
33	1	FENDER INNER TRIM RH	\$	<i>Sm</i> 430.42	
34	1	TAILLAMP RH	\$	<i>Sm</i> 425.04	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5956Z - AXA**ROEL**

35	1	TAILLAMP PANEL RH	\$	<i>R</i> 759.00 <i>X</i>
36	1	TAILLAMP LH	\$	<i>Sm</i> 425.04 <i>X</i>
37	1	TAILLAMP PANEL LH	\$	<i>R</i> 759.00 <i>X</i>
38	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 1,684.52 <i>X</i>
39	1	SPARE WHEEL PANEL TRIM	\$	<i>Sm</i> 470.93 <i>X</i>
40	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,132.13 <i>X</i>
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 311.20 <i>X</i>
42	1	EXHAUST REAR	\$	<i>R</i> 5,760.00 <i>X</i>
43	1	EXHAUST CAP REAR	\$	<i>R</i> 177.30 <i>X</i>

TOTAL	\$	27,364.17
10%	\$	2,736.42
	\$	24,627.75

Specical Nett

1	1SET	PARKING AID	\$	<i>Sm</i> 600.00 <i>X</i>
2	1SET	REAR BUMPER CLIP	\$	<i>R</i> 66.00 <i>✓</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>R</i> 33.00 <i>✓</i>
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>R</i> 10.00 <i>X</i>
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>R</i> 20.00 <i>✓</i>
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>R</i> 10.00 <i>X</i>
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>R</i> 20.00 <i>X</i>
8	1SET	BUMPER LOWER REAR CLIP	\$	<i>R</i> 66.00 <i>✓</i>
9	1	EXHAUST MOUNTING REAR	\$	<i>Sm</i> 17.82
10	1SET	BOOT FINISHER CLIP	\$	<i>R</i> 24.20
11	1	BOOT STICKER "Trans-cab"	\$	<i>R</i> 30.00
12	1	BOOT STICKER "6555-3333"	\$	<i>R</i> 30.00
13	1	BOOT INNER TRIM CLIP	\$	<i>R</i> 45.00
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>R</i> 35.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>R</i> 35.00
16	1	FENDER INNER TRIM CLIP LH	\$	<i>R</i> 28.00
17	1	FENDER INNER TRIM CLIP LH	\$	<i>R</i> 28.00
18	1	TAILLAMP CLIP RH	\$	<i>R</i> 5.00
19	1	TAILLAMP CLIP LH	\$	<i>R</i> 5.00
20	2	REAR WINDSCREEN SELANT	\$	<i>R</i> 80.00
21	1	WINDSCREEN MOULDING	\$	<i>Sm</i> 100.00
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>R</i> 100.00
23	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sm</i> 385.00
24	1	SPARE TYRE	\$	<i>Sm</i> 330.00

TOTAL	\$	2,103.02
TOTAL PARTS	\$	26,730.77

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5956Z - AXA**ROEL**

Putty And Spray Painting Of The Affected Portion.	\$	2200 5,400.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,600.00 2000
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X

TOTAL	\$	12,790.00
Over All Total	\$	39,520.77

(PARTS BY PARTS)**Repair Days****15Days**

1 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: