

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7806R - AIG

Done - 4/4/16

Candy*Not Authorized
V/Lump &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7806R - Candy

KL1LA69RJBB107393

CHEVROLET

EPICA 2.0

31.03.16

AIG**PART****LIST**

1	1	Front Bumper	\$	<i>Bu</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	295.25 ?
3	1	Front Bumper Lower Absorber	\$	180.00 ?
4	1	Front Bumper Lower Grille	\$	<i>Bu</i> 78.00 X
5	1	Front Bumper Retainer RH	\$	<i>Bu</i> 102.00 X
6	1	Front Bumper Retainer LH	\$	<i>Bu</i> 102.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Front Headlamp RH	\$	<i>mtgnt</i> 816.00 ✓
9	1	Front Headlamp LH	\$	816.00 ?
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Bu</i> 32.40 X
11	1	Front Bumper Fog Lamp Outer Cover RH	\$	<i>Bu</i> 32.40 X
12	1	Front Support Panel Assy (Panel A-Frt)	\$	<i>Bu</i> 1,222.32 ✓
13	1	Bonnet (Panel A-Hood)	\$	<i>Bu</i> 1,250.00 ✓
14	1	Centre 'CHEVROLET' Logo Badge	\$	<i>mt</i> 144.30 ✓
15	1	Bonnet Moulding	\$	<i>mt</i> 257.00 ✓
16	1	Bonnet Insulator	\$	<i>Bu</i> 84.63 X
17	1	Bonnet hinge RH	\$	<i>R</i> 36.00 X
18	1	Bonnet hinge LH	\$	<i>R</i> 36.00 X
19	1	Bonnet cable	\$	<i>Bu</i> 150.00 X
20	1	Bonnet lock	\$	<i>R</i> 200.00 X
21	2	HORN LH	\$	<i>Bu</i> 320.00 X
22	1	Radiator Grille (Grille A-Rad)	\$	<i>CRA</i> 367.00 ✓
23	1	Radiator Assembly (Radiator A)	\$	<i>1 hour CRA</i> 618.00 ✓
24	1	Aircon Condenser (Condenser A)	\$	600.00 ?
25	1	Air Cleaner Assembly	\$	<i>Bu</i> 112.00 X
26	1	Front Centre Member	\$	<i>Bu</i> 265.63 X
27	1	Air Intercooler	\$	652.00 ?
28	1	Fan Blade (Small)	\$	536.00 ?
29	1	Fan Blade (Big)	\$	634.00 ?
30	1	Front Fender LH	\$	<i>R</i> 837.60 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7806R - AIG**Candy**

31	1	Front Fender RH	\$	R	837.60	X
32	1	Front Fender Liner LH	\$	Sn	47.00	X
33	1	Front Fender Liner RH	\$	Sn	47.00	X
34	1	Rear Bumper	\$	Bt	1,202.00	—
35	1	Rear Bumper Beam	\$	Bt	239.94	—
36	1	Rear Bumper Centre Absorber	\$	CM	260.00	—
37	1	Rear Bumper Side Retainer RH	\$	CR	68.76	—
38	1	Rear Bumper Side Retainer LH	\$	CM	68.76	—
39	1	Rear Bumper Reflectors RH	\$	Br	119.74	—
40	1	Rear Bumper Reflectors LH	\$	Br	119.74	—
41	1	Rear Bumper stay RH	\$	CM	35.00	—
42	1	Rear Bumper stay LH	\$	CM	35.00	—
43	1	Rear Bumper Tow Hook Cover	\$	Sn	93.00	X
44	1	Rear Luggage Floor Panel	\$	R	973.00	X
45	1	Rear Luggage Floor Panel Insulator	\$	nn	63.50	X
46	1	Rear Luggage Floor Panel Trim Board	\$	Sn	378.00	X
47	1	Rear End Panel Inner	\$	Bt	336.84	—
48	1	Rear End Panel Outer	\$	Bt	623.76	—
49	1	Rear End Panel Inner Trim	\$	my CM	263.84	—
50	1	Bootlid	\$	Br	973.00	—
51	1	Bootlid inner trim board	\$	Sn	400.00	X
52	1	Bootlid Weatherstrip	\$	Dis / Rd	344.28	50 / Sn
53	1	Bootlid Lock - Top	\$	Rd	466.56	—
54	1	Bootlid lock - bottom	\$	R	39.40	X
55	1	Bootlid 'CHEVROLET' Badge	\$	Rd	120.62	—
56	1	Bootlid Logo	\$	Rd	138.84	—
57	1	Bootlid 'EPICA LT' Badge	\$	Rd	119.84	—
58	1	Bootlid inner handle	\$	Sn	45.55	X
59	1	Bootlid Reflector Centre	\$	Sn	217.97	X
60	1	Bootlid Reflector RH	\$	Sn	128.40	X
61	1	Bootlid Reflector LH	\$	Sn	128.40	X
62	1	Bootlid Hinge RH	\$	R	120.00	X
63	1	Bootlid Hinge LH	\$	R	120.00	X
64	1	Rear Tail Lamp RH	\$	CM	479.30	—
65	1	Rear Tail Lamp Panel RH	\$	R	359.00	X
66	1	Rear Tail Lamp LH	\$	my CM	479.30	—
67	1	Rear Tail Lamp Panel LH	\$	R	359.00	X
68	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R	1,110.00	X
69	1	Rear Fender RH	\$	R	1,145.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7806R - AIG**Candy**

70	1	Rear Fender Inner Cowling RH	\$	<i>Sn</i> 298.00 X
71	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44 X
72	1	Rear Fender LH	\$	<i>Bur</i> 1,145.00 ✓
73	1	Rear Fender Inner Cowling LH	\$	<i>Di's</i> 298.00 ✓
74	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 X

TOTAL	\$	27,797.72
10%	\$	2,779.77
	\$	25,017.95

Specical Nett

1	1Set	Front Bumper Fastener Clip	\$	<i>Mer</i> 24.00 ✓
2	1Set	Front Licence Plate With Holder	\$	<i>Di</i> 192.00 455 ✓
3	1Set	Radiator Grille Clip	\$	<i>Mer</i> 18.00 ✓
4	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
5	1Set	Radiator Grille Top Cover Clip	\$	<i>nn</i> 10.00 X
6	1Set	Front Fender Liner Clip	\$	<i>nn</i> 40.00 X
7	1Set	Rear Bumper Parking Sensor	\$	<i>Odd Short</i> 300.00 ✓
8	1Set	Rear Bumper Fastener Clip	\$	<i>Mer</i> 30.00 ✓
9	/ 2Set	Rear Fender inner cowling clip	\$	<i>Mer</i> 30.00 ✓
10	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 X
11	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 X
12	1	Rear Boot Sticker 'Trans-cab'	\$	<i>Mer</i> 30.00 —
13	1	Rear Boot Sticker '6555-3333'	\$	<i>Mer</i> 30.00 —
14	1	Door Sticker " Trans-cab " LH	\$	<i>nn</i> 80.00 X
15	1	Door Sticker " Trans-cab " RH	\$	<i>nn</i> 80.00 X
16	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00 X
17	1	Spare Tyre	\$	<i>Sn</i> 180.00 X
18	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74 X
19	1	Spare Tyre Board	\$	<i>Sn</i> 10.00 X
20	2	Rear Windscreen Sealant	\$	<i>Mer</i> 80.00 405 ✓
21	1	Rear Windscreen Inner Sponge Seal	\$	<i>Mer</i> 100.00 305 ✓

TOTAL	\$	1,470.74
TOTAL PARTS	\$	26,488.69

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 8,400.00 2000 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7806R - AIG**Candy**

To Check Electrical Lighting Concerned.	\$	170.00	40%
To Rust-Proofing Of The Affected Areas.	\$	170.00	150%
Putty And Spray Painting Of The Affected Portion.	\$	8,350.00	1800%
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	60%
To reinstall rear bumper parking sensor.	\$	170.00	60%
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	} 100%
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	
To transfer of boot fittings and conduct water seepage test.	\$	170.00	60%
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	Agreed X
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	120%
To vacuum, replace, refix and recharge air condenser	\$	380.00	100%
To replace, refix and top up coolant for radiator	\$	170.00	50%
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	50%

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7806R - AIG**Candy**

Towing Fees.

\$

120.00 *5d*

\$

19,510.00

TOTAL

\$

45,998.69

Repair Days*30 Days**12 days***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: