

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2016		08 Mar 2016 10:34 Edit Adj Rpt	S\$650.00 Edit Estimates	S\$650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SEAGULL PTE. LTD., Co. Reg. No.: 200311849H									
Main Claimant: TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K									
Vehicle Reg. No.:	SHD5151Z	Date of Loss:	03/03/2016 20:00 - :59 [74 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0374771	Policy/Cover Note No.:	P1594390 (Comprehensive)						
Vehicle Reg. No. (Insured):	YN4957T	Policy No. (Claimant):	VPX/P1680520						
		Excess:	S\$0.00						
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Stacey Ng - 6880 4351]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/09/2020]								
Driver/Custodian (Insured):	ALBERT ANTHONY (), NRIC: S9131059G, Tel: +6592714304 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (17/09/2020): Alert - Adj Mandate Approved (S\$1286.70) - SHD5151Z - Claim Handler: Stacey Ng - AXA_SG (14/12/2016): Re: Direct Settlement - Accident Involving YN4957T (OI : AXA - C0374771) and SHD... - AXA_SG (03/10/2016): Re: Direct Settlement - Accident Involving YN4957T (OI : AXA - C0374771) and SHD... - AXA_SG (20/05/2016): Re: Direct Settlement - Accident Involving YN4957T (OI : AXA - C0374771) and SHD... - AXA_SG (08/03/2016): WP / New TP Assignment - C0374771/P1594390									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD5151Z (C0374771)**
[YN4957T]
TP
TRANS-CAB SERVICES PTE LTD
Mar 3 2016 8:00PM
[SEAGULL PTE. LTD.]
Trans-cab Auto Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
Assessment Reports					1 per page ▼ ☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	03/10/16 14:31	Accident Statement From: SC - Reg. No: YN4957T, Claimant: SEAGULL PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/03/16 17:10	Adjuster Immediate Advice		Load HTM	
Documentation					1 per page ▼ ☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	08/03/16 09:16	Email_ABS		Load PDF	
2	08/03/16 09:16	SHD5151Z TP GIA Report_ABS		Load PDF	
3	08/03/16 09:16	Police Report_ABS		Load PDF	
4	08/03/16 10:29	CI		Load PDF	
5	08/03/16 10:29	POLICY SCHEDULE		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/03/16 11:18	TP ESTIMATE - MARKED		Load PDF	
2	20/06/17 11:39	LKK INSPECTION PHOTOS		Load PDF	
3	20/06/17 14:40	LETTER TO OI		Load PDF	
4	25/09/20 15:45	Authorisation to Act		Load PDF	
5	25/09/20 15:45	EMAIL		Load PDF	
6	25/09/20 15:45	LTA SEARCH		Load PDF	
7	25/09/20 15:45	PAYMENT BREAKDOWN - EXPRESS SETTLEMENT FORM		Load PDF	
8	25/09/20 15:45	RENTAL MILEAGE		Load PDF	
9	25/09/20 15:45	RENTAL RECEIPT		Load PDF	
10	25/09/20 16:02	INVOICE NO DATED 20.06.2017		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16004337/KBA3S2-1
Date: 25/09/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1594390
Claimant Vehicle No : SHD5151Z **Insured Vehicle No :** YN4957T
 Date of Loss: 03/03/2016 Nature of Claim: TP Claim No: C0374771

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD5151Z**
 Make & Model: TOYOTA WISH, 2.0 (A) Engine No: 3ZRA412988
 Reg. Date: 30/12/2009 (Man. Year: 2009) Chassis No: JTDGJ20W105001432
 Colour: Red/White Odometer: 560734 km
 Engine Capacity: 1987 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Rovel 4 mm Rear Left Side: Falken 6 mm
 Front Right Side: Rovel 4 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,806.38	655.82	2,150.56	76.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	150.00	1,630.00	91.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,586.38	805.82	3,780.56	82.43
Approved Total (Overridden) (S\$)		650.00		
(S\$)	4,586.38	650.00	3,936.38	85.83
+ GST 7.00/7.00% (S\$)	321.05	45.50	275.55	85.83
Nett Amount (S\$)	4,907.43	695.50	4,211.93	85.83
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$96.30/day) (S\$)		385.20		
+ Doc/Search Fee (S\$)		6.00		
Nett Liability (S\$)		1,286.70		
Global Sum Settlement (S\$)		1,100.00		

INSPECTION

Date of Assignment: 08/03/2016
 Date Inspected: 04/03/2016 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Sep 2020)	
Parts:	N/A	TOYOTA WISH 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5151Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (CONSISTENT)	Repair	837.60 FL	*- FL
2	1		*FRONT FENDER LINER LH (CONSISTENT)	Serviceable	369.14 FL	*- FL
3	1		*FRONT DOOR LH (CONSISTENT)	Repair	1,554.00 FL	*- FL
4	1		*FRONT SIDE VIEW MIRROR LH (CONSISTENT)	Broken	874.43 FL	*874.43 FL
5	1		*DOOR STICKER TRANS-CAB LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
					Sub Total (\$\$)	3,715.17 874.43
					- List Item Discount on L Items 25.00/25.00% (\$\$)	908.79 218.61
					Total Parts (\$\$)	2,806.38 655.82

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	840.00	60.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	120.00	10.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	820.00	80.00
Gross Labour Cost (\$\$)			1,780.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >