TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111 TEL NO.6287 6666 FAX NO.6257 1330 CO/GST REG NO.201019626G

SHD5151Z - AXA

Not Mhorin

Candy

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

SHD 5151Z - Candy

JTDGJ20W105001432

TOYOTA

WISH 2.0 BI-FUEL

03.03.16

		Third Party Insurer:	AXA	
		PART		LIST
1	1	Front Fender LH	\$	837.60 x369.14 <
2	1	Front Fender Liner LH	\$	369.14 <
3	1	Front door LH	\$	1,554.00 ×
4	1	Front side view mirror LH	\$	Br 874.43
		TOTAL	\$	3,635.17
		25%	\$	908.79
			\$	2,726.38
		Specical Nett		
1	1	Door Sticker "TRANS-CAB" LH	\$	wa 80.00 X
		TOTAL	\$	80.00
		TOTAL PARTS	\$	2,806.38
		Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of		
		Parts, Adjust And Realign The Same	\$	840.00 Gol
		To Check Electrical Lighting Concerned.	\$	120.00
		Putty And Spray Painting Of The Affected Portion.	\$	820.00 <i>I</i> e1
			-180	

LKK Auto	Consultants	hence	notify
	rer of the foll		

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Projudice" basis
 No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: Date:

Acknowledged by Repairer

	\$ 1,780.00
TOTAL	\$ 4,586.38

3 DAYS

1 day