

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHF 655J - AXA

ROEL

Not Authorized
1-B-1

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF 655J - ROEL
 VF1ABL15AUC278397
 RENAULT
 LATITUDE
 17.02.16
AXA

PART			LIST	
1	1	BUMPER COVER FRT	\$	CM 968.79 ✓
2	1	BUMPER SPOILER FRT	\$	Tn 139.81 ✓
3	1	BUMPER ABSORBER FRT	\$	Tn 303.60 ✓
4	1	BUMPER BRACKET FRT LH(Headlamp lower)	\$	CM 116.47 ✓
5	1	BUMPER RETAINER FRT LH	\$	D.Y 18.37 ✓
6	1	BUMPER BRACKET FRT RH(Headlamp lower)	\$	Sn 115.98 X
7	1	BUMPER REPAIRER FRT RH	\$	Sn 18.37 X
8	1	BUMPER UNDERTRAY FRT	\$	Sn 363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	D.Y 205.23 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	D.Y 159.39 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	Sn 159.39 X
12	1	BUMPER BEAM FRT	\$	R 703.14 ✓
13	1	RADAIOR GRILLE	\$	nn 1,313.68 X
14	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	nn 173.36 X
15	1	RADAIOR GRILLE FRAME	\$	CM 1,041.35 ✓
16	1	FRAME FULL SUPPORT PANEL	\$	R 473.77 X
17	1	FRAME FULL SUPPORT BRACKET	\$	R 69.07 X
18	1	FRONT BRACE PANEL	\$	R 136.32 X
19	1	SUBFRAME OUTER FRT	\$	Sn 2,040.34 X
20	1	HEADLALMP LH	\$	CM 911.10 ✓
21	1	HEADLALMP RH	\$	Sn 911.10 X
22	1	HEADLAMP PANEL FRT RH	\$	R 134.59 X
23	1	HEADLAMP PANEL FRT LH	\$	R 134.59 X
24	1	BONNET	\$	R 1,493.56 ✓
25	1	BONNET INSULATOR	\$	Sn 312.10 X
26	1	BONNET HINGE LH	\$	R 267.93 X
27	1	BONNET HINGE RH	\$	R 267.93 X
28	2	BAL HOOD	\$	Sn 75.60 X
29	1	BONNET LOCK	\$	R 234.99 X
30	1	BONNET SEAL OUTER	\$	Sn 71.04 X
31	1	FENDER PANEL FRT LH	\$	R 602.95 ✓
32	1	FENDER PANEL FRT RH	\$	R 602.95 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHF 655J - AXA**ROEL**

33	1	FENDER WHEELARCH FRT LH (Linner)	\$	107.32 X
34	1	FENDER WHEELARCH FRT RH (Linner)	\$	214.49 X
35	1	FENDER PANEL BRACKET FRT RH	\$	161.52 X
36	1	FENDER PANEL BRACKET FRT LH	\$	161.52 X
37	1	RADIATOR	\$	924.77 X
38	1	RADIATOR FAN COWLING L70Y	\$	525.99 X
39	1	RADIATOR FAN MOTOR LH L70Y	\$	620.10 X
40	1	RADIATOR FAN MOTOR RH L70Y	\$	948.37 X
41	1	RADIATOR TANK	\$	208.09 X
42	1	RADIATOR HOSE UPPER	\$	154.20 X
43	1	RADIATOR HOSE LOWER	\$	314.86 X
44	1	WATER HOSE PUMP	\$	439.00 X
45	1	RADIATOR TANK HOSE	\$	39.22 X
46	1	AIR CLEANER HOSE	\$	58.57 X
47	1	AIR CLEANER LOWER	\$	311.95 X
48	1	ENGINE UNDERTRAY	\$	434.60 X
49	1	A/C CONDENSER	\$	1,554.13 X
50	1	A/C CONDENSER GARNISH LH UPPER	\$	24.12 X
51	1	A/C CONDENSER GARNISH RH UPPER	\$	24.12 X
52	1	A/C CONDENSER GARNISH LH	\$	35.76 X
53	1	A/C CONDENSER GARNISH RH	\$	36.24 X
54	1	AIR INTERCOOLER	\$	852.66 X
55	1	AIR INTERCOOLER HOSE (Long)	\$	616.68 X
56	1	AIR INTERCOOLER HOSE (Short)	\$	228.12 X
57	1	STEERING PUMP ELECTRIC	\$	1,543.08 X
58	1	STERING HOSE LOW PRESSURE LONG	\$	442.50 X
59	1	STERING HOSE LOW PRESSURE	\$	247.18 X
60	1	WINDSCREEN FRT	\$	1,327.34 X
61	1	WIPER RESERVOIR	\$	190.96 X
62	1	WIPER RESERVOIR NECK	\$	27.78 X
63	1	WIPER RESERVOIR MOTOR	\$	100.95 X
64	1	DOOR FRT RH	\$	2,188.20 X
65	1	DOOR MIRROR RH	\$	1,141.08 X
66	1	DOOR SEAL FRT RH	\$	50.92 X
67	1	DOOR FRT LH	\$	2,188.20 X
68	1	DOOR MIRROR LH	\$	1,141.08 X

TOTAL	\$	34,126.21
10%	\$	3,412.62
	\$	30,713.59

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHF 655J - AXA

ROEL

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	NN 52.00 X
2	1SET	BUMPER CLIP FRT	\$	nn 66.00 ✓
3	1	TOW COVER FRT	\$	nn 14.50 X
4	1SET	RADAITOR GRILLE SCREW	\$	nn 16.00 X
5	1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00 X
6	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00 X
7	2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00 X
8	2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00 X
9	2	BONNET CABLE CLIP	\$	nn 6.40 X
10	1SET	WHEELARCH CLIP FRT LH	\$	nn 30.50 X
11	1SET	WHEELARCH CLIP FRT RH	\$	nn 29.40 X
12	1	DOOR STICKER "Trans-cab" LH	\$	nn 80.00 X
13	1	DOOR STICKER "Classic" LH	\$	nn 30.00 X
14	1	DOOR STICKER "Trans-cab" RH	\$	nn 80.00 X
15	1	DOOR STICKER "Classic" RH	\$	nn 30.00 X
16	1	DASHBOARD SCREW	\$	nn 55.55 X
17	1	CAP HUB LH FRT	\$	nn 35.00 X
18	1	RIM LH FRT	\$	nn 385.00 X
19	1	TYRE LH FRT	\$	nn 330.00 X
20	1SET	Front licence plate with holder	\$	nn 80.00 455

TOTAL	\$	1,509.35
TOTAL PARTS	\$	32,222.94

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 600
Putty and spray painting of the affected portion.	\$	3,000.00 880
To rust-proofing of the affected areas.	\$	170.00 60
Towing Fees.	\$	120.00 50
To check steering geometry and computer wheel alignment	\$	nn 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHF 655J - AXA

ROEL

To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To check ABS brake efficiency, final checking and testing.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	Repair 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20

TOTAL	\$	8,950.00
Over All Total	\$	41,172.94

< parts by parts > Repair Days

~~10 DAYS~~
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____