

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111.

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9209R -*Not Authorise* **ROEL**
61 Sep 8

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9209R - ROEL
LK1LA69RJBBO58904
CHEVROLET
CHEVROLET EPICA 2.0
04.02.16
AXA

		PART		LIST	
1	1	Front Bumper	\$	<i>C/P</i> 1,202.00	✓
2	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25	X
3	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00	X
4	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sn</i> 32.40	X
5	1	Front Bumper Lower Grille	\$	<i>Sn</i> 78.00	X
6	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37	X
7	1	Front Bumper Retainer LH	\$	<i>Diy</i> 102.00	✓
8	1	Front Headlamp LH	\$	<i>Wt</i> 816.00	✓
9	1	Front Fender LH	\$	<i>Bt</i> 837.60	✓
10	1	Front Fender Liner LH	\$	<i>C/P</i> 47.00	✓
11	1	Resonator (B/S Fender LH) AIR BOX	\$	134.67	?
12	1	Resonator Hose	\$	37.00	?
13	1	Radiator Grille (Grille A-Rad)	\$	<i>Sn</i> 367.00	X
14	1	Bonnet	\$	<i>R</i> 1,250.00	X
15	1	Bonnet Moulding	\$	<i>Sn</i> 161.97	X
16	1	Front Shock Absorber Assy LH	\$	216.17	?
17	1	Front Lower Arm LH	\$	283.00	?
18	1	Front Knuckle Arm LH	\$	230.00	?
19	1	Side Rocker Panel Garnish LH	\$	<i>Sn</i> 236.40	X
20	1	Front Door LH	\$	<i>R</i> 1,133.00	X
21	1	Front Side View Mirror LH	\$	<i>Sn</i> 939.00	X

TOTAL	\$	8,712.83
10%	\$	871.28
	\$	7,841.55

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>Wt</i> 30.00	✓
1 Set	Front licence plate with holder	\$	<i>Sn</i> 192.00	X
1 Set	Radiator Grille Top Cover Clip	\$	<i>Wt</i> 10.00	X
1 Set	Radiator Grille clip	\$	<i>Wt</i> 35.00	X
1 Set	Front Fender Liner Clip	\$	<i>Wt</i> 30.00	✓
1	Door Sticker "Trans-cab"	\$	<i>Wt</i> 80.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9209R -**ROEL**

1	Front Tyre LH	\$	<i>Sn</i> 360.00	X
1	Front Wheel Rim LH	\$	<i>Sn</i> 254.00	?
1	Front Wheel Rim Hub Cap LH	\$	<i>Sn</i> 166.30	X

TOTAL	\$	<u>1,157.30</u>
TOTAL PARTS	\$	<u>8,998.85</u>

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *400*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected

\$ 2,700.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

Labour charge to mount and dismount vehicle on
jig bench, to facilitate repair.

\$ *wn* 380.00 X

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ 380.00 ?

Towing fees

\$ 120.00 *500*

To check steering geometry and computer wheel
alignment

\$ 220.00 *600*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 ?

TOTAL	\$	<u>7,160.00</u>
Over All Total	\$	<u>16,158.85</u>

REPAIR DAYS**10 DAYS***2 1/2*