

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

**SHD 9209R -**

*Not Authorised* ROEL  
*61 Sep 8*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD 9209R - ROEL**  
**LK1LA69RJBBO58904**  
**CHEVROLET**  
**CHEVROLET EPICA 2.0**  
**04.02.16**  
*AXA*

		PART		LIST
1	1	Front Bumper	\$	<i>C/D</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25 X
3	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
4	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sn</i> 32.40 X
5	1	Front Bumper Lower Grille	\$	<i>Sn</i> 78.00 X
6	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
7	1	Front Bumper Retainer LH	\$	<i>D17</i> 102.00 ✓
8	1	Front Headlamp LH	\$	<i>Wt</i> 816.00 ✓
9	1	Front Fender LH	\$	<i>Bt</i> 837.60 ✓
10	1	Front Fender Liner LH	\$	<i>C/D</i> 47.00 ✓
11	1	Resonator (B/S Fender LH) AIR BOX	\$	134.67 ?
12	1	Resonator Hose	\$	37.00 ?
13	1	Radiator Grille (Grille A-Rad)	\$	<i>Sn</i> 367.00 X
14	1	Bonnet	\$	<i>R</i> 1,250.00 X
15	1	Bonnet Moulding	\$	<i>Sn</i> 161.97 X
16	1	Front Shock Absorber Assy LH	\$	216.17 ?
17	1	Front Lower Arm LH	\$	283.00 ?
18	1	Front Knuckle Arm LH	\$	230.00 ?
19	1	Side Rocker Panel Garnish LH	\$	<i>Sn</i> 236.40 X
20	1	Front Door LH	\$	<i>R</i> 1,133.00 X
21	1	Front Side View Mirror LH	\$	<i>Sn</i> 939.00 X

<b>TOTAL</b>	\$	<b>8,712.83</b>
<b>10%</b>	\$	<b>871.28</b>
	\$	<b>7,841.55</b>

**Special Nett**

1 Set	Front Bumper Fastener Clip	\$	<i>Wt</i> 30.00 ✓
1 Set	Front licence plate with holder	\$	<i>Sn</i> 192.00 X
1 Set	Radiator Grille Top Cover Clip	\$	<i>Wt</i> 10.00 X
1 Set	Radiator Grille clip	\$	<i>Wt</i> 35.00 X
1 Set	Front Fender Liner Clip	\$	<i>Wt</i> 30.00 ✓
1	Door Sticker "Trans-cab"	\$	<i>Wt</i> 80.00 X

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

**SHD 9209R -**

1	Front Tyre LH	\$	<i>Sn</i> 360.00 X
1	Front Wheel Rim LH	\$	<i>Sn</i> 254.00 ?
1	Front Wheel Rim Hub Cap LH	\$	<i>Sn</i> 166.30 X

<b>TOTAL</b>	\$	<b>1,157.30</b>
<b>TOTAL PARTS</b>	\$	<b>8,998.85</b>

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of  
Parts, Adjust And Realign The Same

\$ 2,800.00 *400*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected

\$ 2,700.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

Labour charge to mount and dismount vehicle on  
jig bench, to facilitate repair.

\$ *Sn* 380.00 X

To dismantle and refit front end suspension,  
undercarriage parts, final checking and testing.

\$ 380.00 *7*

Towing fees

\$ 120.00 *500*

To check steering geometry and computer wheel  
alignment

\$ 220.00 *600*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *?*

<b>TOTAL</b>	\$	<b>7,160.00</b>
<b>Over All Total</b>	\$	<b>16,158.85</b>

**REPAIR DAYS****10 DAYS***2 1/2*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: