

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7998U - AIG

Not Authorized
21 Sep @ 1550h

ROEL

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 7998U - ROEL
KL1LA69RJBB122287
CHEVROLET
EPICA 2.0
24.01.16
AIG

		PART	LIST	
1	1	Rear Bumper	\$	<i>Bumper</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>R</i> 239.94 X
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i> 260.00 X
4	1	Rear Bumper Side Retainer RH	\$	<i>Dry</i> 68.76 ✓
5	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74 X
6	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00 X
7	1	Rear End Panel Outer	\$	<i>R</i> 623.76 X
8	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84 X
9	1	Bootlid	\$	<i>R</i> 973.00 X
10	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00 X
11	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28 X
12	1	Bootlid Lock - Top	\$	<i>R</i> 466.56 X
13	1	Bootlid 'CHEVROLET' Badge	\$	<i>WV</i> 120.62 X
14	1	Bootlid Logo	\$	<i>WV</i> 138.84 X
15	1	Bootlid 'EPICA LT' Badge	\$	<i>WV</i> 119.84 X
16	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97 X
17	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40 X
18	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30 X
19	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00 X
20	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
21	1	Rear Fender RH	\$	<i>WV</i> (Det) 1,145.00 X
22	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44 X

TOTAL	\$	9,292.29
10%	\$	929.23
	\$	8,363.06

Special Nett

1	1Set	Rear Bumper Parking Sensor	\$	<i>Del/Scr</i> 300.00 ✓
2	1Set	Rear Bumper Fastener Clip	\$	<i>WV</i> 44.00 ✓
3	1Set	Rear Fender Inner Trim Clip RH	\$	<i>WV</i> 30.00 X
4	1	Rear Boot Sticker 'Trans-cab'	\$	<i>WV</i> 30.00 X
5	1	Rear Boot Sticker '6555-3333'	\$	<i>WV</i> 30.00 X
6	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00 X
7	2	Rear Windscreen Sealant	\$	<i>WV</i> 80.00 X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>WV</i> 100.00 X

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHB 7998U - AIG

ROEL

TOTAL	\$	624.00
TOTAL PARTS	\$	8,987.06

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00	200/
To Check Electrical Lighting Concerned.	\$	170.00	10/
To Rust-Proofing Of The Affected Areas.	\$	170.00	nn X
Putty And Spray Painting Of The Affected	\$	1,350.00	200/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	nn X
To transfer of boot fittings and conduct water seepage test.	\$	170.00	nn X

	\$	3,600.00
TOTAL	\$	12,587.06

Repair Days

5 Days

1 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: