

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20005614/GYF3E2

Date: 23/06/2020

REFERENCE

Insured/Claimant:	MYZA IZAYA TRANSPORTER	Policy No:	DMB1SN3034671900		
Date of Loss:	05/05/2020	Nature of Claim:	OD	Claim No:	SNM20D201871/PC8017U/ADELINE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8017U	Engine No:	1GD8388005
Make & Model:	TOYOTA HIACE, 2.8 D GL (A)	Chassis No:	GDH2232001465
Reg. Date:	10/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	50.00	0.00	50.00	100.00
Calculated Gross Total (\$\$)	50.00	0.00	50.00	100.00
- Excess (\$\$)	0.00	1,500.00	-1,500.00	
(\$\$)	50.00	-1,500.00	1,550.00	3,100.00
+ GST 7.00/0.00% (\$\$)	3.50	0.00	3.50	100.00
Nett Amount (\$\$)	53.50	-1,500.00	1,553.50	2,903.74

INSPECTION

Date of Assignment: 15/05/2020 Present Location:
Date Inspected: 15/05/2020 Inspected At:

S & H Motor Pte Ltd (Sin Ming)
S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$80,000.00
OMV : \$43,704.00
PARF Rebate (1) : \$0.00
Quota Premium Paid : \$20,709.00
COE Rebate (2) : \$16,567.00
Total Rebate (1) + (2) = : \$16,567.00

The total amount incurred will be Market Value \$80,000.00 minus Total Rebate \$16,567.00 = \$63,433.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jun 2020)
Parts:	213	TOYOTA HIACE 2.8 D GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8017U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >