

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|--|---|---|--------------------------------|------------|--|
| AXA | A INSURANCE PTE LTD | | Ref: CS3/ASM19022670/T1vf3s2-1 | | |
| C/O: SEAH ONG & PARTNERS LLP 36 ROBINSON ROAD #12-03 CITY HOUSE SINGAPORE 068877 | | Date: 30-06-2020 Code: ASM | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | | |
| | Insured Veh. | SMJ 2024L | Veh. Inspected | SMM 4109Y | |
| | Policy No. | VPA/P2258740 | Coverage (\$) | 0.00 | |
| | Claim No. | 20.27848PD-O | Excess (\$) | 0.00 | |
| | Assign From | XIN YI | Assign Date | 08/05/2020 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA NOAH HYBRID | c.c | 1797 | |
| | Engine No. | HIDDEN | Year of Reg. | 2019 | |
| | Chassis No. | ZWR800384293 | Colour | BLACK | |
| | Odometer | - | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195/65 R15 | GOODYEAR | 6 mm | |
| | L/H Front Tyre | 195/65 R15 | GOODYEAR | 6 mm | |
| | R/H Rear Tyre | 195/65 R15 | GOODYEAR | 6 mm | |
| | L/H Rear Tyre | 195/65 R15 | GOODYEAR | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. | | | | |
| | REPAIR CONDITION SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 21/12/2019 | Inspection Date | 12/06/2020 | |
| | Survey held at | MY CAR CONSULTANT PTE LT | D | | |
| | | 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 | | | |
| 5a. | 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | b. Estimate Days of Repair | | | | |
| | i e | | | | |

6 Working Days