

ASS. REC. BY:

REF:

LAW/20005623/Kg

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB 2366D

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru XV

c.c

1600

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

131.810

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JF1GP3K05GG-167385

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/1

D.O.I.

11/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Submit accordingly

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLB2366D

Report No. : PAS/TP/0441018

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Tailgate	Dented		\$ 1,523.00	6-R \$ 1,523.00 <i>18012</i>
2	1 pc	Tailgate emblem (Subaru)	Necessary		\$ 79.20	\$ 79.20
3	1 pc	Tailgate emblem (AWD)	Necessary		\$ 64.80	\$ 64.80
4	1 pc	Tailgate emblem (XV)	Necessary		\$ 64.80	\$ 64.80
5	1 pc	Tailgate outer moulding	Loop Cracked		\$ 260.00	N/A \$ 260.00 X
6	1 pc	Tailgate emblem (Logo)	Necessary		\$ 80.00	\$ 80.00
7	2 pc	Tailgate support stay R/L	Serviceable	\$ 144.70	\$ 289.40	\$ -
8	1 pc	Tailgate inner trim	Cracked/Deformed		\$ 353.00	2-C \$ 353.00 X
9	11 pc	Tailgate inner trim clip	Necessary	\$ 3.20	\$ 35.20	\$ 35.20
10	1 pc	Tailgate lock	Dented/Jammed		\$ 270.00	R \$ 270.00 X
11	1 pc	Tailgate striker	Serviceable		\$ 24.00	\$ -
12	1 pc	Tailgate weatherstrip	Necessary		\$ 111.60	\$ 111.60
13	1 pc	Tailgate lock antenna	Dented/Cracked		\$ 177.00	\$ 177.00
14	2 pc	Taillamp R/L	Cracked	\$ 482.00	\$ 964.00	di/11 \$ 964.00 X
15	1 pc	Rr bumper	Dented/Torn		\$ 863.00	\$ 863.00
16	2 pc	Rr bumper reflector R/L	Refit	\$ 41.40	\$ 82.80	\$ -
17	1 pc	Rr bumper fog lamp	Cracked		\$ 92.20	\$ 92.20
18	1 pc	Rr bumper tow hook cover	Dented		\$ 14.60	\$ 14.60
19	1 pc	Rr bumper reinforcement	Dented		\$ 320.00	\$ 320.00
20	6 pc	Rr bumper clip	Necessary	\$ 3.60	\$ 21.60	\$ 21.60
21	2 pc	Rr bumper retainer R/L	Cracked/Necessary	\$ 18.00	\$ 36.00	\$ 36.00
22	2 pc	Rr bumper bracket R/L	Cracked	\$ 16.40	\$ 32.80	\$ 32.80
23	1 pc	Rr end panel	Dented/Distorted		\$ 572.80	\$ 672.80
24	1 pc	Rr end panel garnish	Deformed/Cracked		\$ 164.00	\$ 164.00
25	6 pc	Rr end panel garnish clip	Necessary	\$ 3.20	\$ 19.20	\$ 19.20
26	1 pc	Rr tool sponge	Dented/Cracked		\$ 265.00	N/A \$ 265.00 X
27	1 pc	Exhaust muffler	Dented		\$ 880.00	\$ 880.00
28	2 pc	Exhaust mounting	Serviceable	\$ 39.00	\$ 78.00	\$ -
29	1 pc	Rr floor panel	Dented/Repair		(Refer labour no. 7, 9 & 10)	
30	2 pcs	Rr chassis member R/L	Dented/Repair		(Refer labour no. 7, 9 & 10)	
					\$ 7,338.00	\$ 7,363.80
Less Discount : 20%					\$ 1,567.60	20% \$ 1,472.76
List Parts Sub-Total :					\$ 6,270.40	\$ 5,891.04
1	1 pc	Tailgate glass inner seal	Necessary	S/N	\$ 50.00	\$ 20.00
2	1 pc	Tailgate glass sealant	Necessary	S/N	\$ 60.00	\$ 40.00
3	1 set	Reverse camera	Refit	S/N	\$ 380.00	\$ -
4	1 set	Reverse sensor	Dented/Damaged	S/N	\$ 250.00	\$ 220.00
5	1 pc	Rr end panel sealant	Necessary	S/N	\$ 60.00	\$ 40.00
Special Nett Sub-Total :					\$ 300.00	\$ 320.00
Parts Total :					\$ 7,070.40	\$ 6,211.04



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St.3 #02-24 S(629890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLB2366D

Report No. : PAS/TP/0441018

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 60.00	\$ 50.00 <i>20%</i>
2	To transfer rear windscreen to new tailgate.	\$ 120.00	<i>NN</i> \$ 120.00 <i>X</i>
3	To transfer tailgate component parts to new tailgate.	\$ 120.00	<i>NN</i> \$ 100.00 <i>60% X</i>
4	To transfer rear reverse camera to new tailgate.	\$ 60.00	\$ 50.00
5	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 50.00
6	To spray anti-rust coating on new and affected panels.	\$ 100.00	\$ 60.00
7	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 140.00	\$ 120.00 <i>60%</i>
8	To straighten, repair, realign center exhaust pipe and replace exhaust silencer.	\$ 100.00	\$ 80.00
9	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,200.00	\$ 880.00 <i>66%</i>
10	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 <i>80%</i>
Labour Total :		<u>\$ 3,160.00</u>	<u>\$ 2,510.00</u>
Total (Parts & Labour) :		<u>\$ 10,230.40</u>	<u>\$ 8,721.04</u>

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 6,980.00

Under normal circumstances, the repairs should be completed within a reasonable period of **8 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

92 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.