

AUTOPROBE CONSULTANTS

To: AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Our Ref.: SVY181000132
Date: 11/03/2019

AUTOMOBILE INSPECTION REPORT

1. SURVEY TYPE: THIRD PARTY

Vehicle Inspected:	SLB-2366-D	Your Reference:	S8M00ZEN
Insured Vehicle:	YP -7947-S	Policy Excess:	-
Assigned by:	MISS VALE OH	Assignment Date:	17/10/2018
Date of Accident:	15/10/2018	Surveyed / Assessed Date:	18/10/2018
Repairer / Survey at:	KUM CHEW MOTOR WORKSHOP	Resurvey Date:	24/10/2018

2. VEHICLE PARTICULARS:

Make & Model:	SUBARU XV 1.6I-S	General Condition:	FAIR
Registration Date:	31/03/2016	Colour:	GREY
Engine Capacity:	1600	Odometer (km):	76077
Chassis No.:	JF1GP3KC5GG167385	Steering:	IN ORDER
Engine No.:	FB16Y172919	Brake:	IN ORDER

3. TYRE CONDITION:

	Size	Make	Thread Depth (%)
FRONT LEFT	225/55R17	YOKOHAMA	20
FRONT RIGHT	225/55R17	YOKOHAMA	20
REAR LEFT	225/55R17	YOKOHAMA	30
REAR RIGHT	225/55R17	YOKOHAMA	30

4. DESCRIPTION OF DAMAGES:

The vehicle sustained damages mainly at the rear left portion.

AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

5. ADJUSTMENT SUMMARY:

Original Estimate:	-
Revised:	-
Final Adjustment:	-
Estimated Repair Duration:	5.00 Working Days

6. ESTIMATED VALUE (at time of accident):

Market Value:	\$70,000.00
LTA Rebate:	\$44,975.00 (as at 18/10/2018)
Nett:	\$25,025.00

7. SPECIAL REMARKS

Despite our request, the repairer did not provide us with the repair estimate.

- Pre-repair inspection conducted on 18/10/2018.
- Post-repair inspection conducted on 24/10/2018.

8. OUR RECOMMENDATION

ESTIMATED REPAIR COST ~ \$3,800/-.

The Inspection was conducted on a "Without Prejudice" basis.

Assessor: TAY BH

AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 2 of 112



Photograph 1 of 112



Photograph 4 of 112



Photograph 3 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 6 of 112




Photograph 5 of 112



Photograph 8 of 112



Photograph 7 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 10 of 112



Photograph 9 of 112



Photograph 12 of 112



Photograph 11 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 14 of 112



Photograph 13 of 112



Photograph 16 of 112



Photograph 15 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 18 of 112



Photograph 17 of 112



Photograph 20 of 112



Photograph 19 of 112



AUTOPROBE CONSULTANTS


Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 22 of 112



Photograph 21 of 112



Photograph 24 of 112



Photograph 23 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 26 of 112



Photograph 25 of 112



Photograph 28 of 112



Photograph 27 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 30 of 112




Photograph 29 of 112



Photograph 32 of 112



Photograph 31 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 34 of 112



Photograph 33 of 112



Photograph 36 of 112



Photograph 35 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 38 of 112



Photograph 37 of 112



Photograph 40 of 112



Photograph 39 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 42 of 112



Photograph 41 of 112



Photograph 44 of 112



Photograph 43 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 46 of 112



Photograph 45 of 112



Photograph 48 of 112



Photograph 47 of 112



AUTOPROBE CONSULTANTS

Your Ref.: S8M00ZEN
Our Ref.: SVY181000132

Vehicle No.: SLB-2366-D
Date of Accident: 15/10/2018

Photograph 50 of 112



Photograph 49 of 112



Photograph 52 of 112



Photograph 51 of 112

