



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

8/5/2020

Vehicle:

SML9408G

Make / Model:

TOYOTA PRIUS

Chassis:

JTDZS3EU70J038298

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER / <i>BR</i>	1	\$ 630.54	\$ 630.54
2	REAR BUMPER SIDE RETAINER LH / <i>BR</i>	1	\$ 113.60	\$ 113.60
3	REAR BUMPER SIDE RETAINER RH / <i>BR</i>	1	\$ 113.60	\$ 113.60
4	REAR BUMPER REINFORCEMENT / <i>BT</i>	1	\$ 350.50	\$ 350.50
5	REAR BUMPER BRACKET LH / <i>BT</i>	1	\$ 115.30	\$ 115.30
6	REAR BUMPER BRACKET RH / <i>BT</i>	1	\$ 115.30	\$ 115.30
7	REAR BUMPER LIP (<i>new spl</i>) / <i>NT</i>	1	\$ 728.90	\$ 728.90
8	REAR BUMPER REFLECTOR LH <i>X NN</i>	1	\$ 80.60	\$ 80.60
9	REAR BUMPER REFLECTOR RH <i>X NN</i>	1	\$ 80.60	\$ 80.60
10	REAR TAILGATE / <i>OD</i>	1	\$ 1,180.60	\$ 1,180.60
11	REAR TAILGATE LOCK / <i>BT</i>	1	\$ 360.10	\$ 361.10
12	REAR TAILGATE LOCK CATCH <i>X NAI</i>	1	\$ 89.50	\$ 89.50
13	REAR TAILGATE LOCK SENSOR <i>X NN</i>	1	\$ 360.90	\$ 360.90
14	REAR TAILGATE LOCK OUTER HANDLER <i>X NN</i>	1	\$ 127.60	\$ 127.60
15	REAR TAILGATE INNER TRIM BOARD / <i>CRU</i>	1	\$ 428.20	\$ 428.20
16	REAR TAILGATE INNER TRIM INSULATOR <i>X / MC</i>	1	\$ 348.60	\$ 348.60
17	REAR TAILGATE INNER SIDE TRIM BOARD LH <i>X NN</i>	1	\$ 119.70	\$ 119.70
18	REAR TAILGATE INNER SIDE TRIM BOARD RH <i>X NN</i>	1	\$ 119.70	\$ 119.70
19	REAR TAILGATE OUTER GARNISH <i>X NN</i>	1	\$ 228.30	\$ 228.30
20	REAR TAILGATE LOGO <i>X NN</i>	1	\$ 95.50	\$ 95.50
21	REAR TAILGATE EMBLEM PRIUS / <i>MC</i>	1	\$ 89.40	\$ 89.40
22	REAR TAILGATE EMBLEM HYBRID / <i>MC</i>	1	\$ 82.30	\$ 82.30
23	REAR NUMBER PLATE LAMP LH <i>X NAI</i>	1	\$ 78.40	\$ 78.40
24	REAR NUMBER PLATE LAMP RH <i>X NN</i>	1	\$ 78.40	\$ 78.40
25	REAR TAILGATE WIRE HARNESS / <i>X NN</i>	1	\$ 998.40	\$ 998.40
26	REAR TAILLAMP RH / <i>BR</i>	1	\$ 690.50	\$ 690.50
27	REAR TAILLAMP INNER PANEL RH <i>X R</i>	1	\$ 280.40	\$ 280.40
28	REAR TAILLAMP LOWER BRACKET RH / <i>BR</i>	1	\$ 89.10	\$ 89.10
29	REAR TAILLAMP CLIPS RH <i>X NN</i>	1	\$ 9.80	\$ 9.80
30	REAR TAILLAMP LH <i>X NN</i>	1	\$ 690.50	\$ 690.50
31	REAR TAILLAMP INNER PANEL LH <i>X NN</i>	1	\$ 280.40	\$ 280.40

513.90 /

929 /

243.60 /

50.00 /

52.30 /

630 /

68 /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

42. Rear Bumper lower cover / DEF \$179
 43. Bootlid rubber / TN \$196

6947.80
 -25%
5210.85

SML9408G

32	REAR TAILLAMP LOWER BRACKET LH X / BR	1	\$ 89.10	\$ 89.10	68/
33	REAR TAILLAMP CLIPS X NN	1	\$ 9.80	\$ 9.80	X
34	REAR FENDER LH X NN	1	\$ 850.30	\$ 850.30	X
35	REAR TOOLS SPONGE / TN	1	\$ 680.40	\$ 680.40	230/
36	REAR TOOLS TOP COVER X / BR	1	\$ 518.30	\$ 518.30	39670/
37	REAR KEYLESS SENSOR ? / BR	1	\$ 169.50	\$ 169.50	/
38	REAR KEYLESS SENSOR WIRE HARNESS ? X NN	1	\$ 438.60	\$ 438.60	X
39	REAR END PANEL ? / DD	1	\$ 660.20	\$ 660.20	/
40	REAR END PANEL TOP GARNISH ? / DEF	1	\$ 225.10	\$ 225.10	/
41	REAR SPARE TYRE COMPARTMENT X BR	1	\$ 694.30	\$ 694.30	X
				\$ 13,491.84	
			Less 25%	\$ 3,372.96	
			Total	\$ 10,118.88	
	S/Nett items:				
1	REAR BUMPER CLIPS	1 SET	\$ 80.00	\$ 80.00	30
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1 SET	\$ 80.00	\$ 80.00	20
3	REAR TAILGATE OUTER GARNISH CLIPS	1 SET	\$ 80.00	\$ 80.00	X NN
4	REAR CAMERA	1	\$ 350.00	\$ 350.00	X NN
5	REAR REVERSE SENSOR	1	\$ 250.00	\$ 250.00	200
6	REAR FENDER INNER TRIM BOARD CLIPS LH	1 SET	\$ 80.00	\$ 80.00	X NN
7	REAR FENDER INNER TRIM BOARD CLIPS RH	1 SET	\$ 80.00	\$ 80.00	X NN
8	REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 80.00	\$ 80.00	10
9	REAR END PANEL SEALANT	1 SET	\$ 60.00	\$ 60.00	30
10	REAR FLOOR PANEL SEALANT	1 SET	\$ 60.00	\$ 60.00	X NN
11	REAR WINDSCREEN GLASS SEALANT	1	\$ 60.00	\$ 60.00	/
12	REAR NUMBER PLATE WITH CASING	1	\$ 60.00	\$ 60.00	X NN
				\$ 1,080.00	350
	Labour to:				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	30
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00	30
3	TO MOVE AND RENEW REAR REVERSE CAMERA	1	\$ 150.00	\$ 150.00	30
4	TO REMOVE AND TRANSFER WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00	120
5	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	1	\$ 200.00	\$ 200.00	50
6	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00	X
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	30
8	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00	600
9	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1,800.00	800
				\$ 4,080.00	1690
Store (CLKK) ML PL 11/5/20, 3.30pm 5 days L/S Ry AL SLy			Parts Replacement Amount	\$ 11,198.88	
			Total Amount for Labour	\$ 4,080.00	
			Total Amount	\$ 15,278.88	\$15,560.13

L/S
 Ry AL SLy

P-5210.85
 N-350
 L-1690
 7250.85

L/S-5800.68
 =5800