

SJQ1136C

ACCIDENT REPAIR ESTIMATE

Vehicle Reg. No. : SJQ1136C

Vehicle Reg. Date: 24-Apr-2009

Make / Model : HONDA FIT 1.3G A

Engine No. : L13A4153003

Chassis No. : GE61138054

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email :

Fax No :

HP No.:

This claim is handled by :

YT AUTOMOBILE PTE LTD.

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SJQ1136C
 Vehicle Reg. Date: 24/4/2009
 Make / Model : HONDA FIT 1.3G A
 Engine No. : L13A4153003
 Chassis No. : GE61138054

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAILGATE WINDSCREEN	✓ CRU.			
2	1SET	TAILGATE WINDSCREEN MLDG	✓ Nec.			
3	1	THIRD BRAKE LIGHT	✓ CRU.			
4	1	TAILGATE WIPER MOTOR	? X SVC			
5	1	TAILGATE WIPER ARM	✓ SCR			
6	1	TAILGATE WIPER BLADE	✓ CRU			
7	1	TAILGATE	✓ DO.			
8	1	TAILGATE LOCK	✓ JUM			
9	1	TAILGATE LOCK CATCH	? X SVC			
10	1	TAILGATE PLATE GARNISH	✓ CRU			
11	2	PLATE LAMP	? ✓ CRA			
12	1	TAILGATE INNER TRIM	? ✓ cut			
13	1SET	TAILGATE INNER TRIM CLIPS	? ✓ Nec			
14	1	TAILGATE WEATHERSTRIP	? ✓ cut			
15	1	TAILGATE EMBLEM - LOGO	✓ NA			
16	1	TAILGATE EMBLEM - FIT	✓ Nec			
17	1	TAILGATE EMBLEM MUGEN	✓ Nec			
18	1/2	TAILGATE LAMP LH/RH	LH/CRU NH ✓ CRA			
19	1/2	TAILGATE LAMP BRACKET LH/RH	X SVC			
20	2	TAILLAMP CLIPS	✓ Nec			
21	1/2	TAIL LAMP PANEL LH/RH	X SVC			
22	1	REAR END PANEL INNER	? } ✓ PD			
23	1	REAR END PANEL OUTER	? } ✓ PD			
24	1	REAR END PANEL TOP GARNISH	? ✓ cut			
25	1SET	REAR END PANEL TOP GARNISH CLIPS	? ✓ Nec			
26	1	SPARE TYRE PANEL	? ✓ CRU			
27	1	SPARE TYRE PANEL TOP BOARD	? ✓ CRU			
28	1	SPARE TYRE PANEL TOOL TRAY	? X SVC			
29	1	REAR BUMPER	✓ CRU.			
30	2	REAR BUMPER RETAINER LH/RH	✓ BR			
31	1	REAR BUMPER REINFORCEMENT	? X SVC			
32	2	REAR BUMPER LOWER SKIRT	✓ SCR.			
33	1	ANTENNA SENSOR	? X SVC			
34	1/2	REAR FENDER LH/RH	LH/CRU RH X R			
35	1/2	REAR FENDER INNER SHIELD (REAR)	? ✓ CRU			
36	2	REAR FENDER INNER SHIELD (FRONT)	? X SVC			
37	1/2SET	REAR FENDER INNER SHIELD CLIPS	? ✓ Nec			
38	1/2	REAR FENDER INNER LOWER TRIM BOARD LH/RH	? LH/CRU			
39	1/2SET	REAR FENDER INNER LOWER TRIMBOARD CLIPS	? ✓ Nec			
40	1/2	REAR FENDER INNER UPPER TRIM BOARD LH/RH	? LH/CRU.			

YT AUTOMOBILE PTE LTD.

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SJQ1136C
 Vehicle Reg. Date: 24/4/2009
 Make / Model : HONDA FIT 1.3G A
 Engine No. : L13A4153003
 Chassis No. : GE61138054

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1 SET	REAR FENDER INNER UPPER TRIM BOARD CLIPS	? / NEC			
42	2	REAR FENDER GLASS LH/RH	X SVC			
43	1	EXHAUST PIPE	X SVC			
44	1	EXHAUST HEAT COVER	X SVC			
45	2	EXHAUST PIPE MOUNTING	X SVC			
46	1	REAR NUMBER PLATE WITH FRAME	/ SCR			
47	2	TAIL LAMP PAD LH/RH	/ NEC	\$ 50.00		35
48	1	REAR END PANEL SEALANT	/ NEC	\$ 150.00		30
49	1	SPARE TYRE PANEL SEALANT	/ NEC	\$ 100.00		40
50	1	SUNDRIES	2 / NEC	\$ 100.00		40
51	1	REVERSE SENSOR	X SVC	\$ 60.00		X
52	1	REVERSE CAMERA	/ PHOT	\$ 300.00		200
53	0	0	X SVC	\$ 500.00		X
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]
$$\text{Repair dy} - \frac{8}{9} \text{ dy}_2.$$

11/05/2020

Sum Pin (LH/LC)

TP without prejudice

45

After print photo.

YT AUTOMOBILE PTE LTD.

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SJQ1136C
 Vehicle Reg. Date: 24/4/2009
 Make / Model : HONDA FIT 1.3G A
 Engine No. : L13A4153003
 Chassis No. : GE61138054

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAILGATE STAY LH/RT	X LH/RT			
2	2	TAILGATE HINGES LH/RH	/ RT			
3	1	TAILGATE INNER HANDLE	X SVC			
4	1	TAILGATE STRIKER	X SVC			
5	1	CABLE, TAILGATE OPENER	X SVC			
6	1	HANDLE ASSY, TAILGATE	/ CUT			
7	1	GUTTER COMP., L. RR. PILLAR Trimming Part	X RT			
8	1	STIFFENER, L. RR. PANEL SIDE	/ RT			
9	1	STIFFENER, R. RR. PANEL SIDE	X R			
10	2	STIFFENER, RR. BUMPER FACE	/ RT			
11	1	AIR DUCT REAR LH	/ MIS			
12	1	ROOF LINING	/ Local Repair	\$100		
13	1	REAR SHOCK ABSORBER LH	X SVC			
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]